



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2004751  
INV Date 06/07/2020  
Reference CC6/CTI19022498/Aea3n2  
Code CTI



### PROFESSIONAL SERVICE FEE

Vehicle No. SKX 3203E  
Insured Veh. SBZ 2800J  
Claim No. SNM19D205914C02/0  
Policy No. DMPCSN1106131908  
Accident Date 11/12/2019  
Inspection Date 17/12/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19022498/Aea3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 06-07-2020



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBZ 2800J	Veh. Inspected	SKX 3203E
Policy No.	DMPCSN1106131908	Coverage (\$)	0.00
Claim No.	SNM19D205914C02/0	Excess (\$)	0.00
Assign From		Assign Date	17/12/2019

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZSU600063209	Colour	BLACK
Odometer	56854	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R18	MICHELIN	6 mm
L/H Front Tyre	235/55 R18	MICHELIN	6 mm
R/H Rear Tyre	235/55 R18	MICHELIN	6 mm
L/H Rear Tyre	235/55 R18	MICHELIN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	11/12/2019	Inspection Date	17/12/2019
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 3203E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SIDE SKIRT LH	CUT	890.00	699.00
1	REAR DOOR LH	DENTED	1,855.50	1,569.00
1	REAR DOOR OUTER CHROME GARNISH LH	DEFORMED	320.00	250.00
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,422.20	-
1	REAR FENDER MUD FLAG LH	CUT	88.30	88.30
1	REAR QUARTER GLASS WITH MOULDING	NOT NECESSARY	820.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,533.20	-
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	62.40	-
	LESS 25% DISCOUNT		-1,747.90	-651.58
			5,243.70	1,954.72
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR FENDER MUD FLAP CLIP (SN)	NOT NECESSARY	30.00	-
1	QUARTER GLASS SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR WHEEL RIM LH (SN)	CUT	850.00	500.00
1	REAR WHEEL TYRE LH (SN)	NOT NECESSARY	450.00	-
			1,440.00	500.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER LH AND REAR BUMPER .		1,200.00	500.00
	TO SPRAY PAINT AFFECTED AREA.		1,200.00	650.00
	TUFF COAT.		180.00	60.00
	WIRING CHECK .		120.00	30.00
	UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX REAR DOOR MECHANISM LH.		160.00	80.00
	REMOVE AND REFIX QUARTER GLASS.	NOT NECESSARY	120.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	FOUR WHEEL ALIGNMENT.		120.00	80.00
			3,220.00	1,400.00
GRAND TOTAL			9,903.70	3,854.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CC6/CT119022498/Aea3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 3203E

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

