



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2007125
INV Date 20/10/2020
Reference CC3/CTI19022500/Fea3s2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHA 999T
Insured Veh. SJC 7380Y
Claim No. SNM19D206043/C02
Policy No. DMPCSN3015471901
Accident Date 17/12/2019
Inspection Date 18/12/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19022500/Fea3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 20-10-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJC 7380Y	Veh. Inspected	SHA 999T
Policy No.	DMPCSN3015471901	Coverage (\$)	0.00
Claim No.	SNM19D206043/C02	Excess (\$)	0.00
Assign From		Assign Date	18/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU203559613	Colour	YELLOW
Odometer	348369	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	7 mm
L/H Front Tyre	195/65 R15	DAVANTI	7 mm
R/H Rear Tyre	195/65 R15	DURATURN	8 mm
L/H Rear Tyre	195/65 R15	DURATURN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/12/2019	Inspection Date	18/12/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 999T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TRUNK LID COVER	TO REPAIR SEE LABOUR	1,126.60	-
1	REAR TRUNK LID LOCK	NOT NECESSARY	457.90	-
1	REAR TRUNK LID GLAS (BLACK COLOR)	NOT NECESSARY	733.50	-
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	TO REPAIR SEE LABOUR	889.70	-
1	REAR TRUNK LID LOGO (PRUIS)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	47.00	47.00
1	ROOF TOP GARNISH SUB, LH	NOT NECESSARY	72.00	-
1	ROOF TOP GARNISH SUB, RH	NOT NECESSARY	75.00	-
1	REAR BUMPER	CRACKED	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER UNDER COVER	CRACKED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	112.70	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	SEAL, REAR BUMPER SIDE, RH	NOT NECESSARY	148.40	-
2	TAIL LAMP ASSY (UPPER) (LH/RH) @ \$557.90	NOT NECESSARY	1,115.80	-
2	TAIL LAMP ASSY (LOWER) (LH/RH) @ \$548.40	O/S CRACKED	1,096.80	548.40
1	REAR END PANEL	NOT NECESSARY	602.10	-
1	REAR END PANEL GARNISH	NOT NECESSARY	165.80	-
	LESS 25% DISCOUNT		-2,025.27	-513.30
			6,075.83	1,539.90
<u>SPECIAL NETT ITEMS</u>				
1	REAR NO. PLATE WITH TRIM COVER (SN)	BROKEN	100.00	100.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @ \$100.00 (SN)	NOT NECESSARY	200.00	-
			535.70	200.00

Report Ref No. CC3/CTI19022500/Fea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR TRUNK LID COVER AND GARNISH SUB-ASSY, BACK DOOR, OUTSIDE.		800.00	640.00
	SPRAY PAINTING CHARGE.		700.00	600.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
			1,680.00	1,270.00
	GRAND TOTAL		8,291.53	3,009.90

RECOMMENDED COST OF REPAIRS			3,009.90
------------------------------------	--	--	-----------------

Report Ref No. CC3/CT119022500/Fea3s2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.