SM SPRAY PAINTING

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third p. vey is on a Without Prejudice" basis • No il'e ilication(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NIL

ON BEHALF OF OWNER:

Policy Particulars: - THIRD PARTY CLAIM

Insured veh.

SFD821E

Excess.

Policy No.

2019-V0100715-VDP-R002

Coverage.

Claiming Against.

SLE4690M

Insured Under.

GREAT EASTERN GENERAL INSURANCE LIMITED

Vehicle Particulars & Condition

Make & Model

BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV

Engine No.

09467889N52B25AF WBAFP320X0C868460

Chassis No.

Odometer Engine CC.

Year Of Reg.

Colour.

GREY

Parf/COE Rebate.

Conditions Of Tyres

Size

Make

R/H Front Tyre L/H Front Tyre R/H Rear Tyre

L/H Rear Tyre

Description Of Damages

FRONT PORTION

General Information

Accident Date.

18/12/2019

Survey held at

Yew Tee Automobile Tech Pte Ltd SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S417800

Remarks

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR:

Days

LKK Auto Consultants hence notify

Not Authoral

- the Repairer of the following: · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal medification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

SM SPRAY PAINTING

Qty.	Description Of Parts	Pr	cicing
1 1 1 1 1 1 1 1 1 1 1	REAR BUMPER SIDE RETAINER RH REAR BUMPER SIDE RETAINER LH REAR BUMPER REFLECTOR RH REAR BUMPER REFLECTOR LH REAR BUMPER REINFORCEMENT REAR BUMPER TOWING COVER BOODLID BOODLID EMBLEM BOOTLID "5231" EMBLEM REAR END PANEL REAR END PANEL REAR END PANEL TOP GARNISH	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	1,571.95 156.70 × 156.70 × 37.75 × 37.75 × 775.95 × 47.85 × 1,650.65 × 71.60 64.45 821.40 ×
		\$	116.15

		List items	\$	5,508.90	
		Less 5%	\$	275.45	
		Sub Total	\$	5,233.45	
1 1 4 8	BUMPER CLIPS REAR NUMBER PLATE REAR BUMPER SENSOR END PANEL TOP GARNISH CLIP	ner 17 5hud	\$ \$ \$	30.00 (35.00 200.00 65.00	ノメンメ
	\$/	N -	ċ	220.00	

SM SPRAY PAINTING

<u>Qty.</u> LABOUR	Description Of Parts	<u>P</u>	ricing
To Remove and To Disconnect ar	Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust ncer and Mountings. Remove and Refit Rear Bumper Sensor. Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, place Damaged Parts.	11 s s	80.00 SO
To Remove and Is and Repair include position using portor to Carry-Out Book To Supply Spray To spray painting masking tape the	Replace the above Damaged Parts, Straighten, Knock out, Realig Jing Cut and Weld body panels. To Re-adjust to the Original		1,200.00 400 80.00 × 90.00 × 800.00 600
		Sub Total. \$ 7% GSt \$ Grand Total \$. 70

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

P-1708 676 8-1622.60 5.N-230.00 L-1880.00 2932.60 2932.60