



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 4022D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT RH FENDER (CONSISTENT)	BENT	383.70	383.70
1	FRONT RH FENDER INNER SPLASH SHIELD (CONSISTENT)	DEFORMED	161.40	161.40
1	SET FRONT RH FENDER INNER SPLASH SHIELD CLIPS (CONSISTENT)	NECESSARY	40.00	40.00
1	RH FRONT DOOR (CONSISTENT)	BENT	975.20	975.20
1	RH FRONT DOOR FRAME BLACK STICKER (CONSISTENT)	NECESSARY	65.60	65.60
1	RH FRONT DOOR UPPER HINGE (CONSISTENT)	TO REPAIR SEE LABOUR	37.40	-
1	RH FRONT DOOR LOWER HINGE (CONSISTENT)	TO REPAIR SEE LABOUR	37.40	-
1	RH FRONT SPORT RIM (CONSISTENT)	CUT	1,196.80	1,196.80
1	RH FRONT LOWER ARM (CONSISTENT)	NOT NECESSARY	259.10	-
1	RH FRONT SHOCK ABSORBER (CONSISTENT)	NOT NECESSARY	392.40	-
1	RH FRONT KNUCKLE ARM (CONSISTENT)	NOT NECESSARY	378.10	-
1	RH FRONT WHEEL BEARING (CONSISTENT)	NOT NECESSARY	566.70	-
	LESS 20% DISCOUNT		-898.76	-564.54
			3,595.04	2,258.16
<b><u>SPECIAL NETT ITEMS</u></b>				
1	RH FRONT TYRE (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
			300.00	-
<b><u>LABOUR</u></b>				
	LABOUR TO REMOVE, REFIT AND REPLACE AFFECTED PARTS.TO PANEL BEATING AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF RH FRONT DOOR UPPER HINGE AND RH FRONT DOOR LOWER HINGE .		800.00	450.00
	PUTTY AND RESPRAY ON AFFECTED AREAS.		800.00	450.00
	TRANSFER RH FRONT DOOR INNER MECHANISM TO NEW DOOR .		100.00	60.00
	APPLY RUST COATING ON AFFECTED AREAS AND PANELS.		80.00	40.00
	REMOVE AND REPLACE RH FRONT UNDERCARRIAGE PARTS.		240.00	100.00

Report Ref No. CC4/ASM19022516/T1ga3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	ADJUST WHEEL ALIGNMENT SYSTEM.		100.00	60.00
			2,120.00	1,160.00
GRAND TOTAL			6,015.04	3,418.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CC4/ASM19022516/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.