

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD19022524/AGA3Q2

**Date:** 27/07/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00016409  
**Claimant**  
**Vehicle No :** GBA7240Z **Insured Vehicle No :** SMG3123T  
**Date of Loss:** 12/12/2019 **Nature of Claim:** TP **Claim No:** 1201900039565

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** GBA7240Z  
**Make & Model:** MITSUBISHI FB70BB1SRDEA, 3.0 D (M) **Engine No:** 4M42A50018  
**Reg. Date:** 28/11/2007 (Man. Year: 2007) **Chassis No:** FB70BBA10305  
**Colour:** White **Odometer:** 324202 km  
**Engine Capacity:** 2977 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

### CONDITION OF TYRES

**Front Tyre Size:** 195 R15C **Rear Tyre Size:** 195 R15C  
**Front Left Side:** Dunlop 6 mm **Rear Left Side:** Dunlop 6 mm  
**Front Right Side:** Dunlop 6 mm **Rear Right Side:** Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,909.45	3,168.92	2,740.53	46.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	830.00	730.00	46.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,469.45</b>	<b>3,998.92</b>	<b>3,470.53</b>	<b>46.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,200.00</b>		
<b>(S\$)</b>	7,469.45	3,200.00	4,269.45	57.16
<b>+ GST 7.00/7.00% (S\$)</b>	522.86	224.00	298.86	57.16
<b>Nett Amount (S\$)</b>	<b>7,992.31</b>	<b>3,424.00</b>	<b>4,568.31</b>	<b>57.16</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		240.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,671.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,650.00</b>		

### INSPECTION

**Date of Assignment:** 23/12/2019  
**Date Inspected:** 15/01/2020 **Inspected At:** People's Vehicle Recovery Service (HQ)  
 Blk 3023A Ubi Rd 1, #01-60  
 Singapore 408717  
**Estimated Period of Repair:** 4.0 days

---

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Mar 2020)	
<b>Parts:</b>	N/A	mitsubishi FB70BB1SRDEA 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBA7240Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRT	Deformed	821.47 FL	*821.47 FL
2	1		*SIGNAL LAMP R/H FRT	Cracked	227.63 FL	*227.63 FL
3	1		*SIDE LAMP R/H	Cracked	159.75 FL	*159.75 FL
4	1		*HEAD LAMP R/H	Not Necessary	635.06 FL	*- FL
5	1		*HEAD LAMP LOWER MOULDING R/H	Not Necessary	19.56 FL	*- FL
6	1		*DOOR R/H FRT	Dented	2,071.55 FL	*1,827.00 FL
7	2		*DOOR HINGE R/H FRT	Bent	325.08 FL	*325.08 FL
8	1		*DOOR RUBBER R/H FRT	Not Necessary	424.44 FL	*- FL
9	1		*DOOR POWER WINDOW GEAR R/H FRT	Damaged	1,363.16 FL	*341.50 FL
10	1		*STEP PANEL GARNISH R/H FRT	Cut	496.13 FL	*496.13 FL
11	1		*BODY LETTERING	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,563.83</b>	<b>4,218.56</b>
<b>- List Item Discount on L Items 10.00/25.00% (\$\$)</b>	654.38	1,049.64
<b>Total Parts (\$\$)</b>	<b>5,909.45</b>	<b>3,168.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REPLACE ACCIDENT DAMAGED PARTS	New	800.00	500.00
2	SPRAY PAINTING ACCIDENT EFFECT PARTS	New	700.00	300.00
3	CHECK ALL LIGHTING AFTER REPAIR	New	60.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,560.00</b>	<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >