

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022527/KRA3Q2
Date: 20/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SKX8098J

Date of Loss: 15/12/2019

Policy No:

Insured Vehicle No :

SCJ813H

Nature of Claim:

TP

Claim No:

2060206879SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKX8098J**

Make & Model: HONDA JAZZ, 1.3 CVT (A)

Reg. Date: 19/12/2015 (Man. Year: 2015)

Colour: Metallic Maroon

Engine Capacity: 1318 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: L13B11010092

Chassis No: JHMGK3850GX216837

Odometer: 59199 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15

Front Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Tyre Size:

175/65 R15

Rear Left Side:

Bridgestone 5 mm

Rear Right Side:

Bridgestone 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,575.28	1,575.28	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	950.00	300.00	24.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,825.28	2,525.28	300.00	10.62
+ GST 7.00/7.00% (S\$)	197.77	176.77	21.00	10.62

Nett Amount (S\$)	3,023.05	2,702.05	321.00	10.62
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		3,110.05		
Global Sum Settlement (S\$)		3,100.00		

INSPECTION

Date of Assignment: 23/12/2019

Date Inspected: 04/02/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Mtg Cracked	492.70 FL	*492.70 FL
2	6		*REAR BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
3	1		*REAR TAILGATE	Bent	814.00 FL	*814.00 FL
4	1		*TAILGATE EMBLEM JAZZ	Necessary	20.50 FL	*20.50 FL
5	1		*TAILGATE INNER LOCK	Dented	186.70 FL	*186.70 FL
6	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	131.80 FL	*131.80 FL
7	1		*ROLL REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
8	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,909.10	1,909.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	333.82	333.82
Total Parts (\$\$)	1,575.28	1,575.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS.	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY, TAILGATE & ATTACHMENT, MOULDING, KNOCK & REPAIR REAR END PANEL & REALIGN THE SAME.	New	500.00	400.00
3	PUTTY & RESPRAY ON REAR BUMPER, REAR PANEL, REAR TAILGATE.	New	600.00	400.00
4	RUSTPROOFING.	New	30.00	30.00
Gross Labour Cost (S\$)			1,250.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >