

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19022528/GKA3Q2

Date: 30/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100502089-01

Claimant Vehicle No : SLQ8696H **Insured Vehicle No :** SLL5322H

Date of Loss: 22/12/2019 Nature of Claim: TP Claim No: 6857625266SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ8696H		
Make & Model:	AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A)	Engine No:	CHZ382442
Reg. Date:	25/07/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ8V9HA143310
Colour:	Red	Odometer:	26984 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,435.00	1,366.40	2,068.60	60.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,422.00	1,522.00	900.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,857.00	2,888.40	2,968.60	50.68
+ GST 7.00/7.00% (S\$)	409.99	202.19	207.80	50.68
Nett Amount (S\$)	6,266.99	3,090.59	3,176.40	50.68
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,392.59		

INSPECTION

Date of Assignment: 26/12/2019

Date Inspected: 26/12/2019 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,708.00 FS	*1,366.40 FS
2	2		*REAR BUMPER STICKY PAD	Not Necessary	11.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	175.00 FS	*- FS
4	2		*REAR BUMPER LOCKING MECHANISM -LH/RH	Not Necessary	24.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Not Necessary	216.00 FS	*- FS
6	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	54.00 FS	*- FS
7	1		*REAR BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	522.00 FS	*- FS
8	1		*REAR BUMPER BRACKET -LH	Not Necessary	25.00 FS	*- FS
9	1		*REAR BUMPER BRACKET -RH	Not Necessary	26.00 FS	*- FS
10	2		*REAR PARKING AID SENSOR -INNER /OUTER	Not Necessary	462.00 FS	*- FS
11	4		*REAR PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
12	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 3,435.00 1,366.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER ,RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,422.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >