

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19022529/EEA3Q2

Date: 22/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700048521

Claimant
Vehicle No : SMR1604C **Insured Vehicle No :** GBG5789P

Date of Loss: 20/12/2019 Nature of Claim: TP Claim No: 5370523223SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR1604C	Engine No:	DED034154
Make & Model:	VOLKSWAGEN SHARAN, 2.0 TSI (A)	Chassis No:	WVWZZZ7NZKV016297
Reg. Date:	29/11/2019 (Man. Year: 2019)	Odometer:	1784 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,188.64	4,559.99	1,628.65	26.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,150.00	5,450.00	3,700.00	40.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,338.64	10,009.99	5,328.65	34.74
+ GST 7.00/7.00% (\$\$)	1,073.70	700.70	373.00	34.74
Nett Amount (\$\$)	16,412.34	10,710.69	5,701.65	34.74
+ Car Rental (8.0 x S\$120.00/day + 7.00% GST) (\$\$)		1,027.20		
+ Other Costs (\$\$)		120.00		
Nett Liability (\$\$)		11,857.89		

INSPECTION

Date of Assignment: 24/12/2019

Date Inspected: 24/12/2019 Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Dented	1,144.79 FS	*1,144.79 FS
2	1		*SPOILER SATIN BLACK	Not Necessary	252.03 FS	*- FS
3	1		*ATTACHMENT STRIP BUMPER CENTRE BRACKET	Not Necessary	178.03 FS	*- FS
4	1		*FOAM INSERT	Not Necessary	126.41 FS	*- FS
5	1		*BUMPER BRACKET (BUMPER REINFORCEMENT)	Not Necessary	754.12 FS	*- FS
6	1		*GUIDE PIECE (BUMPER SIDE BRACKET LH)	Not Necessary	76.72 FS	*- FS
7	1		*GUIDE PIECE (BUMPER SIDE BRACKET RH)	Not Necessary	76.72 FS	*- FS
8	1		*REAR TRUNK LID	Dented	2,734.69 FS	*2,734.69 FS
9	1		*INSCRIPTION CHROME (SHARAN)	Necessary	83.72 FS	*83.72 FS
10	1		*VW SIGN BLACK HIGH GLOSS	Necessary	98.06 FS	*98.06 FS
11	1		*PACKING ADHESIVE REAR NUMBER PLATE PACKING	Broken	27.03 FS	*27.03 FS
12	1		*ADDITIONAL BRAKE LIGHT WI 3RD BRAKE LIGHT	Necessary	208.66 FS	*208.66 FS
13	1		*SEAL RING SATIN BLACK	Necessary	0.69 FS	*0.69 FS
14	1		*SENSOR PRIMED	Not Necessary	164.62 FS	*- FS
15	2		*1K WINDOW ADHESIVE	Necessary	99.76 FS	*99.76 FS
16	1		*PRIMER	Necessary	25.92 FS	*25.92 FS
17	2		*APPLICATOR	Necessary	18.96 FS	*18.96 FS
18	1		*ACTIVATOR FOR PRECOATED W	Necessary	24.00 FS	*24.00 FS
19	1		*ALL PURPOSE CLEANER	Necessary	89.95 FS	*89.95 FS
20	2		*RIVETTED CAP NUT	Necessary	3.76 FS	*3.76 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 6,188.64 4,559.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
3	R&R REAR WINDSCREEN GLASS	New	840.00	840.00
4	LABOUR	New	3,360.00	1,680.00
5	SPRAY PAINTING	New	3,200.00	1,600.00
6	CHECK REAR WATER LEAK TEST	New	150.00	150.00
7	TRANSFER BOOTLID PARTS	New	840.00	420.00
Gross Labour Cost (\$\$)			9,150.00	5,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >