

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19022530/HBA3Q2

Date: 03/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100293125

Claimant
Vehicle No : SJV1502C **Insured Vehicle No :** SKE5605R

Date of Loss: 17/12/2019 Nature of Claim: TP Claim No: 5522099905SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV1502C		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	3ZZ4963901
Reg. Date:	13/01/2010 (Man. Year: 2009)	Chassis No:	MR053ZEE106165404
Colour:	Silver	Odometer:	137750 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	APLUS 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	APLUS 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,937.56	5,389.67	4,547.89	45.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,700.00	3,390.00	2,310.00	40.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,637.56	8,779.67	6,857.89	43.86
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	15,637.56	7,000.00	8,637.56	55.24
+ Car Rental (11.0 x S\$100.00/day) (S\$)		1,100.00		
Nett Liability (S\$)		8,100.00		

INSPECTION

Date of Assignment: 20/12/2019

Date Inspected: 20/12/2019 Inspected At:

Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22
Autobay
Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: LEE HOCK ANN

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	785.20 FL	*700.30 FL
2	1		*BOOTLID LOGO	Necessary	89.60 FL	*52.10 FL
3	1		*BOOTLID COROLLA EMBLEM	Necessary	85.20 FL	*42.20 FL
4	1		*BOOTLID ALTIS EMBLEM	Necessary	86.30 FL	*44.20 FL
5	1		*BOOTLID 1.6 EMBLEM	Necessary	82.60 FL	*32.40 FL
6	1		*BOOTLID OUTER CHROME GARNISH	Cracked	298.70 FL	*253.70 FL
7	2		*BOOTLID NUMBER PLATE LAMPS	Serviceable	159.20 FL	*- FL
8	1		*BOOTLID INNER TRIM	Crumpled	265.30 FL	*220.80 FL
9	2		*BOOTLID LAMPS	Cracked	595.60 FL	*510.40 FL
10	2		*BOOTLID LAMPS INNER SEALER	Necessary	80.00 FL	*20.00 FL
11	2		*BOOTLID LAMPS INNER COVER	Serviceable	104.60 FL	*- FL
12	1		*BOOTLID INNER LOCK	Jammed	148.60 FL	*148.60 FL
13	1		*BOOTLID LOCK CATCH	Repair	55.20 FL	*- FL
14	1		*BOOTLID WEATHERSTRIP	Crumpled	197.60 FL	*155.60 FL
15	2		*BOOTLID HINGES	Repair	176.40 FL	*- FL
16	1		*BOOTLID STOPPERS	N/S Missing	100.00 FL	*15.00 FL
17	1		*REAR BUMPER	Cut	598.70 FL	*485.50 FL
18	2		*REAR BUMPER SIDE RETAINERS (LONG)	Necessary	175.00 FL	*120.40 FL
19	2		*REAR BUMPER SIDE RETAINERS (SHORT)	Necessary	97.40 FL	*97.40 FL
20	1		*REAR REINFORCEMENT WITH SPONGE	Serviceable	205.60 FL	*- FL
21	1		*REAR REINFORCEMENT BRACKETS	Damaged	145.20 FL	*82.80 FL
22	1		*REAR BUMPER REFLECTORS	O/S Crumpled	150.60 FL	*56.80 FL
23	2		*TAILAMPS	Cracked	797.40 FL	*634.80 FL
24	2		*TAILAMPS INNER SEALER	Necessary	80.00 FL	*20.00 FL
25	2		*TAILAMPS PANELS	Bent	591.20 FL	*167.60 FL
26	1		*END PANEL	Cut	598.70 FL	*470.80 FL
27	1		*END PANEL TOP GARNISH	Cracked	198.40 FL	*120.80 FL
28	1		*SPARE TYRE PANEL	Bent	698.70 FL	*560.80 FL
29	1		*SPARE TYRE PANEL TOP BOARD	Cracked	368.50 FL	*276.60 FL
30	1		*SPARE TYRE WHEEL CAP	Crumpled	65.20 FL	*32.80 FL
31	1		*REAR FENDERS	O/S Bent / N/S Repair	1,809.32 FL	*790.80 FL
32	2		*REAR FENDER INNER COWLING	Serviceable	197.20 FL	*- FL
33	1		*REAR FENDER INNER TRIM	O/S Cracked	718.40 FL	*281.50 FL
34	1		*REAR WINDSCREEN MOLDING	Necessary	98.70 FL	*75.60 FL
35	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FL	*30.00 FL
36	1		*REAR AIR VENT LH	Crumpled	98.70 FL	*34.50 FL
37	1		*REAR SILENCER BOX	Repair	756.30 FL	*- FL
38	2		*REAR EXHAUST MOUNTING	Serviceable	84.60 FL	*- FL
39	1		*REAR EXHAUST GASKET	Serviceable	54.30 FL	*- FL
40	1		*SET REAR NUMBER PLATE WITH CASING	Necessary	50.00 FS	*30.00 FS
41	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*20.00 FS
42	1		*SET BOOTLID CHROME GARNISH CLIPS	Necessary	30.00 FS	*15.00 FS
43	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	30.00 FS	*20.00 FS
44	1		*SET REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
45	2		*SET TAILLAMPS CLIPS	Necessary	60.00 FS	*20.00 FS
46	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FS	*20.00 FS
47	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*30.00 FS
48	1		*SET SPARE TYRE INSULATOR PADS	Necessary	200.00 FS	*30.00 FS
49	2		*SET REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
50	1		*REAR REINFORCEMENT BRACKET LH	Bent	145.20 FL	*98.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 12,963.42 7,047.90
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,025.86 1,658.23

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	9,937.56
						5,389.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS ,REPLACE BEAT WELD ,REALIGN ,STRAIGHTENED MEMBER	New	2,200.00	1,500.00
2	TO RESPRAY AFFECTED AREAS	New	2,000.00	1,500.00
3	TO TUFFCOAT AFFECTED AREA	New	150.00	70.00
4	TO REMOVE/REFIT REAR WINDSCREEN	New	150.00	100.00
5	TO REMOVE/REFIT FUEL TANK TO FACILITATE FENDER REPLACEMENT	New	180.00	0.00
6	TO CONDUCT WATER LEAKAGE TEST	New	80.00	40.00
7	TO REMOVE/REFIT INTERIOR UPHOLSTERY	New	180.00	0.00
8	TO REMOVE /REFIT REPLACE BOOTLID MECHANISM	New	150.00	0.00
9	TO REMOVE /REFIT REAR SILENCER BOX	New	120.00	70.00
10	TO REMOVE/REFIT /REPLACE REAR SENSOR AND DISTANCE SETTLING	New	120.00	70.00
11	LABOUR TO APPLY SEALANT TO AFFECTED AREAS	New	250.00	0.00
12	TO REMOVE/REFIT WIRING CHECKS ON REAR TAILAMP	New	120.00	40.00
Gross Labour Cost (\$)			5,700.00	3,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >