



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 9197X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID (CONSISTENT)	NOT NECESSARY	1,034.20	-
1	REAR EMBLEM (CONSISTENT)	NOT NECESSARY	67.40	-
1	REAR LOGO - LANCER (CONSISTENT)	NOT NECESSARY	65.30	-
1	REAR LOGO - EX (CONSISTENT)	NOT NECESSARY	65.90	-
1	LH BOOTLID LAMP (CONSISTENT)	NOT NECESSARY	476.90	-
1	REAR BUMPER (CONSISTENT)	DENTED	899.40	899.40
10	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
1	LH REAR BUMPER RETAINER (CONSISTENT)	BROKEN	67.80	67.80
1	LH REAR BUMPER BRACKET (CONSISTENT)	NOT NECESSARY	99.50	-
1	LH REAR BUMPER REFLECTOR (CONSISTENT)	NOT NECESSARY	196.40	-
2	REAR NUMBER PLATE LAMP (CONSISTENT)	NOT NECESSARY	289.60	-
1	LH TAILLAMP (CONSISTENT)	NOT NECESSARY	769.20	-
1	LH REAR FENDER (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	REAR REINFORCEMENT (CONSISTENT)	NOT NECESSARY	396.40	-
1	REAR BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	211.30	-
1	END PANEL (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
LESS 10% DISCOUNT			-466.93	-99.72
			4,202.37	897.48
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	250.00	-
1	REAR BUMPER LOWER SKIRT (SN) (CONSISTENT)	BROKEN	657.40	400.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	80.00	30.00
			1,037.40	430.00
<u>LABOUR</u>				
LABOUR FOR FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF LH REAR FENDER AND END PANEL.			1,200.00	300.00
TO RESPRAY BOOTLID.			300.00	-
TO RESPRAY REAR BUMPER.			300.00	200.00

Report Ref No. CC4/ASM19022533/Epa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY LH REAR FENDER.		300.00	200.00
	TO RESPRAY END PANEL.	NOT NECESSARY	300.00	-
	TO REMOVE AND REFIT REAR BOOTLID COMPONENT.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT REAR TRIM.	NOT NECESSARY	150.00	-
	RUST PROOFING.		100.00	30.00
			2,800.00	730.00
GRAND TOTAL			8,039.77	2,057.48

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,650.00
---	--	--	--	-----------------

Report Ref No. CC4/ASM19022533/Epa3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.