

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19022545/APS3Q2

Date: 14/04/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00015675

Claimant Vehicle No : SLC8737Y **Insured Vehicle No :** SLT1221A

Date of Loss: 20/12/2019 Nature of Claim: TP Claim No: 1201900041223

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC8737Y		
Make & Model:	HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A)	Engine No:	L15B4034711
Reg. Date:	27/05/2016 (Man. Year: 2016)	Chassis No:	RU11114704
Colour:	White	Odometer:	58382 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,264.90	8,060.00	6,204.90	43.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,230.00	3,560.00	1,670.00	31.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,494.90	11,620.00	7,874.90	40.39
Approved Total (Overridden) (S\$)		9,200.00		
Nett Amount (S\$)	19,494.90	9,200.00	10,294.90	52.81
+ Loss of Use (13.0 x S\$60.00/day) (S\$)		780.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,987.45		
Global Sum Settlement (S\$)		9,980.00		

INSPECTION

Date of Assignment: 23/12/2019

Date Inspected: 23/12/2019 Inspected At:

Advance Auto Garage (HQ)
23 KAKI BUKIT AVENUE 4 #04-01
AAS KAKI BUKIT CENTRE
Singapore 415933

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Apr 2020)
Parts:	144	HONDA VEZEL 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC8737Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	2		*REAR NUMBER PLATE LAMP	Not Necessary	130.00 F	*- FL
4	1		*REAR BUMPER	Distorted	880.00 F	*880.00 FL
5	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
6	2		*REAR BUMPER SIDE HOLDER	Necessary	71.20 F	*71.20 FL
7	1		*REAR BUMPER REFLECTOR	O/S Cracked	312.40 F	*156.20 FL
8	2		*REAR BUMPER SIDE	Deformed	390.00 F	*390.00 FL
9	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
10	1		*REAR END PANEL	Dented	595.60 F	*595.60 FL
11	1		*REAR END PANEL TOP GARNISH	Deformed	156.40 F	*156.40 FL
12	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 F	*20.00 FL
13	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
14	1		*REAR END PANEL ANTENNA	Cracked	98.10 F	*98.10 FL
15	1		*REAR END PANEL BUZZER	Cracked	91.60 F	*91.60 FL
16	2		*TAILLAMP	Cracked	921.00 F	*921.00 FL
17	1		*TAILGATE	Distorted	1,100.40 F	*1,100.40 FL
18	1		*TAILGATE LOCK	Jammed	237.50 F	*237.50 FL
19	1		*TAILGATE WEATHERSTRIPE	Cut	165.90 F	*165.90 FL
20	1		*TAILGATE INNER HOLDER	Not Necessary	30.50 F	*- FL
21	1		*TAILGATE OUTER GARNISH	Not Necessary	385.00 F	*- FL
22	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 F	*- FL
23	1		*TAILGATE INNER TRIM BOARD	Deformed	321.70 F	*321.70 FL
24	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 F	*30.00 FL
25	2		*TAILGATE DAMPER	Not Necessary	264.00 F	*- FL
26	2		*TAILGATE HINGE	Not Necessary	148.20 F	*- FL
27	1		*TAILGATE GLASS MOULDING	Necessary	125.00 F	*125.00 FL
28	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
29	1		*HONDA LOGO	Not Necessary	35.00 F	*- FL
30	1		*VEZEL EMBLEM	Necessary	40.80 F	*40.80 FL
31	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
32	2		*REAR FENDER	Repair	1,990.00 F	*- FL
33	2		*REAR FENDER INNER TRIM	Cracked	650.80 F	*650.80 FL
34	1		*REAR FENDER INNER TRIM CLIPS	Necessary	60.00 F	*60.00 FL
35	2		*REAR FENDER INNER SHIELD	Not Necessary	319.80 F	*- FL
36	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 F	*- FL
37	2		*REAR FENDER ARC GARNISH	Cracked	390.80 F	*390.80 FL
38	1		*REAR FENDER ARC GARNISH CLIPS	Necessary	40.00 F	*40.00 FL
39	1		*SPARE TYRE PANEL	Distorted	1,130.00 F	*1,130.00 FL
40	1		*SPARE TYRE PANEL TOP BOARD	Deformed	305.40 F	*305.40 FL
41	1		*SPARE TYRE PANEL UNDER COVER	Deformed	245.80 F	*245.80 FL
42	1		*SPARE TYRE PANEL UNDER COVER CLIPS	Necessary	30.00 F	*30.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
44	1		*SPARE TYRE PANEL CROSS MEMBER	Bent	130.80 F	*130.80 FL
45	1		*REAR EXHAUST PIPE	Bent	704.90 F	*704.90 FL
46	1		*REAR EXHAUST TAIL PIPE	Bent	150.00 FS	*80.00 FS
47	1		*REAR EXHAUST MOUNTING	Not Necessary	36.20 F	*- FL
48	1		*REAR EXHAUST HEAT SHIELD	Crumpled	98.30 F	*98.30 FL
49	1		*TOOLS TRAY SPONGE	Cracked	281.80 F	*281.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,264.90	9,960.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,900.00
Total Parts (\$)	14,264.90	8,060.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	2,200.00	1,400.00
2	SPRAY PAINTING	New	1,800.00	1,400.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	100.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE UPHOLSTERY AND REAR SEAT	New	350.00	250.00
8	TO REMOVE EXHAUST PIPE	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
Gross Labour Cost (S\$)			5,230.00	3,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >