

Claim Documents

*SKW6526J (615430)
OD
Dec 22 2019 2:00PM
[CHUNG SU ANN CHERYL]
Volkswagen Centre Singapore

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	23/12/19 10:00	Accident Statement	 Load HTM	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/12/19 17:19	Adjuster Immediate Advice	 Load HTM	☒
2	30/12/19 10:10	Adjuster Immediate Advice	 Load HTM	☒
Photos/Images			3 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
8	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
9	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
10	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
11	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
12	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
13	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
14	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
15	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
16	23/12/19 10:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/12/19 12:01	Odometer Reading	 Load JPG	☒
2	26/12/19 12:01	Chassis Number	 Load JPG	☒
3	26/12/19 12:01	General View	 Load JPG	☒
4	26/12/19 12:01	General View	 Load JPG	☒
5	26/12/19 12:01	General View	 Load JPG	☒
6	26/12/19 12:01	General View	 Load JPG	☒
7	26/12/19 12:01	General View	 Load JPG	☒
8	26/12/19 12:01	General View	 Load JPG	☒
9	26/12/19 12:01	General View	 Load JPG	☒
10	26/12/19 12:01	General View	 Load JPG	☒
11	26/12/19 12:01	General View	 Load JPG	☒
12	26/12/19 12:01	General View	 Load JPG	☒
13	26/12/19 12:01	General View	 Load JPG	☒
14	26/12/19 12:01	General View	 Load JPG	☒
15	26/12/19 12:01	General View	 Load JPG	☒
16	26/12/19 12:01	General View	 Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)		Thumbnail	Print
17	26/12/19 12:01	General View		Load JPG	☒
18	26/12/19 12:01	General View		Load JPG	☒
19	26/12/19 12:01	General View		Load JPG	☒
20	26/12/19 12:01	General View		Load JPG	☒
21	26/12/19 12:01	General View		Load JPG	☒
22	26/12/19 12:01	General View		Load JPG	☒
23	26/12/19 12:01	General View		Load JPG	☒
24	26/12/19 12:01	General View		Load JPG	☒
25	26/12/19 12:01	General View		Load JPG	☒
26	26/12/19 12:01	General View		Load JPG	☒
27	26/12/19 12:01	General View		Load JPG	☒
28	26/12/19 12:01	General View		Load JPG	☒
29	26/12/19 12:01	General View		Load JPG	☒
30	26/12/19 12:01	General View		Load JPG	☒
31	26/12/19 12:01	General View		Load JPG	☒
32	26/12/19 12:01	General View		Load JPG	☒
33	26/12/19 12:01	General View		Load JPG	☒
34	26/12/19 12:01	General View		Load JPG	☒
35	26/12/19 12:01	General View		Load JPG	☒
36	26/12/19 12:01	General View		Load JPG	☒
37	26/12/19 12:01	General View		Load JPG	☒
38	26/12/19 12:01	General View		Load JPG	☒
39	26/12/19 12:01	General View		Load JPG	☒
40	26/12/19 12:01	General View		Load JPG	☒
41	26/12/19 12:01	General View		Load JPG	☒
42	26/12/19 12:01	General View		Load JPG	☒
43	26/12/19 12:01	General View		Load JPG	☒
44	26/12/19 12:01	General View		Load JPG	☒
45	26/12/19 12:01	General View		Load JPG	☒
46	26/12/19 12:01	General View		Load JPG	☒
47	26/12/19 12:01	General View		Load JPG	☒
48	26/12/19 12:01	General View		Load JPG	☒
49	26/12/19 12:01	General View		Load JPG	☒
50	26/12/19 12:01	General View		Load JPG	☒
51	26/12/19 12:01	General View		Load JPG	☒
52	26/12/19 12:01	General View		Load JPG	☒
53	26/12/19 12:01	General View		Load JPG	☒
54	26/12/19 12:01	General View		Load JPG	☒
55	26/12/19 12:01	General View		Load JPG	☒
56	26/12/19 12:01	General View		Load JPG	☒
57	26/12/19 12:01	General View		Load JPG	☒
58	26/12/19 12:01	General View		Load JPG	☒
59	26/12/19 12:01	General View		Load JPG	☒
60	26/12/19 12:01	General View		Load JPG	☒
61	26/12/19 12:01	General View		Load JPG	☒
62	26/12/19 12:01	General View		Load JPG	☒
63	03/01/20 11:22	DISMANTLE PHOTO		Load JPG	☒
64	03/01/20 11:22	DISMANTLE PHOTO		Load JPG	☒
65	03/01/20 11:22	DISMANTLE PHOTO		Load JPG	☒
66	03/01/20 11:22	DISMANTLE PHOTO		Load JPG	☒
67	03/01/20 11:22	DISMANTLE PHOTO		Load JPG	☒
68	03/01/20 11:22	DISMANTLE PHOTO		Load JPG	☒
69	03/01/20 11:22	DISMANTLE PHOTO		Load JPG	☒
70	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
71	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
72	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)		Thumbnail	Print
73	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
74	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
75	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
76	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
77	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
78	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
79	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
80	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
81	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
82	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
83	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
84	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
85	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
86	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
87	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
88	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
89	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
90	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
91	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
92	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
93	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
94	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
95	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
96	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
97	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
98	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
99	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
100	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
101	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
102	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
103	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
104	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
105	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
106	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
107	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
108	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
109	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
110	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
111	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
112	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
113	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
114	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
115	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
116	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
117	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
118	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
119	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
120	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
121	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
122	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
123	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
124	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
125	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
126	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
127	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
128	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)		Thumbnail	Print
129	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
130	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
131	03/01/20 11:23	DISMANTLE PHOTO		Load JPG	☒
132	03/01/20 11:24	BEFORE PAINT PHOTO		Load JPG	☒
133	03/01/20 11:24	BEFORE PAINT PHOTO		Load JPG	☒
134	03/01/20 11:24	BEFORE PAINT PHOTO		Load JPG	☒
135	03/01/20 11:24	BEFORE PAINT PHOTO		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/12/19 10:31	Estimate from Volkswagen		Load PDF	
2	24/12/19 10:32	Email from Volkswagen to arrange for survey urgently		Load PDF	
No	Finalized On	Volkswagen Centre Singapore (HQ)		Thumbnail	Print
1	23/12/19 09:17	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	23/12/19 09:17	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	
3	23/12/19 09:17	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	☒
4	23/12/19 09:17	Driving License [Linked Accident Report Documents]		Load JPG	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	24/12/19 11:14	Email - Outsource Instruction		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/12/19 12:04	ESTIMATE		Load PDF	
2	30/12/19 10:06	SUPPLEMENTARY LIST		Load PDF	

Linked Accident Report Documents

Photos/Images				View	View in Browser
No	Finalized On	Volkswagen Centre Singapore (HQ)		Thumbnail	Print
1	23/12/19 10:00	Accident Photo		Load JPG	☒
2	23/12/19 10:00	Accident Photo		Load JPG	☒
3	23/12/19 10:00	Accident Photo		Load JPG	☒
4	23/12/19 10:00	Accident Photo		Load JPG	☒
5	23/12/19 10:00	Accident Photo		Load JPG	☒
6	23/12/19 10:00	Accident Photo		Load JPG	☒
7	23/12/19 10:00	Accident Photo		Load JPG	☒
8	23/12/19 10:00	Accident Photo		Load JPG	☒
9	23/12/19 10:00	Accident Photo		Load JPG	☒
10	23/12/19 10:00	Accident Photo		Load JPG	☒
11	23/12/19 10:00	Accident Photo		Load JPG	☒
12	23/12/19 10:00	Accident Photo		Load JPG	☒
13	23/12/19 10:00	Accident Photo		Load JPG	☒
14	23/12/19 10:00	Accident Photo		Load JPG	☒
15	23/12/19 10:00	Accident Photo		Load JPG	☒
16	23/12/19 10:00	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)		Thumbnail	Print
1	23/12/19 09:17	Sketch Plan		Load TIF	
2	23/12/19 09:17	Sketch Plan #2		Load TIF	
3	23/12/19 09:17	Accident Sketch Plan		Load JPG	☒
4	23/12/19 09:17	Driving License		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19022558/R1QF3E2

Date: 09/01/2020

REFERENCE

Insured/Claimant:	CHUNG SU ANN CHERYL	Policy No:	28639772AVW
Date of Loss:	22/12/2019	Nature of Claim:	OD
		Claim No:	615430

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW6526J	Engine No:	CCZ483142
Make & Model:	VOLKSWAGEN SHARAN, 2.0 TSI (A)	Chassis No:	WVWZZZ7NZFV040789
Reg. Date:	09/11/2015 (Man. Year: 2015)	Odometer:	49663 km
Colour:	Brown		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$93,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55Z R17	Rear Tyre Size:	215/55Z R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,467.47	11,319.17	4,148.30	26.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,658.00	4,758.00	2,900.00	37.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,125.47	16,077.17	7,048.30	30.48
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	21,125.47	14,077.17	7,048.30	33.36
+ GST 7.00/7.00% (S\$)	1,478.78	985.40	493.38	33.36
Nett Amount (S\$)	22,604.25	15,062.57	7,541.68	33.36

INSPECTION

Date of Assignment: 24/12/2019

Date Inspected: 24/12/2019 Inspected At:

Volkswagen Centre Singapore (Tuas)
17 TUAS AVENUE
Singapore 639176

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2020)
Parts:	M1-MPV	VOLKSWAGEN SHARAN 2.0 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW6526J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD FRT BONNET	Bent	1,061.29 FS	*1,061.29 FS
2	1		*FLAP HINGE BONNET HINGE LH	Bent	115.73 FS	*115.73 FS
3	1		*FLAP HINGE BONNET HINGE RH	Bent	115.73 FS	*115.73 FS
4	1		*HOOK LATCH	Bent	62.96 FS	*62.96 FS
5	1		*HOOD LATCH LOWER PORTION LOCK	Bent	95.60 FS	*95.60 FS
6	1		*COVER FOR BUMPER PRIMED	Deformed	1,076.62 FS	*1,076.62 FS
7	1		*BUMPER BRACKET REINFORCEMENT	Bent	496.42 FS	*496.42 FS
8	1		*GUIDE PIECE BUMPER CENTRE BRACKET	Cracked	94.80 FS	*94.80 FS
9	1		*SUPPORT PART BUMPER INNER BRACKET LH	Serviceable	18.42 FS	*- FS
10	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Cracked	22.81 FS	*22.81 FS
11	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Serviceable	22.81 FS	*- FS
12	1		*CAP PRIMED NOZZLE CAP RH	Serviceable	39.42 FS	*- FS
13	1		*CAP PRIMED NOZZLE LH	Serviceable	39.42 FS	*- FS
14	1		*JET CARRIER WITH JET NOZZLE LH	Serviceable	28.71 FS	*- FS
15	1		*PRESSURE CYLINDER NOZZLE CYLINDER LH	Serviceable	129.04 FS	*- FS
16	2		*SENSOR PRIMED	Serviceable	237.05 FS	*- FS
17	1		*GRILL SATIN BLACK BUMPER CENTRE LOWER GRILLE	Cut	120.30 FS	*120.30 FS
18	1		*DECORATIVE MOULDING BRIGH CENTRE LOWER GRILLE CHROM	Cracked	136.43 FS	*136.43 FS
19	1		*COOLING AIR GRILL SATIN B FOG LAMP GRILLE LH	Cut	115.80 FS	*115.80 FS
20	1		*RADIATOR GRILLE SATIN BLA	Cracked	327.23 FS	*327.23 FS
21	1		*HEADLAMPS FOR CURVE LIGHT H/LAMP RH	Cracked	1,607.40 FS	*1,607.40 FS
22	1		*HEADLAMPS FOR CURVE LIGHT H/LAMP LH	Broken	1,607.40 FS	*1,607.40 FS
23	1		*GAS DISCHARGE BULB	Serviceable	399.07 FS	*- FS
24	1		*CONTROL UNIT FOR CORNERIN	Cut	424.12 FS	*424.12 FS
25	1		*BALLAST FOR GAS DISCHARGE	Serviceable	558.17 FS	*- FS
26	1		*POWER MODULE FOR DAY DRIV	Serviceable	275.87 FS	*- FS
27	1		*FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING (2PCS)	Cracked (1Pc Only)	25.85 FS	*12.92 FS
28	1		*LOCK CARRIER WITH MOUNTIN	Cracked	604.63 FS	*604.63 FS
29	1		*SUPPORT FOR LOCK CARRIER	Bent	79.10 FS	*79.10 FS
30	1		*CROSS SUPPORT H/LAMP TOP PANEL LH	Bent	39.43 FS	*39.43 FS
31	1		*CROSS SUPPORT H/LAMP TOP PANEL RH	Bent	39.43 FS	*39.43 FS
32	1		*AIR DUCT SATIN BLACK	Serviceable	35.06 FS	*- FS
33	1		*INTAKE AIR DUCT SATIN BLA	Serviceable	10.22 FS	*- FS
34	1		*REFRIGERANT CONDENSER WIT A/C CONDENSER	Bent	584.99 FS	*584.99 FS
35	1		*CHARGE AIR COOLER	Serviceable	608.28 FS	*- FS
36	1		*AIR PIPE CENTRE PRESSURE PIPE	Serviceable	157.79 FS	*- FS
37	1		*RADIATOR	Bent	543.90 FS	*543.90 FS
38	2		*COOLANT CONCENTRATE	Necessary	61.68 FS	*61.68 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*WATER HOSE WITH THERMOSTA RADIATOR TOP HOSE	Serviceable	179.42 FS	*- FS
40	1		*QUICK COUPLING PIECE RADIATOR TOP HOSE ADAPTOR	Cracked	17.27 FS	*17.27 FS
41	1		*AIR DUCT AIR GUIDE RH	Serviceable	28.09 FS	*- FS
42	1		*AIR DUCT AIR GUIDE LH	Cracked	28.09 FS	*28.09 FS
43	1		*DUAL FAN COWL	Serviceable	170.85 FS	*- FS
44	1		*ELECTRIC FAN	Serviceable	507.12 FS	*- FS
45	1		*ELECTRIC FAN	Shorted	938.65 FS	*938.65 FS
46	1		*BATTERY TRAY	Serviceable	48.60 FS	*- FS
47	1		*AIR DUCT U-AIR INTAKE PIPE	Cracked	23.24 FS	*23.24 FS
48	1		*AIR CLEANER	Cracked	218.02 FS	*218.02 FS
49	1		*WASH WATER RESERVOIR WIPER TANK	Serviceable	101.07 FS	*- FS
50	1		*GASKET	Not Necessary	3.10 FS	*- FS
51	1		*GASKET	Not Necessary	1.31 FS	*- FS
52	1		*WINDSHIELD CLEANER CONCEN	Serviceable	11.38 FS	*- FS
53	1		*FENDER RH	Serviceable	525.10 FS	*- FS
54	1		*FENDER LH	Bent	525.10 FS	*525.10 FS
55	1		*CROSS SUPPORT FENDER BRACKET LH	Bent	28.21 FS	*28.21 FS
56	1		*FRONT NUMBER PLATE	Bent	80.00 FS	*80.00 FS
57	1		*BONNET STOPPER	Necessary	13.87 FS	*13.87 FS
					Total Parts (\$\$)	15,467.47 11,319.17

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK SHORT CIRCUIT / HARNESS REPAIR	New	200.00	200.00
2	DIAGNOSTIC AND PROGRAMMING	New	360.00	360.00
3	LEAKED CHECK, VACUUM & REGAS	New	238.00	238.00
4	A/C GAS	New	60.00	60.00
5	LABOUR	New	3,800.00	1,900.00
6	SPRAY PAINTING	New	3,000.00	2,000.00
Gross Labour Cost (S\$)			7,658.00	4,758.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >