

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19022559/ESF3E2

Date: 16/04/2020

REFERENCE

Insured/Claimant:	HUANG ZHONGSEN, JASON	Policy No:	1900093890
Date of Loss:	20/12/2019	Nature of Claim:	OD Claim No: 6226180037SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML225B	Engine No:	CVK077959
Make & Model:	AUDI A4, 2.0 TFSI Limited Edition (A)	Chassis No:	WAUZZZF43KA047352
Reg. Date:	30/04/2019 (Man. Year: 2019)	Odometer:	28528 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$132,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	245/40Z R18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,147.00	8,246.64	4,900.36	37.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,752.00	3,822.00	2,930.00	43.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,899.00	12,068.64	7,830.36	39.35
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	19,099.00	11,268.64	7,830.36	41.00
+ GST 7.00/7.00% (S\$)	1,336.93	788.80	548.13	41.00
Nett Amount (S\$)	20,435.93	12,057.44	8,378.49	41.00

INSPECTION

Date of Assignment:	24/12/2019	
Date Inspected:	24/12/2019	Inspected At: 281 Alexandra Road
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,999.00 FS	*1,599.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	531.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Necessary	32.00 FS	*25.44 FS
4	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	56.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	123.00 FS	*- FS
6	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
7	1		*FRONT BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
8	1		*FRONT BUMPER GUIDE SECTION - LH	Broken	33.00 FS	*26.08 FS
9	1		*LOCK CARRIER BRACKET	Not Necessary	125.00 FS	*- FS
10	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	52.00 FS	*- FS
11	1		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	231.00 FS	*- FS
12	4		*FRONT PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
13	1		*FRONT FENDER - LH	Dented	700.00 FS	*559.60 FS
14	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	183.00 FS	*- FS
15	1		*FRONT FENDER CLOSING ELEMENT - LH	Bent	45.00 FS	*36.00 FS
16	1		*FRONT FENDER BRACKET - LH	Not Necessary	32.00 FS	*- FS
17	1		*DEFORMATION ELEMENT BRACKET - LH	Not Necessary	45.00 FS	*- FS
18	1		*FRONT FENDER BRACE - LH	Bent	107.00 FS	*85.60 FS
19	1		*FRONT WHEEL HOUSING LINER - LH	Crushed	223.00 FS	*178.40 FS
20	1		*FRONT WHEEL SPOILER - LH	Deformed	66.00 FS	*52.32 FS
21	1		*FRONT WHEEL SPOILER TRIM - LH	Not Necessary	32.00 FS	*- FS
22	1		*STONE CHIP GUARD - LH	Not Necessary	46.00 FS	*- FS
23	1		*FENDER LEDGE COVER - LH	Not Necessary	28.00 FS	*- FS
24	1		*FENDER LEDGE TOP COVER - LH	Not Necessary	21.00 FS	*- FS
25	1		*LED HEADLIGHT - LH	Cut	7,087.00 FS	*5,669.60 FS
26	1		*LIFT CYLINDER - LH	Not Necessary	192.00 FS	*- FS
27	1		*FRONT ALUMINIUM RIM - LH (NPA)	Not Necessary	0.00 FS	*- FS
28	1		*SUNDRIES	Necessary	300.00 FS	*14.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 13,147.00 8,246.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,500.00
3	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER	New	3,000.00	1,650.00
4	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			6,752.00	3,822.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >