

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022575/AKA3Q2

Date: 17/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800063226

Claimant
Vehicle No : SLJ8355D **Insured Vehicle No :** SKB3769E

Date of Loss: 21/12/2019 Nature of Claim: TP Claim No: 5278692297SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ8355D		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	1ZZ2747322
Reg. Date:	03/01/2007 (Man. Year: 2006)	Chassis No:	ZNE100336545
Colour:	Silver	Odometer:	299076 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Dayton 6 mm	Rear Left Side:	Dayton 6 mm
Front Right Side:	Dayton 6 mm	Rear Right Side:	Dayton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,369.80	10,367.95	10,001.85	49.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,610.00	3,860.00	2,750.00	41.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,979.80	14,227.95	12,751.85	47.26
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	26,979.80	7,500.00	19,479.80	72.20
+ GST 7.00/7.00% (S\$)	1,888.59	525.00	1,363.59	72.20
Nett Amount (S\$)	28,868.39	8,025.00	20,843.39	72.20
+ Car Rental (11.0 x S\$130.00/day + 7.00% GST) (S\$)		1,530.10		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,562.55		
Global Sum Settlement (S\$)		9,560.00		

INSPECTION

Date of Assignment: 23/12/2019

Date Inspected: 23/12/2019 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4,, #08-09
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	1,280.00 FL	*1,280.00 FL
2	1		*TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
3	1		*TAILGATE OUTER MOULDING	Cracked	240.00 FL	*240.00 FL
4	1		*TAILGATE OUTER SWITCH BUTTOM	Not Necessary	460.00 FL	*- FL
5	1		*TAILGATE WIPER HEAD RUBBER	Not Necessary	90.00 FL	*- FL
6	1		*TAILGATE WIPER MOTOR	Damaged	745.00 FL	*745.00 FL
7	1		*TAILGATE INNER LOCK	Damaged	445.10 FL	*445.10 FL
8	1		*TAILGATE LOWER LOCK	Not Necessary	35.00 FL	*- FL
9	1		*TAILGATE DAMPER LH	Not Necessary	194.00 FL	*- FL
10	1		*TAILGATE INNER HOLDER	Deformed	48.00 FL	*48.00 FL
11	1		*TAILGATE STOPPER LH	Not Necessary	20.00 FL	*- FL
12	1		*TAILGATE WEATHER STRIP	Cut	320.00 FL	*320.00 FL
13	1		*TAILGATE INNER TRIM (TOP)	Not Necessary	285.00 FL	*- FL
14	2		*TAILGATE INNER TRIM (TOP SIDE)	Not Necessary	390.00 FL	*- FL
15	1		*TAILGATE INNER TRIM (LOWER)	Deformed	395.00 FL	*395.00 FL
16	1		*TAILGATE WINDSCREEN GLASS	Not Necessary	980.00 FL	*- FL
17	1		*TAILGATE WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
18	2		*REAR NUMBER PLATE LAMP	Not Necessary	104.00 FL	*- FL
19	1		*REAR BUMPER	Distorted	590.00 FL	*590.00 FL
20	2		*REAR BUMPER REFLECTOR	Not Necessary	136.00 FL	*- FL
21	1		*REAR BUMPER BRACKET	O/S Dented	140.20 FL	*70.10 FL
22	2		*REAR BUMPER SIDE RETAINER	Damaged	120.00 FL	*120.00 FL
23	1		*TAILLAMP C/W BRACKET RH	Smashed	520.00 FL	*410.00 FL
24	1		*TAILLAMP PANEL RH	Dented	670.00 FL	*670.00 FL
25	1		*TAILLAMP INNER PANEL RH	Repair	670.00 FL	*- FL
26	1		*REAR FENDER RH	Buckled	980.00 FL	*980.00 FL
27	1		*REAR FENDER INNER TRIM TOP (FRONT) RH	Cut	320.00 FL	*320.00 FL
28	1		*REAR FENDER INNER TRIM TOP (REAR) RH	Deformed	495.00 FL	*495.00 FL
29	1		*REAR FENDER INNER PANEL RH	Repair	1,065.00 FL	*- FL
30	2		*REAR FENDER INNER TRIM	Cracked	1,476.20 FL	*1,476.20 FL
31	1		*REAR FENDER QUARTER GLASS C/W MOULDING RH	Shattered	580.00 FL	*580.00 FL
32	2		*REAR FENDER INNER COWLING	Missing	760.00 FL	*760.00 FL
33	1		*REAR FENDER INNER BOTTOM PANEL RH	Repair	455.00 FL	*- FL
34	1		*REAR FENDER AIR VENT	Deformed	95.00 FL	*95.00 FL
35	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	198.00 FL	*- FL
36	1		*REAR DOOR LOCK CLUTCH RH	Not Necessary	45.00 FL	*- FL
37	1		*REAR DOOR INNER LOCK RH	Not Necessary	425.00 FL	*- FL
38	1		*REAR DOOR INNER TRIM BOARD RH	Not Necessary	785.00 FL	*- FL
39	1		*ROOF LINING		2,460.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR END PANEL	Not Necessary Distorted	480.00 FL	*480.00 FL
41	1		*REAR END PANEL TOP GARNISH	Deformed	245.00 FL	*245.00 FL
42	1		*REAR END PANEL (EXTEND) RH	Repair	298.70 FL	*- FL
43	1		*REAR END PANEL BOTTOM (CENTRE)	Dented	311.10 FL	*311.10 FL
44	1		*REAR FLOOR PANEL TOP BOARD (INNER SUPPORT)	Cracked	410.10 FL	*410.10 FL
45	1		*REAR FLOOR PANEL TOP BOARD	Deformed	460.00 FL	*460.00 FL
46	2		*REAR FLOOR PANEL SIDE BOARD	Not Necessary	390.00 FL	*- FL
47	1		*SPARE TYRE CHAIN	Not Necessary	350.00 FL	*- FL
48	1		*REAR NUMBER PLATE	Deformed	50.00 FS	*50.00 FS
49	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
50	1		*SET TAILLAMP CLIP	Necessary	30.00 FS	*10.00 FS
51	1		*TAILLAMP PANEL SEALANT RH	Not Necessary	80.00 FS	*- FS
52	1		*TAILLAMP INNER PANEL SEALANT RH	Not Necessary	80.00 FS	*- FS
53	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
54	1		*SET TAILGATE OUTER MULDING CLIP	Necessary	50.00 FS	*20.00 FS
55	1		*SET TAILGATE INNER TRIM (TOP) CLIP	Necessary	50.00 FS	*20.00 FS
56	1		*SET TAILGATE INNER TRIM (TOP SIDE) CLIP	Necessary	50.00 FS	*20.00 FS
57	1		*SET TAILGATE INNER TRIM (LOWER) CLIP	Necessary	50.00 FS	*20.00 FS
58	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
59	1		*TAILGATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*40.00 FS
60	1		*TAILGATE WINDSCREEN GLASS SOLAR FILM	Necessary	550.00 FS	*200.00 FS
61	1		*SET PRIVATE HRER DECAL	Necessary	80.00 FS	*30.00 FS
62	1		*TAILLAMP PANEL SEALANT RH	Not Necessary	60.00 FS	*- FS
63	1		*REAR FENDER RH SEALANT	Not Necessary	120.00 FS	*- FS
64	1		*REAR FENDER INNEM TRIM TOP (FRONT) RH	Necessary	50.00 FS	*20.00 FS
65	1		*REAR FENDER INNER TRIM TOP (REAR) RH	Necessary	50.00 FS	*20.00 FS
66	1		*REAR FENDER INNER PANEL SEALANT RH	Not Necessary	80.00 FS	*- FS
67	1		*REAR FENDER INNER BOTTOM PANEL SEALANT RH	Not Necessary	80.00 FS	*- FS
68	1		*SET REAR DOOR INNER TRIM BOARD CLIP RH	Not Necessary	50.00 FS	*- FS
69	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
70	1		*REAR FENDER QUARTER GLASS SEALANT LH	Necessary	80.00 FS	*40.00 FS
71	1		*REAR FENDER QUARTER GLASS INNER SHIELD LH	Not Necessary	60.00 FS	*- FS
72	1		*REAR FENDER QUARTER GLASS SOLAR FILM LH	Necessary	180.00 FS	*60.00 FS
73	1		*SET ROOF LINING CLIP	Not Necessary	150.00 FS	*- FS
74	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
75	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
76	1		*REAR END PANEL (EXTEND) INSULATION SEAL	Not Necessary	150.00 FS	*- FS
77	1		*REAR EXHAUST CHROME PIPE (SPECIAL TYPE)	Not Necessary	280.00 FS	*- FS
78	1		*REVERSE CAMERA	Damaged	450.00 FS	*380.00 FS
79	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	25,906.40	13,400.60
				- List Item Discount on L Items 25.00/25.00% (S\$)	5,536.60	3,032.65
				Total Parts (S\$)	20,369.80	10,367.95
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPACE PARTS	New	2,400.00	1,600.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,500.00
3	TUFF COAT	New	250.00	100.00
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	New	350.00	120.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTACE SETTING	New	80.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
8	REMOVE AND REFIX REAR VIDEO RECORDER	New	80.00	50.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
10	REMOVE AND REFIX REAR FENDER GLASS LH	New	80.00	60.00
11	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
12	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
13	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
14	REAR CHASSIS ALIGNMENT	New	180.00	0.00
15	VACUUM AND CLEAN REAR WINDSCREEN GLASS SPLINTER	New	250.00	100.00
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			6,610.00	3,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >