

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022580/KBA3Q2
Date: 01/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100376101
Claimant Vehicle No :	SJJ7811J	Insured Vehicle No :	SKN4066E
Date of Loss:	19/12/2019	Nature of Claim:	TP
		Claim No:	8671224353SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ7811J	Engine No:	1ZZ3135402
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDER12WX03000718
Reg. Date:	25/09/2008 (Man. Year: 2008)	Odometer:	236200 km
Colour:	Metallic Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	806.34	775.06	31.28	3.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	750.00	200.00	21.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,756.34	1,525.06	231.28	13.17
Approved Total (Overridden) (S\$)		1,200.00		

(S\$)	1,756.34	1,200.00	556.34	31.68
+ GST 7.00/7.00% (S\$)	122.94	84.00	38.94	31.67
Nett Amount (S\$)	1,879.28	1,284.00	595.28	31.68
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		1,612.00		
Global Sum Settlement (S\$)		1,600.00		

INSPECTION

Date of Assignment: 23/12/2019

Date Inspected: 26/02/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	564.30 FL	*564.30 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Distorted	62.80 FL	*62.80 FL
3	5		*REAR BUMPER CLIP	Necessary	19.45 FL	*19.45 FL
4	1		*LH TAILLAMP LOWER RETAINER	Not Necessary	41.70 FL	*- FL
5	1		*TAILGATE LOGO	Necessary	68.50 FL	*68.50 FL
6	1		*TAILGATE EMBLEM AEROTOURER	Necessary	51.70 FL	*51.70 FL
7	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	1,008.45
					- List Item Discount on L Items 25.00/25.00% (\$\$)	202.11
					Total Parts (\$\$)	806.34
						966.75
						191.69
						775.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR BUMPER REVERSE SENSORS ,TAILLAMPS ,KNOCKING & REPAIR REAR END PANEL & REALIGN TAILGATE THE SAME	New	350.00	250.00
2	PUTTY & RESPRAY REAR BUMPER ,REVERSE SENSORS ,TAILGATE REAR END PANEL & ALL AFFECTED AREAS	New	600.00	500.00
Gross Labour Cost (\$\$)			950.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >