

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19022584/GPS3Q2

Date: 02/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJA637P	Insured Vehicle No :	SHC1782J
Date of Loss: 19/12/2019	Nature of Claim: TP	Claim No: MCT19120470

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJA637P	Engine No:	HIDDEN
Make & Model:	HONDA CIVIC, 1.6 (A)	Chassis No:	JHMF46208S200207
Reg. Date:	27/11/2007 (Man. Year: 2007)	Odometer:	167003 km
Colour:	Blue		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,000.96	1,069.92	21,931.04	95.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,730.00	1,270.00	7,460.00	85.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,730.96	2,339.92	29,391.04	92.63
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	31,730.96	1,850.00	29,880.96	94.17
+ GST 7.00/7.00% (S\$)	2,221.17	129.50	2,091.67	94.17
Nett Amount (S\$)	33,952.13	1,979.50	31,972.63	94.17
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		2,575.95		
Global Sum Settlement (S\$)		2,570.00		

INSPECTION

Date of Assignment: 24/12/2019

Date Inspected: 24/12/2019 Inspected At:

RICO 60 AUTO SERVICES PTE LTD
(HQ)
8, KAKI BUKIT AVENUE 4, #02-24,

PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2021)
Parts:	143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA637P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	406.90 FL	*- FL
2	1		*BOOTLID	Repair	1,329.70 FL	*- FL
3	1		*BOOTLID LOGO (HONDA)	Necessary	109.70 FL	*39.60 FL
4	1		*BOOTLID EMBLEM (CIVIC)	Necessary	86.40 FL	*39.60 FL
5	1		*BOOTLID EMBLEM (1.6)	Necessary	81.80 FL	*20.90 FL
6	1		*BOOTLID EMBLEM (I.VTEC)	Necessary	87.90 FL	*39.60 FL
7	1		*BOOTLID HANDLE	Not Necessary	418.10 FL	*- FL
8	1		*BOOTLID LOCK SWITCH	Not Necessary	319.70 FL	*- FL
9	2		*BOOTLID CARPLATE LAMP (L+R)	Not Necessary	226.40 FL	*- FL
10	2		*BOOTLID LAMP (L+R)	Not Necessary	897.40 FL	*- FL
11	1		*BOOTLID INNER TRIM	Not Necessary	617.10 FL	*- FL
12	1		*BOOTLID LOCK	Not Necessary	418.40 FL	*- FL
13	1		*BOOTLID LOCK COVER	Not Necessary	199.40 FL	*- FL
14	1		*BOOTLID LOCK CATCH	Not Necessary	74.90 FL	*- FL
15	2		*BOOTLID HINGE (L+R)	Not Necessary	242.60 FL	*- FL
16	2		*BOOTLID HINGE COVER (L+R)	Not Necessary	310.40 FL	*- FL
17	2		*BOOTLID STOPPER (L+R)	Not Necessary	79.80 FL	*- FL
18	1		*BOOTLID WEATHERSTRIP	Twisted	319.60 FL	*104.50 FL
19	2		*TAIL LAMP (L+R)	Not Necessary	1,219.00 FL	*- FL
20	2		*TAIL LAMP PANEL (L+R)	Not Necessary	894.20 FL	*- FL
21	1		*REAR BUMPER	Deformed	1,190.60 FL	*638.00 FL
22	2		*REAR BUMPER RETAINER (L+R)	Deformed	296.40 FL	*46.20 FL
23	1		*REAR BUMPER REINFORCEMENT BAR (NPA)	Not Necessary	0.00 FL	*- FL
24	2		*REAR BUMPER BRACKET (L+R)	Not Necessary	319.20 FL	*- FL
25	1		*REAR BUMPER BEAM (NPA)	Not Necessary	0.00 FL	*- FL
26	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
27	1		*REAR BUMPER UNDERCOVER	Not Necessary	442.90 FL	*- FL
28	2		*REAR FENDER (L+R)	Not Necessary	2,649.80 FL	*- FL
29	2		*REAR FENDER INNER TRIM (L+R)	Not Necessary	1,294.40 FL	*- FL
30	2		*REAR FENDER COWLING (L+R)	Not Necessary	684.60 FL	*- FL
31	2		*REAR FENDER MUDFLAP (L+R)	Not Necessary	219.40 FL	*- FL
32	2		*REAR FENDER AIR VENT (L+R)	Not Necessary	206.20 FL	*- FL
33	2		*REAR QUARTER PANEL (L+R)	Not Necessary	896.40 FL	*- FL
34	1		*END PANEL	Repair	896.70 FL	*- FL
35	1		*END PANEL TOP GARNISH	Deformed	294.40 FL	*71.50 FL
36	1		*SPARE WHEEL PANEL	Not Necessary	1,679.80 FL	*- FL
37	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	796.10 FL	*- FL
38	1		*SPARE WHEEL PANEL TOP BOARD TOP MAT	Not Necessary	456.70 FL	*- FL
39	2		*SPARE WHEEL PANEL TOOLBOX (L+R)	Not Necessary	408.40 FL	*- FL
40	1		*EXHAUST PIPE	Not Necessary	1,296.10 FL	*- FL
41	1		*EXHAUST GASKET	Not Necessary	76.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	2		*EXHAUST BRACKET (L+R)	Not Necessary	176.20 FL	*- FL
43	1		*EXHAUST HEAT SHIELD	Not Necessary	231.10 FL	*- FL
44	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
45	10		*BOOTLID INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
46	1		*BOOTLID EMBLEM (HONDA)	Repeated	300.00 FS	*- FS
47	1		*REVERSE CAMERA	Damaged	800.00 FS	*250.00 FS
48	1		*REAR CARPLATE	Not Necessary	120.00 FS	*- FS
49	1		*REAR CARPLATE FRAME	Not Necessary	120.00 FS	*- FS
50	10		*REAR BUMPER CLIPS	Necessary	100.00 FS	*20.00 FS
51	2		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
52	1		*REAR FENDER SEALANT	Not Necessary	120.00 FS	*- FS
53	20		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
54	20		*REAR FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
55	4		*REAR FENDER MUDFLAP CLIPS	Not Necessary	80.00 FS	*- FS
56	1		*REAR QUARTER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
57	1		*END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
58	10		*END PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
59	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	120.00 FS	*- FS
60	1		*SPARE TYRE	Not Necessary	700.00 FS	*- FS
61	1		*SPARE RIM	Not Necessary	1,000.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,571.20	1,269.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,570.24	199.98
Total Parts (\$\$)	23,000.96	1,069.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RNR ACCIDENT DAMAGED PARTS, CUT / WELD, KNOCK & REALIGN.	New	3,600.00	500.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.	New	2,400.00	600.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA.	New	250.00	0.00
4	TO RNR REAR WINDSCREEN.	New	400.00	0.00
5	TO RNR REAR BOOT MECHANISM.	New	400.00	40.00
6	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS.	New	400.00	60.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	New	150.00	40.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS.	New	250.00	0.00
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION.	New	150.00	30.00
10	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	New	400.00	0.00
11	TO DO WATER LEAK TEST.	New	80.00	0.00
12	TO RNR FUEL TANK TO ASSIST WORK LOAD.	New	250.00	0.00
Gross Labour Cost (\$)			8,730.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >