

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19022592/HGA3Q2

**Date:** 02/06/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SKJ3882T	<b>Insured Vehicle No :</b>	SH8961G
Date of Loss: 18/12/2019	Nature of Claim:	TP Claim No: MCT19120460

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKJ3882T</b>	Engine No:	PY20462270
Make & Model:	MAZDA 6, 2.5 4-DOOR SEDAN 2.5L SP.6E (A)	Chassis No:	JM6GJ1031F0146680
Reg. Date:	23/12/2014 (Man. Year: 2014)	Odometer:	95644 km
Colour:	Blue		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,678.10	4,999.88	5,678.22	53.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,130.00	1,570.00	58.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,378.10</b>	<b>6,129.88</b>	<b>7,248.22</b>	<b>54.18</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,900.00</b>		
(S\$)	13,378.10	4,900.00	8,478.10	63.37
<b>+ GST 7.00/7.00% (S\$)</b>	936.47	343.00	593.47	63.37
<b>Nett Amount (S\$)</b>	<b>14,314.57</b>	<b>5,243.00</b>	<b>9,071.57</b>	<b>63.37</b>
<b>+ Car Rental (6.0 x S\$120.00/day) (S\$)</b>		720.00		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>Nett Liability (S\$)</b>		<b>5,999.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,900.00</b>		

#### INSPECTION

Date of Assignment:	23/12/2019	
Date Inspected:	23/12/2019 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** LEE HOCK ANN

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2020)
<b>Parts:</b> 143	MAZDA 6 2.5 4-DOOR SEDAN 2.5L SP.6E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKJ3882T)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	1,496.70 F	*1,211.90 FL
2	1		*FRONT BUMPER RETAINER RH	Serviceable	112.30 F	*- FL
3	1		*FRONT BUMPER RETAINER LH	Crumpled	112.30 F	*87.30 FL
4	1		*FRONT BUMPER SPONGE	Serviceable	158.70 F	*- FL
5	2		*FRONT BUMPER PARKING SENSOR	Serviceable	500.00 F	*- FL
6	1		*FOG LAMP LH	Cracked	327.60 F	*327.60 FL
7	1		*FOG LAMP GARNISH LH	Cracked	105.60 F	*105.60 FL
8	1		*FRONT BUMPER UNDER COVER	Serviceable	182.30 F	*- FL
9	1		*HEAD LAMP LH	Scratched	1,570.80 F	*1,250.70 FL
10	1		*FRONT FENDER LH	Bent	1,155.70 F	*580.80 FL
11	1		*FRONT FENDER INNER SHIELD LH	Cracked	482.30 F	*232.80 FL
12	1		*FRONT WHEEL RIM LH	Scratched	1,750.00 F	*1,277.20 FL
13	1		*FRONT ABSORBER LH	Crumpled	582.50 F	*471.90 FL
14	1		*FRONT ABSORBER TOP MOUNTING LH	Serviceable	238.60 F	*- FL
15	1		*FRONT KNUCKLE ARM LH	Crumpled	695.30 F	*400.30 FL
16	1		*FRONT KNUCKLE BEARING LH	Crumpled	235.00 F	*235.00 FL
17	1		*FRONT LOWER ARM LH	Serviceable	572.40 F	*- FL
18	1		*225/55/17 MICHELIN TYRE LH	Not Necessary	250.00 FS	*- FS
19	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
20	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	50.00 FS	*25.00 FS
21	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,678.10</b>	<b>6,236.10</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	1,236.22
<b>Total Parts (\$\$)</b>	<b>10,678.10</b>	<b>4,999.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO R&R FRONT BUMPER PARKING SENSOR	New	100.00	20.00
2	TO CONDUCT HEAD LAMP FOCUS	New	100.00	20.00
3	TO CHECK WIRING AND LIGHTING SYSTEM	New	80.00	30.00
4	TO SUPPLY UNDER COATING /PUTTY ON PARTS REPLACED	New	80.00	0.00
5	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	60.00	0.00
6	TO CONDUCT ALL WHEEL ALIGNMENT BEFORE AND AFTER	New	180.00	60.00
7	TO R&R FRONT LH WHEEL RIM, TYRE AND BALANCING	New	50.00	0.00
8	TO R&R FRONT LH UNDERCARRIAGE DAMAGED PARTS }	New	350.00	150.00
9	TO PRESS FRONT LH KNUCKLE BEARING ASSY }	New	100.00	0.00
10	TO REPAIR ,REPLACE AND REALIGN DAMAGED AREAS	New	800.00	450.00
11	TO SPRAY PAINTING ON AFFECTED AREAS	New	800.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,700.00</b>	<b>1,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >