

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022606/FKA3Q2

Date: 13/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800043104

Claimant
Vehicle No : SHC8556A **Insured Vehicle No :** SGY2954U

Date of Loss: 20/12/2019 Nature of Claim: TP Claim No: 5624688553SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8556A	Engine No:	2ZRS060469
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU603563003
Reg. Date:	26/07/2017 (Man. Year: 2017)	Odometer:	262821 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 7 mm	Rear Left Side:	Davanti 7 mm
Front Right Side:	Davanti 7 mm	Rear Right Side:	Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,670.77	3,158.82	511.95	13.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,850.00	310.00	14.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,830.77	5,008.82	821.95	14.10
+ GST 7.00/7.00% (\$\$)	408.15	350.62	57.53	14.10
Nett Amount (\$\$)	6,238.92	5,359.44	879.48	14.10
+ Loss of Use (7.0 x S\$50.00/day) (\$\$)		350.00		
+ Car Rental (7.0 x S\$125.40/day) (\$\$)		877.80		
		6,587.24		
Liabile Amount (50.00%) (\$\$)		3,293.62		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		3,301.11		
Global Sum Settlement (\$\$)		3,250.00		

INSPECTION

Date of Assignment: 23/12/2019

Date Inspected: 24/12/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	458.60 FL	*458.60 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*TAIL LAMP ASSY (LOWER) (LH)	Not Necessary	548.40 FL	*- FL
4	1		*REAR FENDER ,RH	Buckled	836.70 FL	*836.70 FL
5	1		*REAR FENDER SHIELD (RH)	Not Necessary	134.20 FL	*- FL
6	1		*REAR TYRE RIM (RH)	Scratched	1,555.00 FL	*1,555.00 FL
7	1		*REAR DOOR -RH	Buckled	1,232.80 FL	*1,232.80 FL
8	1		*RIGHT ROCKER PANEL (NPA)	Repair	0.00 FL	*- FL
9	1		*REAR DOOR COMFORT & APPS STICKER	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,867.70	4,185.10
- List Item Discount on L Items 25.00/25.00% (S\$)	1,196.93	1,026.28
Total Parts (S\$)	3,670.77	3,158.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	850.00	800.00
2	SPRAY PAINTING CHARGE	New	700.00	700.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	50.00
5	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
6	REMOVE /REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
7	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
8	REAR WHEEL ALIGNMENT	New	80.00	0.00
9	TRANSFER OF DOOR	New	80.00	80.00
Gross Labour Cost (\$\$)			2,160.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >