Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022609/FKA3Q2

Date: 09/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SHC1926L Insured Vehicle No: SKR9591B

Date of Loss: 22/12/2019 Nature of Claim: TP Claim No: 7857686472SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC1926L

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2G16759

Reg. Date: 20/12/2019 (Man. Year: 2019) Chassis No: JTDKB3FU403090492

Colour: Blue Odometer: 277 km

Engine Capacity: 1798 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,054.80	64.87	3,989.93	98.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	740.00	510.00	40.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,304.80	804.87	4,499.93	84.83
+ GST 7.00/7.00% (S\$)	371.34	56.34	315.00	84.83
Nett Amount (S\$)	5,676.14	861.21	4,814.93	84.83
+ Loss of Use (5.0) x S\$50.00/day) (S\$)	250.00		
+ Car Rental (5.0	x S\$126.47/day) (S\$)	632.35		
+1	Doc/Search Fee (S\$)	7.49		
	Nett Liability (S\$)	1,751.05		
Global	Sum Settlement (S\$)	1,751.00		

INSPECTION

Date of Assignment: 23/12/2019

Date Inspected: 24/12/2019 Inspected At: ComfortDelGro Engineering Pte Ltd

(Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: PARASURAM SHANMUGAM Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	490.50 FL	*- FL
2	10		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER-RH	Not Necessary	82.30 FL	*- FL
4	1		*FRONT BUMPER BRACKET-RH	Not Necessary	29.60 FL	*- FL
5	1		*SUPPORT FRONT BUMPER -RH	Not Necessary	81.70 FL	*- FL
6	1		*HEADLAMP-RH	Not Necessary	3,455.00 FL	*- FL
7	1		*HEADLAMP PANEL-RH	Not Necessary	213.50 FL	*- FL
8	1		*FRONT FENDER-RH	Repair	945.30 FL	*- FL
9	1		*FRONT FENDER HYBRID EMBLEM-RH	Necessary	86.50 FL	*86.50 FL
F=Fra	ınchise	part. L=ListIt	emDisc.	Sub Total (S\$)	5,406.40	86.50
			- List Item Discount on L Items	s 25.00/25.00% (S\$)	1,351.60	21.63
				Total Parts (S\$)	4,054.80	64.87
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	650.00	480.00
2	SPRAY PAINTING CHARGE	New	500.00	200.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	30.00
		Gross Labour Cost (S\$)	1,250.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >