

22/02/2012

ASS. REC. BY:

REF:

08/SPF19022610/Gs d3er

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Penny HE

of

SPF

Date/Time: 23/12/11 @ 3.50pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QX 773A

Insured:

at Workshop m/s

Indeco

Tel:

9787 7084

of

39 Deft Lane 12

Policy No:

Claim No:

MHASPF03 00000113

Sum Insured:

Excess:

TBA

Make of Veh:

(Client's Record)

D.O.A.

CA (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

8.46am @ 24/12/11

Person Contacted:

Mike

Vehicle IN/OUT

Date/Time

Action/Instruction

Johnnie (✓)

24/12/11 -

Mike said will call after Christmas due to work close. so call back on 26/12/2011.

QX 773A - NA / INC 12014418 / el

JOA: 24/12/2012

31/12/11

@ 12:05 pm went to Penny via email.

ASS. REC. BY:

Cul

REF:

SPF

ASSIGNMENT

11 MAR 2011

From:

Date:

30/12/10

Veh No:

QXT73A

Yr Regn:

-

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

QX773A

at Workshop m/s

Indeco

of

39 Defu bene 12

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh:

2pm - 4pm

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / (REV) REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

police car 1.6

Make:

Hyundai Avante

C.C

1591

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

118009

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMH DU 41 BMAU 033664

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

30-12-19

Survey held at

w/s

3:40pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S RA, O/S RA

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/12

Finalized 28 Hrs with Anson

RECEIVED 15 JAN 2020

Date/Time, File Pass to?

15/01/20

1)

Type

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B. / C

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp

(\$

Interview

(\$

Tech. Insp

(\$

Weekend

(\$

Survey Fee:

180

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

180

Shirley Hiew (LKK Auto)

From: Perry HE (HTX) <Perry_HE@htx.gov.sg>
Sent: Tuesday, 14 January 2020 3:30 pm
To: Shirley Hiew (LKK Auto)
Cc: Kim Pang CHAY (HTX); Kwee Huat TAN (HTX); SUR
Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX773A

Hi Shirley,

Ok, pls submit softcopies will do.

Perry He Junyun

Contract Management Engineer (Land Systems – Vehicles)
Capability Sustainment
Home Team Science & Technology Agency (Forward Deployed to SPF)
DID: (65) 6478 4869 | HP: (65) 9191 5725



eXponentially
impacting
Singapore's
safety and security_



Home Team Science & Technology Agency W htx.gov.sg FB fb.com/HTXSG IG Instagram.com/htxsg

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 14 January 2020 3:11 PM
To: Perry HE (HTX) <Perry_HE@htx.gov.sg>
Cc: Kim Pang CHAY (HTX) <CHAY_Kim_Pang@htx.gov.sg>; Kwee Huat TAN (HTX) <TAN_Kwee_Huat@htx.gov.sg>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX773A

Dear Perry,

Please advise whether can we submit our report of QX 773A accordingly.

"Wishing you a Happy and Prosperous Lunar New Year"



Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 31 December 2019 12:05 pm
To: Perry HE (HTX)
Cc: Kim Pang CHAY (HTX); Kwee Huat TAN (HTX); SUR
Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX773A
Attachments: LKK SURVEYOR PHOTO.pdf; QX 773A.xls

Dear Perry,

Please refer attached.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (HTX) [mailto:Perry_HE@htx.gov.sg]
Sent: Monday, 23 December 2019 3:50 PM
To: assignments <assignments@lkkauto.com>
Cc: Kim Pang CHAY (HTX) <CHAY_Kim_Pang@htx.gov.sg>; Kwee Huat TAN (HTX) <TAN_Kwee_Huat@htx.gov.sg>; 'Denise Tay (LKKAuto)' <denisetay@lkkauto.com>
Subject: Appraisal Services for SPF vehicle at INDECO - QX773A

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO, with new contractual rate.

Ref: MHASPF0300000113

Pls also advise whether this vehicle is structurally safe to repair.

QX773A

Parts:

- 1.1 FRT BUMPER
- 1.2 FRT BUMPER RETAINER LH
- 1.3 FRT BUMPER RETAINER RH
- 1.4 FRT BUMPER LOWER GRILLE

Nivitha (LKK Auto)

From: Perry HE (HTX) <Perry_HE@htx.gov.sg>
Sent: Monday, 23 December 2019 3:50 PM
To: assignments
Cc: Kim Pang CHAY (HTX); Kwee Huat TAN (HTX); 'Denise Tay (LKKAuto)'
Subject: Appraisal Services for SPF vehicle at INDECO - QX773A

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO, with new contractual rate.

Ref: MHASPF0300000113

Pls also advise whether this vehicle is structurally safe to repair.

QX773A

Parts:

- 1.1 FRT BUMPER
- 1.2 FRT BUMPER RETAINER LH
- 1.3 FRT BUMPER RETAINER RH
- 1.4 FRT BUMPER LOWER GRILLE
- 1.5 FRT BUMPER LOWER LIP
- 1.6 FRT BUMPER CLIP
- 1.7 FOGLAMP COVER LH
- 1.8 LHF FENDER
- 1.9 LHF FENDER INNER SHIELD
- 1.10 LHF FENDER INNER SHILED CLIP
- 1.11 LHF SPORT RIM 15"
- 1.12 LHF S/SBSORBER
- 1.13 LHF LOWER ARM
- 1.14 LHF KNUCKLE ARM
- 1.15 LHF WHEEL HUB
- 1.16 LHF WHEEL BEARING
- 1.17 LHF ANTI ROLL BAR LINK
- 1.18 ANTI ROLL BAR
- 1.19 LHF TIE ROD
- 1.20 LHF TIE ROD END
- 1.21 LHF LOWER ARM BALL JOINT
- 1.22 STEERING RACK & PINON
- 1.23 ENGINE CROSS MEMBER
- 1.24 RHF TYRE 185/65/15 SOR 5B CAT A
- 1.25 LHF TYRE 185/65/15 SOR 5B CAT A
- 1.26 RHF SPORT RIM 15" WITH 1.11
- 1.27 ENGINE OIL SUMP
- 1.28 ENGINE OIL SUMP GASKET
- 1.29 HEADLAMP LH
- 1.30 ENGINE UNDER COVER ASSY
- 1.31 RHF S/SBSORBER
- 1.32 RHF LOWER ARM
- 1.33 RHF KNUCKLE ARM
- 1.34 RHF WHEEL HUB
- 1.35 RHF WHEEL BEARING

9001 1683 ② *ASAP*

- 1.36 RHF ANTI ROLL BAR LINK
- 1.37 RHF TIE ROD
- 1.38 RHF TIE ROD END
- 1.39 RHF LOWER ARM BALL JOINT

Labour:

Description	Hour
TO REPLACE AND RESPRAY FRT BUMPER	5
TO REPLACE AND RESPRAY LHF FENDER	4
TO REPAIR AAND RESPRAY LHF DOOR	5
TO REPAIR AND RESPRAY LH ROCKER PANEL	2
TO REPLACE FRT UNDER CARRIAGE PARTS	4
TO PERFORM 4 WHEEL ALIGNMENT	1
TO REPAIR AND RESPRAY DAMAGE AREA AT UNDER CHASSIS	6
TO REPLACE ENGINE OIL SUMP	1

Thank you.

Perry He Junyun

Contract Management Engineer

Capability Sustainment

Home Team Science & Technology (Forward Deployment to SPF)

DID: (65) 6478 4869 | HP: (65) 9191 5725




eXponentially
impacting
Singapore's
safety and security_



Home Team Science & Technology Agency W htx.gov.sg FB fb.com/HTXSG IG Instagram.com/htx_sg

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

Reference No.
MHA/SPF/2019/12-0005 1100039726





LAR Auto Consultants hence notify the Registrar of the following: 1. The name of the company to be liquidated	
Remarks:	SUBJECT TO PARTS A



ACCIDENT/DAMAGE REPAIR AND AD HOC WORKS REQUEST FORM

ILMS Notification No	1100039726		
Vehicle No	QX773A	Division/Unit	A/MB NPC
Vehicle Type (e.g. FRC, minibus)	FRC	Date	29/11/2019
Vehicle Make & Model	Hyundai Avante	Mileage (km)	

Description	Pls tick	Police Report No & Date of Accident (if applicable)
NP168 (Accident involve 3 rd Party)		
NP168 (Accident do not involve 3 rd Party)	✓	T/20191129/2212
NP299 Discovered Damage		
NP299 Vandalism		
Ad hoc, pls specify		

Description of affected area/required works (e.g. dented, cracked, grazed etc)	
Front Left Bumper Damaged, Front Right Tyre Burst.	
Pls mark affected area with	
	
	
Rank/Name: SSS M. Haberbulla A0 MB NPC	Signature: 

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRT BUMPER	1	DISTORTED	\$ 114.00	\$ 114.00	
1.2	FRT BUMPER RETAINER LH	1	DENTED	\$ 21.60	\$ 21.60	
1.3	FRT BUMPER RETAINER RH	1	NOT NECESSARY	\$ 21.60		
1.4	FRT BUMPER LOWER GRILLE	1	DENTED	\$ 36.00	\$ 36.00	
1.5	FRT BUMPER LOWER LIP	1	DISTORTED	\$ 30.00	\$ 30.00	
1.6	FRT BUMPER CLIP	10	NECESSARY	\$ 18.00	\$ 180.00	
1.7	FOGLAMP COVER LH	1	CUT	\$ 30.00	\$ 30.00	
1.8	LHF FENDER	1	BUCKLED	\$ 72.00	\$ 72.00	
1.9	LHF FENDER INNER SHIELD	1	DENTED	\$ 42.00	\$ 42.00	
1.10	LHF FENDER INNER SHIELD CLIP	6	NECESSARY	\$ 10.80	\$ 64.80	
1.11	LHF SPORT RIM 15"	1	CUT	\$ 636.00	\$ 636.00	
1.12	LHF S/SBSORBER	1	BENT	\$ 168.00	\$ 168.00	
1.13	LHF LOWER ARM	1	BENT	\$ 78.00	\$ 78.00	
1.14	LHF KNUCKLE ARM	1	BENT	\$ 186.00	\$ 186.00	
1.15	LHF WHEEL HUB	1	BENT	\$ 108.00	\$ 108.00	
1.16	LHF WHEEL BEARING	1	BENT	\$ 60.00	\$ 60.00	
1.17	LHF ANTI ROLL BAR LINK	1	BENT	\$ 24.00	\$ 24.00	
1.18	ANTI ROLL BAR	1	BENT	\$ 186.00	\$ 186.00	
1.19	LHF TIE ROD	1	BENT	\$ 55.20	\$ 55.20	
1.20	LHF TIE ROD END	1	BENT	\$ 54.00	\$ 54.00	
1.21	LHF LOWER ARM BALL JOINT	1	BENT	\$ 45.60	\$ 45.60	
1.22	STEERING RACK & PINION	1	BENT	\$ 546.00	\$ 546.00	
1.23	ENGINE CROSS MEMBER	1	BENT	\$ 1,140.00	\$ 1,140.00	
1.24	RHF TYRE 185/65/15 SOR 5B CAT A	1	CUT	\$ 112.71	\$ 112.71	
1.25	LHF TYRE 185/65/15 SOR 5B CAT A	1	CUT	\$ 112.71	\$ 112.71	

1.26	RHF SPORT RIM 15" WITH 1.11	1	CUT	\$	-	\$	-
1.27	ENGINE OIL SUMP	1	CUT	\$	42.00	\$	42.00
1.28	ENGINE OIL SUMP GASKET	1	NECESSARY	\$	50.40	\$	50.40
1.29	HEADLAMP LH	1	CUT	\$	216.00	\$	216.00
1.30	ENGINE UNDER COVER ASSY	1	DISTORTED	\$	42.00	\$	42.00
1.31	RHF S/SBSORBER	1	BENT	\$	168.00	\$	168.00
1.32	RHF LOWER ARM	1	BENT	\$	78.00	\$	78.00
1.33	RHF KNUCKLE ARM	1	BENT	\$	186.00	\$	186.00
1.34	RHF WHEEL HUB	1	BENT	\$	108.00	\$	108.00
1.35	RHF WHEEL BEARING	1	BENT	\$	60.00	\$	60.00
1.36	RHF ANTI ROLL BAR LINK	1	BENT	\$	24.00	\$	24.00
1.37	RHF TIE ROD	1	BENT	\$	55.20	\$	55.20
1.38	RHF TIE ROD END	1	BENT	\$	54.00	\$	54.00
1.39	RHF LOWER ARM BALL JOINT	1	BENT	\$	45.60	\$	45.60
LABOUR DESCRIPTION							
1	SCOPE OF REPAIRS						
1.1	TO REPLACE AND RESPRAY FRT BUMPER						5
1.2	TO REPLACE AND RESPRAY LHF FENDER						4
1.3	TO REPAIR AND RESPRAY LHF DOOR						5
1.4	TO REPAIR AND RESPRAY LH ROCKER PANEL						2
1.5	TO REPLACE FRT UNDER CARRIAGE PARTS						4
1.6	TO PERFORM 4 WHEEL ALIGNMENT						1
1.7	TO REPAIR AND RESPRAY DAMAGE AREA AT UNDER CHASSIS						6
1.8	TO REPLACE ENGINE OIL SUMP						1
COSTING				TOTAL PARTS COST			
				TOTAL MAN-HOUR			
						\$5,231.82	28

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF19022610/Gsd3e2

CONTRACT MANAGEMENT SECTION
 (SPORE POLICE FORCE)1 MOUNT PLEASANT
 ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE
 298333

Date : 04-02-2020



ATTN : PERRY HE

Code : SPF3

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	QX 773A
Policy No.		Coverage (\$)	0.00
Claim No.	MHASPF0300000113	Excess (\$)	0.00
Assign From	PERRY HE	Assign Date	23/12/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE 1.6	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KMH DU41BMAU033664	Colour	WHITE
Odometer	118009	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	FALKEN	5 mm
L/H Front Tyre	185/65 R15	FALKEN	5 mm
R/H Rear Tyre	185/65 R15	FALKEN	5 mm
L/H Rear Tyre	185/65 R15	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT, O/S FRONT AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date		Inspection Date	30/12/2019
Survey held at	INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139		

5a. Remarks

--



Registration No. QX 773A

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRT BUMPER	1	DISTORTED	\$ 114.00	\$ 114.00	
1.2	FRT BUMPER RETAINER LH	1	DEFORMED	\$ 21.60	\$ 21.60	
1.3	FRT BUMPER RETAINER RH	1	NOT NECESSARY	\$ 21.60		
1.4	FRT BUMPER LOWER GRILLE	1	DEFORMED	\$ 36.00	\$ 36.00	
1.5	FRT BUMPER LOWER LIP	1	DISTORTED	\$ 30.00	\$ 30.00	
1.6	FRT BUMPER CLIP	10	NECESSARY	\$ 18.00	\$ 180.00	
1.7	FOGLAMP COVER LH	1	CUT	\$ 30.00	\$ 30.00	
1.8	LHF FENDER	1	BUCKLED	\$ 72.00	\$ 72.00	
1.9	LHF FENDER INNER SHIELD	1	DEFORMED	\$ 42.00	\$ 42.00	
1.10	LHF FENDER INNER SHIELD CLIP	6	NECESSARY	\$ 10.80	\$ 64.80	
1.11	LHF SPORT RIM 15"	1	CUT	\$ 636.00	\$ 636.00	
1.12	LHF S/SBSORBER	1	BENT	\$ 168.00	\$ 168.00	
1.13	LHF LOWER ARM	1	BENT	\$ 78.00	\$ 78.00	
1.14	LHF KNUCKLE ARM	1	BENT	\$ 186.00	\$ 186.00	
1.15	LHF WHEEL HUB	1	BENT	\$ 108.00	\$ 108.00	
1.16	LHF WHEEL BEARING	1	BENT	\$ 60.00	\$ 60.00	
1.17	LHF ANTI ROLL BAR LINK	1	BENT	\$ 24.00	\$ 24.00	
1.18	ANTI ROLL BAR	1	BENT	\$ 186.00	\$ 186.00	
1.19	LHF TIE ROD	1	BENT	\$ 55.20	\$ 55.20	
1.20	LHF TIE ROD END	1	BENT	\$ 54.00	\$ 54.00	
1.21	LHF LOWER ARM BALL JOINT	1	BENT	\$ 45.60	\$ 45.60	
1.22	STEERING RACK & PINON	1	BENT	\$ 546.00	\$ 546.00	
1.23	ENGINE CROSS MEMBER	1	BENT	\$ 1,140.00	\$ 1,140.00	
1.24	RHF TYRE 185/65/15 SOR 5B CAT A	1	CUT	\$ 112.71	\$ 112.71	
1.25	LHF TYRE 185/65/15 SOR 5B CAT A	1	CUT	\$ 112.71	\$ 112.71	
1.26	RHF SPORT RIM 15" WITH 1.11	1	CUT	\$ -	\$ -	
1.27	ENGINE OIL SUMP	1	CUT	\$ 42.00	\$ 42.00	
1.28	ENGINE OIL SUMP GASKET	1	NECESSARY	\$ 50.40	\$ 50.40	

1.29	HEADLAMP LH	1	CUT	\$ 216.00	\$ 216.00	
1.30	ENGINE UNDER COVER ASSY	1	DISTORTED	\$ 42.00	\$ 42.00	
1.31	RHF S/SBSORBER	1	BENT	\$ 168.00	\$ 168.00	
1.32	RHF LOWER ARM	1	BENT	\$ 78.00	\$ 78.00	
1.33	RHF KNUCKLE ARM	1	BENT	\$ 186.00	\$ 186.00	
1.34	RHF WHEEL HUB	1	BENT	\$ 108.00	\$ 108.00	
1.35	RHF WHEEL BEARING	1	BENT	\$ 60.00	\$ 60.00	
1.36	RHF ANTI ROLL BAR LINK	1	BENT	\$ 24.00	\$ 24.00	
1.37	RHF TIE ROD	1	BENT	\$ 55.20	\$ 55.20	
1.38	RHF TIE ROD END	1	BENT	\$ 54.00	\$ 54.00	
1.39	RHF LOWER ARM BALL JOINT	1	BENT	\$ 45.60	\$ 45.60	
	LABOUR DESCRIPTION					
1	SCOPE OF REPAIRS					
1.1	TO REPLACE AND RESPRAY FRT BUMPER					5
1.2	TO REPLACE AND RESPRAY LHF FENDER					4
1.3	TO REPAIR AND RESPRAY LHF DOOR					5
1.4	TO REPAIR AND RESPRAY LH ROCKER PANEL					2
1.5	TO REPLACE FRT UNDER CARRIAGE PARTS					4
1.6	TO PERFORM 4 WHEEL ALIGNMENT					1
1.7	TO REPAIR AND RESPRAY DAMAGE AREA AT UNDER CHASSIS					6
1.8	TO REPLACE ENGINE OIL SUMP					1
COSTING		TOTAL PARTS COST			\$5,231.82	
		TOTAL MAN-HOUR				28

Registration No. QX 773A

Registration No. QX 773A

Vehicle Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.