

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19022647/EVD3E2

Date: 29/04/2020

REFERENCE

Insured/Claimant: PANG LU THING SHANE (FENG RUXIN SHANE)

Policy No:

Date of Loss: 23/12/2019

Nature of Claim: OD Claim No: 3788004045SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDR209Z**

Make & Model: AUDI Q5, 2.0 TFSI Quattro (A)

Engine No: DAX033166

Reg. Date: 25/08/2018 (Man. Year: 2018)

Chassis No: WAUZZZFVXJ2139439

Colour: Black

Odometer: 24857 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$179,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19

Rear Tyre Size: 235/55 R19

Front Left Side: Continental 5 mm

Rear Left Side: Continental 5 mm

Front Right Side: Continental 5 mm

Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,484.00	11,808.72	16,675.28	58.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,572.00	3,072.00	3,500.00	53.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,056.00	14,880.72	20,175.28	57.55
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	34,556.00	14,380.72	20,175.28	58.38
+ GST 7.00/7.00% (S\$)	2,418.92	1,006.65	1,412.27	58.38
Nett Amount (S\$)	36,974.92	15,387.37	21,587.55	58.38

INSPECTION

Date of Assignment: 26/12/2019

Date Inspected: 26/12/2019 Inspected At:

281 Alexandra Road

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	2,364.00 FS	*1,891.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	244.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	68.00 FS	*- FS
4	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	202.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	129.00 FS	*- FS
6	1		*FRONT BUMPER FRONT SPOILER	Not Necessary	685.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	431.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	156.00 FS	*- FS
9	1		*RADIATOR GRILLE	Broken	3,258.00 FS	*2,606.40 FS
10	1		*QUATTRO INSCRIPTION	Not Necessary	87.00 FS	*- FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Broken	222.00 FS	*177.20 FS
12	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	1,038.00 FS	*- FS
13	2		*FRONT BUMPER END CAP - LH / RH	Not Necessary	166.00 FS	*- FS
14	4		*LOCKING CLIP	Necessary	15.00 FS	*11.52 FS
15	1		*FRONT BUMPER CARRIER	Not Necessary	831.00 FS	*- FS
16	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	259.00 FS	*207.20 FS
17	1		*FOAM FILLER PIECE COVER	Not Necessary	116.00 FS	*- FS
18	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	68.00 FS	*- FS
19	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
20	1		*AIRCON STICKER	Not Necessary	18.00 FS	*- FS
21	1		*HORN - LH LOW TONE	Not Necessary	178.00 FS	*- FS
22	1		*HORN - RH HIGH TONE	Not Necessary	178.00 FS	*- FS
23	2		*FRONT PARKING AID SENSOR - INNER (RH)	Not Necessary	462.00 FS	*- FS
24	2		*FRONT PARKING AID SENSOR - OUTER (RH)	Not Necessary	462.00 FS	*- FS
25	4		*FRONT PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
26	2		*HEADLIGHT MOUNTING - LH / RH	Broken	214.00 FS	*171.20 FS
27	1		*LED HEADLIGHT - LH / RH	N/S Cut	14,454.00 FS	*5,781.60 FS
28	2		*LIFT CYLINDER - LH / RH	Not Necessary	256.00 FS	*- FS
29	1		*HEADLIGHT HOSE	Not Necessary	113.00 FS	*- FS
30	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,154.00 FS	*922.40 FS
31	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	43.00 FS	*- FS
32	1		*RADIATOR AIR GUIDE - CENTRE	Not Necessary	37.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	43.00 FS	*- FS
34	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	100.00 FS	*- FS
35	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	54.00 FS	*- FS
36	1		*EXTERNAL TEMPERATURE SENSOR BRACKET	Not Necessary	14.00 FS	*- FS
37	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
38	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **28,484.00** **11,808.72**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	750.00
3	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS	New	3,500.00	1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			6,572.00	3,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >