

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19022649/EYD3E2

Date: 01/06/2020

REFERENCE

Insured/Claimant:	HENET PTE LTD	Policy No:
Date of Loss:	21/12/2019	Nature of Claim: OD Claim No: 7978667284SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC9414K	
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Engine No: DAX033244
Reg. Date:	27/07/2018 (Man. Year: 2018)	Chassis No: WAUZZZFVXJ2141806
Colour:	Silver	Odometer: 14216 km
Engine Capacity:	1984 cc	
Market Value/New Car Price:	S\$178,000.00	
Sum Insured (\$\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,207.80	4,284.72	3,923.08	47.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,452.00	3,752.00	2,700.00	41.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,659.80	8,036.72	6,623.08	45.18
- Excess (\$\$)	1,000.00	1,000.00	0.00	0.00
(\$\$)	13,659.80	7,036.72	6,623.08	48.49
+ GST 7.00/7.00% (\$\$)	956.19	492.57	463.62	48.49
Nett Amount (\$\$)	14,615.99	7,529.29	7,086.70	48.49

INSPECTION

Date of Assignment:	26/12/2019	
Date Inspected:	26/12/2019	Inspected At: 281 ALEXANDRA ROAD
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	1,571.00 FS	*1,256.80 FS
2	1		*REAR BUMPER COVER	Broken	1,077.00 FS	*861.60 FS
3	1		*REAR BUMPER SPOILER	Broken	754.00 FS	*602.80 FS
4	1		*REAR BUMPER TOWING EYE COVER - LH	Crushed	43.00 FS	*34.00 FS
5	1		*REAR BUMPER TOWING EYE COVER - RH	Not Necessary	26.00 FS	*- FS
6	1		*REAR BUMPER CLOSING ELEMENT - LH	Not Necessary	86.00 FS	*- FS
7	1		*REAR BUMPER TRIM - LH	Not Necessary	213.00 FS	*- FS
8	1		*TAIL LIGHT - LH	Broken	627.00 FS	*501.60 FS
9	1		*BOOT LID CONTROL UNIT	Not Necessary	387.00 FS	*- FS
10	1		*REAR BUMPER CARRIER	Not Necessary	831.00 FS	*- FS
11	1		*REAR BUMPER HOLDING STRAP	Not Necessary	151.00 FS	*- FS
12	1		*REAR BUMPER FOAM FILLER PIECE - LH	Not Necessary	56.00 FS	*- FS
13	2		*REAR PARKING AID SENSOR	Not Necessary	462.00 FS	*- FS
14	4		*REAR PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
15	1		*SET REAR BUMPER WIRING	Not Necessary	453.00 FS	*- FS
16	2		*REAR WHEEL COVER - LH / RH	Necessary	974.00 FS	*779.20 FS
17	1		*SUNDRIES	Necessary	300.00 FS	*63.92 FS
18	1		*REAR BUMPER GUIDE SECTION - LH	Shorted	184.80 FS	*184.80 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **8,207.80** **4,284.72**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER, REAR BUMPER LOWER SPOILER AND BOTH REAR WHEEL ARCH TRIMS	New	2,700.00	1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
5	TO REPAIR END PANELLING	New	800.00	500.00
6	TO RESPRAY END PANELLING	New	1,200.00	550.00
Gross Labour Cost (S\$)			6,452.00	3,752.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >