

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III19022669/UPA3Q2

**Date:** 23/06/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0002033
<b>Claimant Vehicle No :</b>	SJN3956E	<b>Insured Vehicle No :</b>	GW2966X
Date of Loss:	24/12/2019	Nature of Claim:	TP
		Claim No:	MCV2020D0000087

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN3956E	Engine No:	R18A13801152
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	JHMRN68809S201211
Reg. Date:	13/02/2009 (Man. Year: 2008)	Odometer:	207999 km
Colour:	Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/50Z R17	Rear Tyre Size:	215/50Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,951.30	2,584.96	6,366.34	71.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,230.00	980.00	44.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,161.30</b>	<b>3,814.96</b>	<b>7,346.34</b>	<b>65.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,050.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,161.30</b>	<b>3,050.00</b>	<b>8,111.30</b>	<b>72.67</b>
<b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,452.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,450.00</b>		

### INSPECTION

Date of Assignment:	26/12/2019	
Date Inspected:	26/12/2019 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
<b>Parts:</b>	M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJN3956E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	788.50 F	*638.00 FL
2	1		*BONNET	Repair	1,028.20 F	*- FL
3	1		*FRONT BUMPER SIDE HOLDER N/S	Bent	66.50 F	*32.50 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	319.20 F	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	38.00 F	*38.00 FL
6	1		*FRONT BUMPER FOG LAMP N/S	Not Necessary	295.00 F	*- FL
7	1		*FRONT FENDER N/S	Badly Dented	815.10 F	*586.00 FL
8	1		*FRONT FENDER INNER SHIELD N/S	Torn	292.30 F	*188.20 FL
9	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	38.00 F	*38.00 FL
10	1		*FRONT FENDER INNER PANEL N/S	Repair	665.10 F	*- FL
11	1		*FRONT SHOCK ABSORBER N/S	Serviceable	588.20 F	*- FL
12	1		*FRONT LOWER ARM N/S	Serviceable	495.30 F	*- FL
13	1		*FRONT KNUCKLE ARM N/S	Bent	615.20 F	*495.20 FL
14	1		*FRONT KNUCKLE ARM BEARING N/S	Damaged	288.50 F	*215.30 FL
15	1		*FRONT DRIVE SHAFT N/S	Not Necessary	1,288.20 F	*- FL
16	1		*SET HEADLAMP STICKER N/S	Necessary	180.00 FS	*150.00 FS
17	1		*FRONT SPORT RIM N/S	Cracked / Bent	950.00 FS	*650.00 FS
18	1		*FRONT TYRE N/S	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,951.30</b>	<b>3,031.20</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	446.24
<b>Total Parts (\$\$)</b>	<b>8,951.30</b>	<b>2,584.96</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	30.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
4	TO DISMANTLE & REPLACING FRONT UNDER CARRIAGE	New	180.00	120.00
5	TO REFILL AIR CON GAS	New	120.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	680.00	400.00
7	TO PUTTY & SPRAY PAINTING	New	980.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,210.00</b>	<b>1,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >