88 7981.73

Date/Time:

55

SS

55

FINAL PAYMENT

Payee 2: (Strike if N.A.)

Payce 3: (Strike if N.A.)

Payce 1:

Global Sum S5:

Email

Lte

SH

CHUMNI MASTON WORK

Confirm with:

Name I:

Name 2

Name 3:

HE

## CHUNNI MOTOR WORK PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO: SHC 1810L

MAKE :

TEL: 6542 5119

India

DATE : 24.12.2019

DEL	: HYUNDAI IONIQ	FAX	: 6542 6039		maria	
Qty	Parts Description/ Labour	Type	Unit Price		Amount	
	Rear Bumper and wondy crack			S	459.40	1
	Rear Bumper Side Bracket (LH) HH			S	33.10	X
	Rear Bumper Cover Clips No.			S	22.00	-
	Rear Fender (LHH) Dents			S	1,768.30	-
	Rear Fender Inner Lining (LH)			S	73.60	X
	Rear Windscreen Moulding			s	28.20	1
	Rear Door (LH) Dank			S	1,789.90	-
	Rear Door Gear / Regulator (LH) Hall			S	229.90	×
	Rear Door Motor (LH)			S	160.50	X
	Rear Door Protector(LH) Nec			5	116.20	i
	Rocker Panel Outer Garnish (LH) ( - 1 143			S	290.00	
				S		X
	Rear Tyre Rim (LH)				1,124.20	1
	Rear Wheel Hup-Cap (LH) C			S	134.10	7
	Rear Wheelbearing ING & Hub 2 D			S	454.00	75
	Rear Trailing Arm (LHH)			S	121.00	14.
	Rear Assist (LH) 2 destated			S	92.80	-
	Rear Shock Absorber (LH) Z destroyed			S	230.50	
	Rear Shock Absorber Mounting (LH) Nu			S	61.40	X
	Rear Crossmember Hy		2	S	756.40	X
	Stabilizer Bar Mai		(398-60	S	224.00	X
	Stabilizer Link +1		6398-60	S	92.10	X
	Rear Upper Arm (LH) Z distant		5114.88	S	112.20	2
	Rear Lower Arm (LH)		511000	S	393.10	2
	Rear Knuckle Arm (LH) ₹ distant			S	386.90	3
	SUB TOTAL			s	9,153.80	1
	LESS 20%			S	1,830.76	
	DISCOUNTED TOTAL			S	7,323.04	1
	Rear Bumper Rubber Mat N			s	50.00	Nett
	Rear Windscreen Sealant Hec			S	46.00	
	Rear Door Comfortdelgro & Apps Sticker (LH) Nec		17600.	S	80.00	100
	Front Door Coloured Comfort Logo (LH)			S	75.00	10000
	Rear Tyre (LH) NH			S	216.00	
	The Late Act			_	210.00	
				S	467.00	
				1		
						ı

SHC 1810L

Ore	Parts Description/ Labour	Type	Unit Price		Amount	1
Qty	Parts Description/ Labour	Туре	Om Free	H	4mount	1
	Labour Charge					
	Panel Beating			s	1,000:00	600
	Spray Painting Charge			S	1,250.00	
	Wiring Charge			S	50.00	
	Tuff Kote			s	100.00	100
	Remove/Refix Cushion & Upholstery Rear			s	150.00	- 1
	Remove/Refix Reverse Sensor			S		
	Remove/Refix Fuel Tank			S	120.00 150.00	7
				s	60.00	
	Repair Exhaust Pipe Transfer of Door			5	-120.00	
			1730-00	5	200.00	
	Remove/Refix Undercarriage (RR)			S		35000
	Rear Wheel Alignment				120.00	001
	Re-set Rear ABS System			S	200.00	11.
	Re-set Rear Power Window System			S	200.00	118
	Diagnostic & Resetting To Erase Fault Code			S	480.00	2
	TOTAL LABOUR			s	4,200.00	
	ESTIMATE TOTAL			S	11,990.04	
	0.1.1					1
	26/2/249 C 1600m NA ANTHI 2/5mc 6 ays.		7024.88 4 S 5660 -			
	Na Avtud		415 56001-			
	,		12 2000			
	I Smil 6 dass.					1
	e '					1
	( Man )					
	JKK AND					
	0					1
	$\rightarrow$					
	Lx	CAuto Cons	ultants hence notify		٦ .	Į
	the	Repairer of	the following:			1
	a Te	resurvey belo	relafter spray painting ged part(s) during resurvey			}
			subject to confirmation		1	1
	- n	and party surve	y is on a "Without Prejudice" b	esis.		
			cation(s) is allowed		1	
	1.5	spiementary i subject to fina	em(s) must be resurveyed ges approval from Insurance Com	any.	1	
		nowledged by sature:	reparer			
	Del			201		
				1	_	
	This is an initial estimate based on a visual inspection of th	-	Transfer out to the second	-	The state of	1

NAME ADDRESS

Home Tel.:

VIN:

Registration: SHC 1810 L

Technician:

Mileage:

206747

Time Printed 26.12.19 4:36 PM

#### HYUNDAI IONIQ

Front: Left

Actual	BEFORE	Specified Range
-0°04"		-3°00' 3°00'
5"59"		-0°19' 5°41'
-0"42"		-1°30' 1°30'
20°48'		
20°44'		

Camber Caster Toe SAI Included Angle Turning Angle Diff.

Actual	BEFORE	Specified Range
-0°40°		-3°00' 3°00'
6"25"		-0°19' 5°41'
0°31"		-1°30' 1°30'
15°33'		
14°52'		

#### Front

Cross Camber Cross Caster Cross SAI Total Toe Cross Turn Diff.

Actual	BEFORE	Specified Range
0°36'		-3°00' 3°00'
-0"25"		-3°00, 3°00,
5"15"		-3°00' 3°00'
-0°12'		-3°00' 3°00'

Rear: Left

BEFORE Specified Range Actual -1°30' 1°59' -3°30' 2°30' -1°30' 1°30'

Camber Toe

	Right	
Actual	BEFORE	Specified Range -3°30' 2°30'
-0°071		-1°30' 1°30'

#### Rear

Cross Camber Total Toe Thrust Angle

Actual	BEFORE	Specified Range
-0°16'		-3°00, 3°00,
1°53'		-3°00' 3°00'
1:03'		-3°00, 3°00,

## Nivitha (LKK Auto)

From:

Motor Claim - III <motorclaim@iii.com.sg>

Sent:

Thursday, 26 December 2019 11:35 AM

To:

'sur@lkkauto.com'; Nivitha (LKK Auto)

Cc:

Subject:

Chunni Motor, Sundari Nagarajan - III

Attachments:

RE: Accident involving veh no: SHC 1810L & GBH 643D (Pan Pac) on 23.12.19

24122019144405.pdf

12:32pm006/12/19 12: Lynn V: IN S:Bryen

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SHC1810L and let us have your report urgently.

This claim will be handled by Ms Sundari.

\*Kindly upload this survey request email to merimen.

\*We have started using audatex since 1st Dec 2019. Please do adjustments through Audatex and upload the report onto Merimen.

Thank You.

Warmest regards,

Stanley Lai

Motor & Work Injury Claims Department India International Insurance Pte Ltd

64 Cecil Street, IOB Building, Level 5 Singapore 049711 Tel: 6347 6100 Ext 206 Fax: 6224 4174

S&P 'A-' rated Company



From: Chunni Motor [mailto:chunnimotor@gmail.com]

Sent: Thursday, 26 December, 2019 8:28 AM To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: Accident involving veh no: SHC 1810L & GBH 643D (Pan Pac) on 23.12.19

Dear Sir,

We appoint LKK Auto Consultants.

Thank you

Regards.

Chunni Motor Work P/L

On Tue, Dec 24, 2019 at 3:26 PM Motor Claim - III < motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We proprose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

We started using audatex since 1st dec 2019. Please submit your estimate/quotation throught Audatex so that our surveyors can make the adjustments according.

Best Regards,

**Gabriel Wee** 



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: Chunni Motor [mailto:chunnimotor@gmail.com]

Sent: 24 December, 2019 3:04 PM

To: Motor Claim - III < motorclaim@iii.com.sg>
Subject: Accident involving veh no: SHC 1810L & GBH 643D on 23.12.19

Dear Sir/Mdm.

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor,#01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

#### DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

#### DISCLAIMER:

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination

of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

## Print Received Message

This mail is associated with:

\*SHC1810L (MFL2020D0000008) [GBH643D] COMFORT TRANSPORTATION PTE LTD Dec 23 2019 8:00PM

Chunni Motor Work Pte Ltd

From

India International Insurance Pte Ltd (HQ) (III\_SG), sent on 06/03/2020 09:09 AM.

To

LKK\_HQ

Subject

Alert - Adj Mandate Approved (S\$7981.73) - SHC1810L - Claim Handler: Sundari Nagarajan

Approved:7981.73:Request TP WS to issue Tax invoice for Repairs in III's favour

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj S	Submitted	Ins Auth'ed	Stat	-	
Main	02 Jan 2020 Edit Reg		26 Dec 2019 00:00 Edit Adj Rpt	\$\$5,60 Edit E	0.00 stimates	1000	,600.00 nw Rpt		Rep	Pending for Survey Report Cancel Case	
	Main	∏ R	eference		Claim Det	ails		Document		1_	Show All
CLAIM SL	BFOLDER D	ETAILS					[Created	by adjuster]			
Insured:	PAN PAC	IFIC VAN & TRU	CK LEASING PTE L	TD, 10:-	5						
Main Claimant:	COMFOR	T TRANSPORTAT	TON PTE LTD, Co	Reg. No.	1993038	21R					
Vehicle Re	SHC181	SHC1810L Date of Loss: 23/12/2019 20:00 - :59 [15 Months and 10 Days From LTA Reg Date (Man Yr)]									
Claim Type	TP / MF	TP / MFL2020D0000008				over	D19MFL000	9MFL0005549			
Vehicle Re- No. (Insured):	GBH643D   Citigment)   D-18088936MFSH										
	Chunni h	lakas Mask Dta I	td (HQ) Bik 10 Ang	Ma Via Inc	Excess:	t 75	#07-10 AM	K Autopoint 5680	d7 Ann	Mo Wio - T	al: 6543
Repairer:	7162	lotor Work Pte L	to (NQ) bik 10 Ang	NO KIO III	smerses s.e.	1.40×	+07-13 Mill	A Autopoint, 3000	or only	THE PART OF	B11 SHAPTE
Handling Insurer:	India Int	ernational Insur	rance Pte Ltd (HQ)	- Tel: 634	76100	Hand	led by <b>Sund</b>	ari Nagarajan -	6347 60	71]	
Claimant's Insurer:			e Ltd (HQ) - Tel: 6								
Adjuster:	LKK Auto	Consultants Pte	e Ltd (HQ) - Tel: 62	56-3561	. [Handled	by B	RYAN TANI	[Final Rpt	due 0	7/01/202	[0]
ASSOCIA	TED MAIL RE	CEIVED						Vie	IIA W	Compose	Case Ma
• 111_SG		Alert - Adj Man	date Approved (S\$ date Approved (S\$			- Clair	m Handler:	Sundari Nagara		- 1	Consultation of the Consul
Due Dat			k Group Subjec	ct Han	dier A	_	view All	Completed On	Create Ne	eated On	Complet

#### **Claim Documents**

#### \*SHC1810L (MFL2020D0000008) [GBH643D] TP

# COMFORT TRANSPORTATION PTE LTD Dec 23 2019 8:00PM [PAN PACIFIC VAN & TRUCK LEASING PTE LTD] Chunni Motor Work Pte Ltd

Pho	otos/Images		3 per page   ✓	8
¥α	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnall	-
	18/01/20 14:32	Rear View Right	1 Load JPG	2
2	18/01/20 14:32	Rear View Left	■ Load JPG	82
1	18/01/20 14:33	General View	■ Load JPG	82
	18/01/20 14:33	General View	■ Load 3PG	R
5	18/01/20 14:33	General View	■ Load JPG	R
5	18/01/20 14:33	General View	■ Load JPG	2
,	18/01/20 14:33	General View	O Load JPG	2
3	18/01/20 14:33	General View	■ Load JPG	1
9	18/01/20 14:33	General View	■ Load JPG	W
10	18/01/20 14:33	General View	■ Load JPG	V
11	18/01/20 14:33	General View	O Load JPG	R
12	18/01/20 14:33	General View	Load JPG	R
13	18/01/20 14:33	General View	O Load JPG	12
14	18/01/20 14:33	General View	O Load 3PG	E
15	18/01/20 14:33	General View	■ Load JPG	B
16	18/01/20 14:33	General View	O Load JPG	R
17	18/01/20 14:33	General View	Load JPG	2
18	18/01/20 14:33	General View	■ Load JPG	8
19	18/01/20 14:33	General View	O Load JPG	2
	727232246122	General View	O Load JPG	2
20	18/01/20 14:33	General View	■ Load JPG	2
21	18/01/20 14:33	General View	O Load JPG	2
22	18/01/20 14:33		■ Load JPG	E
23	18/01/20 14:33	General View	■ Load JPG	E
24	18/01/20 14:33	General View		- E
25	18/01/20 14:33	General View	O Load JPG	B
26	18/01/20 14:33	General View	O Load JPG	-
27	18/01/20 14:33	General View	E Load JPG	2
28	18/01/20 14:33	General View	O Load JPG	E
29	18/01/20 14:33	General View	Lead JPG	2
30	18/01/20 14:33	General View	■ Load JPG	2
31	18/01/20 14:33	General View	■ Load JPG	2
32	18/01/20 14:33	General View	■ Load JPG	2
13	18/01/20 14:33	General View	0 Load JPG	1 12
34	18/01/20 14:33	General View	1 Load JPG	1
35	18/01/20 14:33	General View	■ Load JPG	2
36	18/01/20 14:33	General View	Load JPG	2
37	18/01/20 14:33	General View	1 Load JPG	2
38	18/01/20 14:33	General View	Load 3PG	2
19	18/01/20 14:33	General View	■ Load JPG	N
40	18/01/20 14:33	General View	1 Load JPG	V
41	18/01/20 14:33	General View	■ Load JPG	E
42	18/01/20 14:33	General View	1 Load JPG	8
43	18/01/20 14:33	General View	■ Load JPG	E

	tos/Images	LVV Auto Consultante Des Ltd (MO)	3 per page	all Pri
No	Relabel/Reorder 18/01/20 14:33	LKK Auto Consultants Pte Ltd (HQ) General View	■ Load JPC	the same of the same of
	- Department of the same	General View	■ Load JPC	- 000
5	18/01/20 14:33	Principle Control Cont	O Loed 3PG	
6	18/01/20 14:33	General View	O Load JP(	
7	18/01/20 14:33	General View		-
8	18/01/20 14:33	General View	Load 3Pi	-
9	18/01/20 14:33	General View	Load 3Pi	
0	18/01/20 14:33	General View	1 Load JP	
1	18/01/20 14:33	General View	1 Load JP	_
2	18/01/20 14:33	General View	■ Load 3P	G 💆
3	18/01/20 14:33	General View	■ Load JP	G E
4	18/01/20 14:33	General View	€ Load JP	G F
5	18/01/20 14:33	General View	■ Load JP	G 5
56	18/01/20 14:33	General View	■ Load JP	G F
7	18/01/20 14:33	General View	O Load JP	
			O Load 3P	444
8	18/01/20 14:33	General View		_
9	18/01/20 14:33	General View	6 Load JP	-
0	18/01/20 14:33	General View	1 Load JP	-
1	18/01/20 14:33	General View	1 Load JP	-
12	18/01/20 14:33	General View	■ Load JP	- 10
3	18/01/20 14:33	General View	E Load JP	G E
4	18/01/20 14:33	General View	■ Load JP	G E
5	18/01/20 14:34	Odometer Reading	■ Load 3P	G B
6	18/01/20 14:34	Chassis Number	■ Load JP	
7	18/01/20 14:34	Reinspection Photo	Load JP	
8	18/01/20 14:34	Reinspection Photo	O Load JP	- 1
-	TOTAL CONTRACTOR	Control Contro		-
9	18/01/20 14:34	Reinspection Photo		-
0	18/01/20 14:34	Reinspection Photo	1 Load JP	- 100
1	18/01/20 14:34	Reinspection Photo	Load JP	_
2	18/01/20 14:34	Reinspection Photo	E Load JP	
3	18/01/20 14:34	Reinspection Photo	1 Load JP	G E
4	18/01/20 14:34	Reinspection Photo	■ Load JP	G E
5	18/01/20 14:34	Reinspection Photo	■ Load 3P	G S
16	18/01/20 14:34	Reinspection Photo	1 Load JP	G E
7	18/01/20 14:34	Reinspection Photo	■ Load JP	G E
78	18/01/20 14:34	Reinspection Photo	■ Load JP	-
19	18/01/20 14:34	Reinspection Photo	■ Load JP	-
10	18/01/20 14:34	Reinspection Photo	■ Load 3P	-
_				
11	18/01/20 14:34	Reinspection Photo	1 Load JP	-
2	18/01/20 14:34	Reinspection Photo	1 Load JP	_
3	18/01/20 14:34	Reinspection Photo	1 Load JP	_
14	18/01/20 14:34	Reinspection Photo	63 Load JP	
5	18/01/20 14:34	Reinspection Photo	■ Load JP	G 5
6	18/01/20 14:34	Reinspection Photo	■ Load JP	G B
7	18/01/20 14:34	Reinspection Photo	■ Load JP	G S
8	18/01/20 14:34	Reinspection Photo	● Load JP	-
19	18/01/20 14:34	Reinspection Photo	■ Load JP	
0	18/01/20 14:34	Reinspection Photo	■ Load 3P	
1	18/01/20 14:34	Reinspection Photo	■ Load JP	
	- I STORES VIEW OF BASE	To the William Control		
2	18/01/20 14:34	Reinspection Photo	O Load JP	_
3	18/01/20 14:34	Reinspection Photo	1 Load JP	-
4	18/01/20 14:34	Reinspection Photo	Load JP	and the last of
5	18/01/20 14:34	Reinspection Photo	■ Load JP	-
6	18/01/20 14:34	Reinspection Photo	■ Load JP	G
7	18/01/20 14:34	Reinspection Photo	■ Load JP	G B
8	18/01/20 14:34	Reinspection Photo	■ Load JP	G 5
9	18/01/20 14:34	Reinspection Photo	■ Load 3P	

	tos/Images		3 per p	age v	N
Vo.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	
100	18/01/20 14:34	Reinspection Photo	0	Load JPG	N
101	18/01/20 14:34	Reinspection Photo	0	Load JPG	100
102	18/01/20 14:34	Reinspection Photo	0	Load JPG	V
103	18/01/20 14:34	Reinspection Photo	0	Load JPG	V
		Reinspection Photo	0	Load JPG	V
104	18/01/20 14:34		0	Load JPG	V
105	18/01/20 14:34	Reinspection Photo			
106	18/01/20 14:34	Reinspection Photo	0	Load JPG	V
107	18/01/20 14:34	Reinspection Photo	0	Load JPG	V
108	18/01/20 14:34	Reinspection Photo	0	Load JPG	Z
109	18/01/20 14:34	Reinspection Photo	0	Load JPG	V
110	18/01/20 14:34	Reinspection Photo	0	Load JPG	V
111	18/01/20 14:34	After Repair Photo	0	Load JPG	V
112	18/01/20 14:34	After Repair Photo	0	Load JPG	V
			0	Load JPG	Ø
113	18/01/20 14:34	After Repair Photo			-
114	18/01/20 14:34	After Repair Photo	0	Load JPG	₩
115	18/01/20 14:34	After Repair Photo	0	Load JPG	N
116	18/01/20 14:34	After Repair Photo	0	Load JPG	V
117	18/01/20 14:34	After Repair Photo	0	Load JPG	V
118	18/01/20 14:34	After Repair Photo	0	Load JPG	2
119	18/01/20 14:34	After Repair Photo	0	Load JPG	V
120	18/01/20 14:34	After Repair Photo	0	Load JPG	V
	TSOURTH AND ADDRESS OF THE PARTY OF THE PART	CONTRACTOR OF THE CONTRACTOR O	0	Load JPG	<b>Z</b>
121	18/01/20 14:34	After Repair Photo		1001050505050	_
122	18/01/20 14:34	After Repair Photo	0	Load JPG	2
123	18/01/20 14:34	After Repair Photo	0	Load JPG	Ø
124	18/01/20 14:34	After Repair Photo	0	Load JPG	12
125	18/01/20 14:34	After Repair Photo	0	Load JPG	M
126	18/01/20 14:34	After Repair Photo	0	Load JPG	V
127	18/01/20 14:34	After Repair Photo	0	Load JPG	V
128	18/01/20 14:34	After Repair Photo	0	Load JPG	V
129	18/01/20 14:34	After Repair Photo	0	Load JPG	Ø
		25180-100-2-00-00-00-00-00-00-00-00-00-00-00-00	0	Load JPG	Ø
130	18/01/20 14:34	After Repair Photo			-
131	18/01/20 14:34	After Repair Photo	0	Load JPG	M
132	18/01/20 14:34	After Repair Photo	0	Load JPG	Ø
133	18/01/20 14:34	After Repair Photo	0	Load JPG	2
134	18/01/20 14:34	After Repair Photo	0	Load JPG	
Doc	umentation		1 per j		82
Nα	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	26/12/19 15:29	ACKNOWLEDGEMENT EMAIL TO III DD 26.12.19	0	Load PDF	-
2	26/12/19 15:29	TP ESTIMATE + TP GIA REPORT	0	Load PDF	
4	08/01/20 01:25	TP ESTIMATE - MARKED WHEEL ALIGNMENT REPORT	0	Load PDF	-
5	08/01/20 01:25 24/02/20 11:23	LOD AND OTHER DOCUMENTS	0	Load PDF	
6	28/02/20 14:07	WORKSHOP INVOICE	ő	Load PDF	
7	28/02/20 14:07	RENTAL RECEIPT	Ŏ	Load PDF	
8	28/02/20 14:07	RENTAL MILEAGE	0	Load PDF	
9	28/02/20 14:07	LTA SEARCH	Ō	Load PDF	
10	28/02/20 14:07	LOD	0	Load POF	
11	30/03/20 09:40	DISCHARGE VOUCHER	0	Load PDF	
12	30/03/20 09:40	AUTHORISATION TO ACT FORM	0	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Prin

#### **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	5ave	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

#### LKK Auto Consultants Pte Ltd (Co.Reg. No;199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19022682/DGA3Q2

Date:

30/03/2020

Claim

No:

REFERENCE

Handling Insurer: India International Insurance Pte

Policy No:

D19MFL0005549

Claimant

SHC1810L

Insured Vehicle No:

GBH643D

TP

Vehicle No: Date of Loss:

23/12/2019

Nature of Claim:

MFL2020D00000008

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**SHC1810L** 

Make & Model:

HYUNDAI AE IONIQ HEV DCT, 1.6 (A) 13/09/2018 (Man. Year: 2018)

Engine No: Chassis No: G4LEJU081784

Reg. Date: Colour

Blue

KMHC851CVKU107536

Engine Capacity:

1580 cc

Odometer:

206747 km

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

Rear Tyre Size:

195/65 R15

Front Tyre Size: Front Left Side:

195/65 R15 Davanti 5 mm Davanti 5 mm

Rear Left Side: Rear Right Side: Davanti 5 mm Davanti 5 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,790.04	5,294.88	2,495.16	32.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	1,730.00	2,470.00	58.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,990.04	7,024.88	4,965.16	41.41
Approved Total (Overridden) (S\$)		5,600.00		
(SS)	11,990.04	5,600.00	6,390.04	53.29
+ GST 7.00/7.00% (S\$)	839.30	392.00	447.30	53.29
Nett Amount (S\$)	12,829.34	5,992.00	6,837.34	53.29
+ Loss of Use (12.0 x S\$4	10.00/day) (S\$)	480.00		
+ Car Rental (12.0 x S\$12	(5.19/day) (S\$)	1,502.28		
+ Doc/Se	+ Doc/Search Fee (S\$)			
Net	Nett Liability (S\$)			

INSPECTION

Date of Assignment:

26/12/2019

Date Inspected:

26/12/2019 Inspected At:

Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g... 30/3/2020

#03-19 AMK Autopoint Singapore 568047

Estimated Period of Repair:

6.0 days

Adjuster: BRYAN TANI Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g... 30/3/2020

## REPAIR DETAILS

Referen	ce				
Part Source:		(Last Synchronised: 28 Feb 2020)			
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	(Unsubmitted, no print-code for SHC1810L)				
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running pag- numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info	tems/values	not in reference catalogue are prefixed with an asterisk *.			

#### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut / Mtg Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER SIDE BRACKET (LH)	Not Necessary	33.10 FL	*-FL
3	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR FENDER (LHH)	Dented	1,768.30 FL	*1,768.30 FL
5	1		*REAR FENDER INNER LINING (LH)	Not Necessary	73.60 FL	*-FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	28.20 FL	*28.20 FL
7	1		*REAR DOOR (LH)	Dented	1,789.90 FL	*1,789.90 FL
8	1		*REAR DOOR GEAR /REGULATOR (LH)	Not Necessary	229.90 FL	*-FL
9	1		*REAR DOOR MOTOR (LH)	Not Necessary	160.50 FL	*-FL
10	1		*REAR DOOR PROTECTOR (LH)	Necessary	116.20 FL	*116.20 FL
11	1		*ROCKER PANEL OUTER GARNISH (LH)	Cut / Bent	290.00 FL	*290.00 FL
12	1		*REAR TYRE RIM (LH)	Not Necessary	1,124.20 FL	*-FL
13	1		*REAR WHEEL HUP-CAP (LH)	Cut	134.10 FL	*134.10 FL
14	1		*REAR WHEELBEARING ING & HUB	Damaged	454.00 FL	*454.00 FL
15	1		*REAR TRAILING ARM (LHH)	Distorted	121,00 FL	*121.00 FL
16	1		*REAR ASSIST (LH)	Distorted	92.80 FL	*92.80 FL
17	1		*REAR SHOCK ABSORBER (LH)	Distorted	230.50 FL	*230.50 FL
18	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	61.40 FL	*-FL
19	1		*REAR CROSSMEMBER	Not Necessary	756.40 FL	*-FL
20	1		*STABILIZER BAR	Not Necessary	224.00 FL	*-FL
21	1		*STABILIZER LINK	Not Necessary	92.10 FL	*-FL
22	1		*REAR UPPER ARM (LH)	Distorted	112.20FL	*112.20 FL
23	1		*REAR LOWER ARM (LH)	Distorted	393.10 FL	*393.10 FL
24	1		*REAR KNUCKLE ARM (LH)	Distorted	386,90 FL	*386.90 FL
25	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
26	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
27	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
28	1		*FRONT DOOR COLOURED COMFORT LOGO (LH)	Not Necessary	75.00 FS	*- FS
29 F=Fn	1 anchise	part S=5	*REAR TYRE (LH) SpcNett. L=ListItemDisc.	Not Necessary	216,00 FS	*- F8
n set di		AMERICA ST	Francisco de America (1868)	Sub Total (S\$)	9,620.80	6,574.60
			- List Item Discount on L Items	시작시간 600 시간		1,279.72
				Total Parts (S\$)	7,790.04	5,294.88

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING CHARGE	New	1,250.00	600.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	100.00	30.00
5	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
6	REMOVE/REFIX REVERSE SENSOR	New	120.00	0.00
7	REMOVE/REFIX FUEL TANK	New	150.00	0.00
8	REPAIR EXHAUST PIPE	New	60.00	0.00
9	TRANSFER OF DOOR	New	120.00	60.00
10	REMOVE/REFIX UNDERCARRIAGE (RR)	New	200.00	150.00
11	REAR WHEEL ALIGNMENT	New	120.00	60.00
12	RE-SET REAR ABS SYSTEM )	New	200.00	150.00
13	RE-SET REAR POWER WINDOW SYSTEM }	New	200.00	0.00
14	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	0.00
	Gross Labour Cost (S		4,200.00	1,730.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.