

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19022690/HPA3Q2

Date: 23/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SKV5968D	Insured Vehicle No :	SHD6594Y
Date of Loss: 21/12/2019	Nature of Claim: TP	Claim No: MCT19120532

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV5968D	Engine No:	CDN040396
Make & Model:	AUDI A5, 2.0 TFSI QUATTRO (A)	Chassis No:	WAUZZZ8T49A053613
Reg. Date:	09/07/2009 (Man. Year: 2009)	Odometer:	181707 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35Z R19	Rear Tyre Size:	255/35Z R19
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,665.62	3,850.46	7,815.16	66.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,220.00	1,260.00	50.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,145.62	5,070.46	9,075.16	64.16
Approved Total (Overridden) (\$\$)		4,050.00		
Nett Amount (\$\$)	14,145.62	4,050.00	10,095.62	71.37
+ Car Rental (7.0 x S\$150.00/day) (\$\$)		1,050.00		
+ Doc/Search Fee (\$\$)		7.45		
+ Other Costs (\$\$)		120.00		
Nett Liability (\$\$)		5,227.45		

INSPECTION

Date of Assignment:	26/12/2019	
Date Inspected:	26/12/2019	Inspected At:
		Sat Motors (HQ)
		24 Defu Lane 12
		Singapore 539131
Estimated Period of Repair:	5.0 days	

Adjuster: LEE HOCK ANN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$61,000.00(est) less LTA Rebate: \$30,603.00(est) = Nett Value :\$30,397.00(est)

Please note that third party vehicle COE expiry date is 31 March 2029.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Feb 2020)	
Parts:	N/A	AUDI A5 2.0 TFSI QUATTRO (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV5968D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	1,458.00 FL	*1,200.70 FL
2	1		*REAR BUMPER SIDE BRACKET (RIGHT)	Crumpled	168.75 FL	*160.31 FL
3	1		*REAR TAIL LAMP (RIGHT)	Cracked	432.00 FL	*410.40 FL
4	1		*REAR WHEEL ARCH COWLING (RIGHT)	Serviceable	255.15 FL	*- FL
5	1		*REAR WHEEL GARNISH (RIGHT)	Cut	1,053.00 FL	*650.50 FL
6	1		*REAR FENDER (RIGHT)	Repair	1,552.50 FL	*- FL
7	1		*REAR WINDOWSCREEN MOULDING	Serviceable	116.10 FL	*- FL
8	1		*REAR BUMPER PARKING SENSOR OUTER (RIGHT)	Shorted	202.50 FL	*150.20 FL
9	1		*REAR ABSORBER (RIGHT)	Serviceable	877.50 FL	*- FL
10	1		*REAR LOWER ARM (RIGHT)	Bent	337.50 FL	*250.80 FL
11	1		*REAR UPPER ARM (RIGHT)	Serviceable	256.50 FL	*- FL
12	1		*REAR WHEEL KNUCKLE (RIGHT)	Crumpled	843.75 FL	*400.20 FL
13	1		*REAR WHEEL BEARING (RIGHT)	Crumpled	432.00 FL	*310.20 FL
14	1		*REAR CALIPER (RIGHT)	Serviceable	618.30 FL	*- FL
15	1		*REAR ROTOR (RIGHT)	Serviceable	243.00 FL	*- FL
16	1		*REAR BRAKE PAD	Serviceable	213.30 FL	*- FL
17	1		*REAR BUMPER DIFFUSER	Scratched	783.00 FL	*350.80 FL
18	1		*REAR EXHAUST MUFFLER (RIGHT)	Serviceable	1,552.50 FL	*- FL
19	1		*REAR TYRE (RIGHT)	Serviceable	607.50 FL	*- FL
20	1		*REAR WHEEL ALIGNMENT	Damaged	162.00 FL	*60.00 FL
21	1		*REAR BUMPER INNER PANEL BRACKET (RIGHT)	Cracked	114.75 FL	*109.01 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	12,279.60	4,053.12
- List Item Discount on L Items 5.00/5.00% (\$\$)	613.98	202.66
Total Parts (\$\$)	11,665.62	3,850.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO FIX & DISMANTLE AFFECTED REAR PORTION ,REPAIR RR FENDER R/H WELDING AND CUTTING OF AFFECTED AREAS ,INCLUDING CHASSIS ALIGNMENT	New	1,000.00	600.00
2	TO APPLY ANTI RUST COAT AND AFFECTED AREAS	New	120.00	0.00
3	TO CHECK WIRING	New	120.00	30.00
4	SPRAY PAINTING FOR AFFECTED PANELS	New	1,000.00	450.00
5	TO APPLY WATERPROOFING SEALER ON END PANELS	New	120.00	60.00
6	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE	New	120.00	80.00
Gross Labour Cost (\$\$)			2,480.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >