

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SKV5968D

Report No

Chassis No:

Engine No:

Date : 24/12/2019

MAKE: AUDI

MODEL: A5

TYPE : MOTOR CAR

Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Rear Bumper ✓ cut	Damaged	\$ 1,458.00	\$ 1,385.10
2	1	Rear Bumper Side Bracket (Right) ✓ CR4	Damaged	\$ 168.75	\$ 160.31
3	1	Rear Tail Lamp (Right) ✓ CR4	Damaged	\$ 432.00	\$ 410.40
4	1	Rear Wheel Arch Cowling (Right) X (SVC)	Damaged	\$ 255.15	\$ 242.39
5	1	Rear Wheel 18 inch (Right) 19 inch ✓ cut	Damaged	\$ 1,053.00	\$ 1,000.35
6	1	Rear Fender (Right) X (CR)	Damaged	\$ 1,552.50	\$ 1,474.88
7	1	Rear Windowscreen Moulding X (SVC)	Necessary	\$ 116.10	\$ 110.30
8	1	Rear Bumper Parking Sensor Outer (Right) ✓	Damaged	\$ 202.50	\$ 192.38
9	1	Rear Absorber (Right) X (SVC)	Damaged	\$ 877.50	\$ 833.63
10	1	Rear Lower Arm (Right) ✓ AT	Damaged	\$ 337.50	\$ 320.63
11	1	Rear Upper Arm (Right) X (SVC)	Damaged	\$ 256.50	\$ 243.68
12	1	Rear Wheel Knuckle (Right) ✓ CR4	Damaged	\$ 843.75	\$ 801.56
13	1	Rear Wheel Bearing (Right) ✓ CR4	Damaged	\$ 432.00	\$ 410.40
14	1	Rear Caliper (Right) X (SVC)	Damaged	\$ 618.30	\$ 587.39
15	1	Rear Rotor (Right) X (SVC)	Damaged	\$ 243.00	\$ 230.85
16	1	Rear Brake Pad X (SVC)	Damaged	\$ 213.30	\$ 202.64
17	1	Rear Bumper Diffuser ✓ SCR	Damaged	\$ 783.00	\$ 743.85
18	1	Rear Exhaust Muffler (Right) X (SVC)	Damaged	\$ 1,552.50	\$ 1,474.88
19	1	Rear Tyre (Right) X (SVC)	Damaged	\$ 607.50	\$ 577.13
20	1	Rear Wheel Alignment (Report) ✓	Damaged	\$ 162.00	\$ 153.90
21	1	Rear Bumper Inner Panel Bracket (Right) ✓ CR4	Necessary	\$ 114.75	\$ 109.01
				\$ 12,279.60	\$ 11,665.62

Total (Parts): \$ 12,279.60

less

5% \$ 11,665.62

Labour Charges

22	To fix & dismantle affected rear portions; repair for fender R/H ✓	\$ 1,000.00
23	welding and cutting of affected areas, including chassis alignment	
24	To apply anti rust coat and affected areas X	\$ 120.00
25	To check wiring ✓	\$ 120.00
26	Spray painting for affected panels. ✓	\$ 1,000.00
27	To apply waterproofing sealer on end panels ✓	\$ 120.00
27	Diagnose ECU system and reset error code. ✓	\$ 120.00

Total Labour: \$ 2,480.00

Total cost of repairs (Total cost of parts + Total Labour Cost): \$ 14,145.62

Less 20%: \$ 11,316.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

As per report without prejudice
Resurvey after paint
5 Day 5.00pm
26/12/19

Hook ANN
8531883
Hook ANN@lkkAuto.com
* Noted and to resurvey
Align report before and after

Resurvey taken
27/12/19
5.00pm

Total
As per

4056.36

\$ 4050.11

parts 4053.12

parts less 5%

3850.46

1220

5070.46

20%