

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 1458G

DATE : 23.12.2019

MAKE :

TEL : 6542 5119

First Capital

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>Dented</i>			\$ 2,265.90	✓
	Bonnet Hinge (LH/RH) <i>✓</i>	\$	41.00	\$ 82.00	✓
	Bonnet Lock <i>✓</i>			\$ 36.90	✓
	Bonnet Absorber <i>HH</i>	\$	58.10	\$ 116.20	X
	Bonnet Insulator <i>HH</i>			\$ 196.50	X
	Bonnet Insulator Clips <i>HH</i>			\$ 8.40	X
	Radiator Grille <i>broken</i>			\$ 1,110.10	✓
	Radiator Grille H Emblem <i>broken/dislodged</i>			\$ 39.50	✓
	Front Bumper Cover <i>trim</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>trim</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>Dented</i>			\$ 402.10	✓
	Front Bumper Grille (LH) <i>dislodged</i>			\$ 93.60	✓
	Front Bumper Grille Airduct (LH) <i>HH</i>			\$ 26.20	X
	Front Bumper Lip <i>HH</i>			\$ 54.90	X
	Front Bumper Bracket Top (LH/RH) <i>HH</i>	\$	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>O/S HH N/S broken</i>	\$	24.60	\$ 49.20	✓
	Headlamp Support Top Cover <i>HH</i>			\$ 222.60	X
	Headlamp Support Panel Assy <i>Dented / broken</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>broken / mostly broken</i>	\$	1,388.00	\$ 2,776.00	✓
	Radiator <i>✓</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>HH</i>			\$ 792.95	X
	Radiator Bracket (RH/LH) <i>HH</i>	\$	6.50	\$ 13.00	X
	Radiator Guard <i>HH</i>	\$	20.00	\$ 40.00	X
	Horn Unit (LH/RH) <i>N/S broken O/S HH</i>	\$	73.80	\$ 147.60	✓
	Horn Wire <i>HH</i>			\$ 156.50	X
	Front Fender (LH) <i>Dented</i>			\$ 566.30	✓
	Front Fender Apron Panel (LH) <i>replaced Dented</i>			\$ 637.00	✓
	Front Fender Shield (LH) <i>HH</i>			\$ 174.90	X
	Air Cleaner Assy <i>broken</i>			\$ 118.60	✓
	Air Duct <i>HH</i>			\$ 134.60	X
	Air Flow Sensor <i>broken</i>			\$ 502.20	✓
	Air Cleaner Bottom Assy <i>broken</i>			\$ 325.00	✓
	Aircon Condenser <i>✓</i>			\$ 927.50	✓
	Front Wheel Rim (LH) <i>HH</i>			\$ 325.30	X
	Front Wheel Hub Cap (LH) <i>HH</i>			\$ 107.10	X
	Front Wheel Bearing <i>Down</i>			\$ 540.50	✓
	Front Shock Absorber (Assy) (LH) <i>distorted</i>			\$ 342.20	✓
	Front Shock Absorber Mounting (LH) <i>HH</i>			\$ 108.80	X
	Front Drive Shaft (LH) <i>HH</i>			\$ 1,030.80	X
	Rack & Pinion Assy <i>HH</i>			\$ 969.60	X
	STG Tie End <i>HH</i>			\$ 62.60	X
	Stabilizer Bar <i>HH</i>			\$ 252.30	X
	Stabilizer Bar Bush (LH) <i>HH</i>			\$ 16.40	X
	Stabilizer Bar Link <i>HH</i>			\$ 61.10	X
	Stabilizer Bracket <i>HH</i>			\$ 24.00	X
	Front Suspension Lower Arm (LH) <i>distorted</i>			\$ 529.30	✓

SHA 1458G

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Chasis Member 2 1st N/S			\$ 1,060.70 ✓
	Knuckle Arm (LH) 2 1st distal			\$ 552.00 ✓
	Engine Under Cover HH			\$ 334.60 X
	Engine Crossmember HH			\$ 2,094.40 X
	Gearbox HH			\$ 14,808.00 X
	Gearbox Mounting HH			\$ 215.40 X
	Inter Cooler 2 punctured			\$ 1,032.50 ✓
	Inter Cooler Mounting (2 PCS) HH			\$ 25.90 X
	Hose B To Inter Cooler HH			\$ 229.70 X
	Hose C To Inter Cooler Inlet HH			\$ 294.50 X
	Pipe To Inter Cooler HH			\$ 167.05 X
	Pipe To Inter Cooler Outlet HH			\$ 244.55 X
	Wiring-Engine 1 Socket broken			\$ 3,326.00 ✓
	Wiring-ECM HH			\$ 3,243.00 X
	Auto Gear Oil HH			\$ 110.40 X
	SUB TOTAL			\$ 46,926.85
	LESS 20%			\$ 9,385.37
	DISCOUNTED TOTAL			\$ 37,541.48
	Front Number Plate broken			\$ 45/- 25.00 Nett ✓
	Front No Plate Trim Cover broken			\$ 30.00 Nett ✓
	Front Fender Advertisement Logo (LH) LCC			\$ 100.00 Nett ✓
				\$ 155.00
	Labour Charge			
	Panel Beating			\$ 1,600.00 800/-
	Spray Painting Charge			\$ 1,250.00 700/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 HH
	Front Chassis Alignment Charge			\$ 400.00 150/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 80/-
	Remove/Refix Engine Gearbox			\$ 650.00 180/-
	Remove/Refix Dashboard			\$ 450.00 150/-
	Remove/Refix Fuse Box			\$ 180.00 50/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Re-set Frt ABS System			\$ 200.00 150/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 150/-
	TOTAL LABOUR			\$ 5,880.00
	ESTIMATE TOTAL			\$ 43,576.48

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Jan

LKK Auto

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 1458G (Supplementary)

DATE : 27.12.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	New Battery <i>crack 50% defraction</i>			\$ 207.00 103.50
				\$ 207.00
	<i>ryan</i>			
	<i>2kk Auto</i>			
	<i>[Signature]</i>			

Nett ✓

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.