Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19022699/UGS3Q2

Date: 04/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700044816

Claimant
Vehicle No: GBF5347L Insured Vehicle No: SLR8060L

Date of Loss: 24/12/2019 Nature of Claim: TP Claim No: 1895900978SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF5347L

Make & Model: NISSAN CABSTAR, 3.0 (M) Engine No: ZD30014414N

Reg. Date: 08/12/2016 (Man. Year: 2016) Chassis No: JN1SC2F24Z0859082

Colour: Silver Odometer: 100109 km

Engine Capacity: 2953 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R13 (D)
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6/6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,660.00	3,572.00	2,088.00	36.89
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,970.00	820.00	1,150.00	58.38
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	7,630.00	4,392.00	3,238.00	42.44
	+ Loss of Use (6.0 x	S\$60.00/day) (S\$)	360.00		

+ Doc/Search Fee (S\$) 2.00

Nett Liability (S\$) 4,754.00

INSPECTION

Date of Assignment: 26/12/2019

Date Inspected: 26/12/2019 Inspected At: Liu's Brother Auto Engineering

Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay

Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki

Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: Chong Pui Lin

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR TAIL LAMP	Cracked	330.00 F	*330.00 FL
2	2		*REAR BACK DOOR (O/S)	Dented / Bent	1,200.00 FS	*1,000.00 FS
3	1		*REAR BACK DOOR LOCK (O/S)	Bent	350.00 FS	*300.00 FS
4	1		*REAR BACK DOOR (N/S)	Dented / Bent	1,300.00 FS	*1,000.00 FS
5	1		*REAR BACK DOOR LOCK (N/S)	Bent	350.00 FS	*300.00 FS
6	1		*REAR 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
7	1		*REAR PILLAR	Repair	650.00 FS	*-FS
8	1		*REAR LICENCE PLATE	Bent	20.00 FS	*15.00 FS
9	1		*REAR REVERSE SENSOR	Cracked	280.00 FS	*200.00 FS
10	1		*REAR STEP PANEL	Bent	480.00 FS	*450.00 FS
11	1		*REAR LOWER MEMBER	Repair	680.00 FS	*-FS
F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 5,660.00 3,605.00						
	- List Item Discount on L Items 0.00/10.00% (S\$)			0.00	33.00	
				Total Parts (S\$)	5,660.00	3,572.00
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00				
2	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	60.00	50.00				
3	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	1,000.00	550.00				
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED ARE	New	800.00	200.00				
5	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	0.00				
	Gross Labour Cost (S\$)		1,970.00	820.00				

< END OF ESTIMATES >

Report was unsubmitted during this print-out.