Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022708/KDA3Q2

Date: 29/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SLK1780A Insured Vehicle No: SLN6885H

Vehicle No:

Date of Loss: ΤP 21/12/2019 Nature of Claim: Claim No: 0410989699SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLK1780A Reg No:

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRR977260

Reg. Date: 09/01/2017 (Man. Year: 2016) Chassis No: JTDKB3FU903540072

Colour: Metallic Pearl White Odometer: 252089 km

Engine Capacity: 1798 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm Front Right Side: Rear Right Side: Yokohama 8 mm Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,800.01	860.86	939.15	52.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	703.97	236.30	467.67	66.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,503.98	1,097.16	1,406.82	56.18
+ GST 7.00/7.00% (S\$)	175.28	76.80	98.48	56.18
Nett Amount (S\$)	2,679.26	1,173.96	1,505.30	56.18
+ Car Rental (4.0 x	S\$78.95/day) (S\$)	315.80		
+ Doo	c/Search Fee (S\$)	7.45		
	Nett Liability (S\$)	1,497.21		

INSPECTION

Date of Assignment: 24/12/2019

24/12/2019 Inspected At: Esteem Performance Pte Ltd (HQ) Date Inspected:

Blk 5033 Ang Mo Kio Ind Park 2, #01-

259

Singapore 569536

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: CHAN JIA LE Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	497.50 FL	*497.50 FL
2	1		*REAR COVER BUMPER	Dented	582.60 FL	*582.60 FL
3	1		*REAR BUMPER COVER	Serviceable	31.70 FL	*- FL
4	1		*L/R BUMPER BRACKET	Repair	112.70 FL	*- FL
5	1		*R/R BUMPER BRACKET	Repair	112.70 FL	*- FL
6	1		*L/R BUMPER CORNER	Mtg Cracked	149.70 FL	*149.70 FL
7	1		*R/R BUMPER CORNER	Serviceable	149.70 FL	*- FL
8	1		*REAR BUMPER REINF	Repair	398.90 FL	*- FL
9	1		*WORDING PRIUS	Not Necessary	51.90 FL	*- FL
10	1		*WORDING HYBRID	Not Necessary	55.47 FL	*- FL
11	1		*ART WORK ART WORK	Not Necessary	300.00 FS	*- FS
F=Fra	nchise	part. S=SpcNe	ett. L=ListItemDisc.			
		Sub Total (S\$)			2,442.87	1,229.80
			- List Item Discount on L	642.86	368.94	
				Total Parts (S\$)	1,800.01	860.86
			Report was unsubi	mitted during this print-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	55.0 WU X 50.00 SGD/H	New	275.00	60.00
2	LABOUR COST 63.0 WU X 50.00 SGD/H	New	315.00	105.00
3	MATERIAL COST	New	113.97	71.30
		Gross Labour Cost (S\$)	703.97	236.30
				-
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >