

CS3/FWD19016722/Gsf3<sup>22</sup>-1  
 ASSIGNMENT (Office)  
 Date/Time: 8/11/2019  
 20/9/2019  
 From Person: Lionel  
Vanessa Chan of FRD  
 Estimated Cost: Bill to:  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS  
 To Inspect Vehicle No: SKM 6795B Insured: SLW 8648 R  
 at Workshop w/s The Mechanic Tel: 91193959 Bao Bao  
 of 25 Kaki Bukit Rd 4 #05-85 Synergy  
 Policy No: PNC2019-00000194 Claim No: W01900028351  
 Sum Insured: Excess:  
 Make of Veh: D.O.A. 19/9/2019  
 (Client's Record)  
 CA / REV / REP. / REV 24 HRS  
 Date/Time: 23/9 Person Contacted: Bao Bao Vehicle IN OILT  
 H.O.D. Endorsement:

Date/Time	Action/Instruction
	SKM 6795B - X
	SLW 8648R - X
	Dismantle: 24/9/2019
	After repair: 25/9/2019

\$2250, 4 Days.  
 (\$4,850/- Red - 68%) 8/1/2020


RECEIVED 09 JAN 2020

Surveyor Enl. REF: FWD  
PRS ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s The Mechanic  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: skm6795B Yr Regn: 03 14  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or 1997  
 Make: BMW 320i cc 1997  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 65551 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WBA3B16000NS51606  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 225/30 ZR19  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 23-09-19  
 Survey held at w/s 4240pm  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction  
\$2000 - \$3000

Date/Time, File Pass to? ☐ : Preli. Report  
☐ : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_

Days Of Repair: 14  
 Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) \$ - RS. \$

) Photos

) Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : PRS

Lump Sum / I.B.I. (\$) \_\_\_\_\_

TOTAL

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	766B

Vehicle No.:	SKM6795B
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jan 2020
Vehicle Make:	B.M.W.
Vehicle Model:	320I SEDAN AT D/AB 4DR ABS HID
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	A2780662N20B20B
Chassis No.:	WBA3B16000NS51606
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$35,862.00
Original Registration Date:	27 Mar 2014
First Registration Date:	27 Mar 2014
Transfer Count:	2
Actual ARF Paid:	\$32,207.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Mar 2024
PARF Rebate Amount:	\$22,544.00

COE Expiry Date:	26 Mar 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$82,000.00
COE Rebate Amount:	\$34,019.00
<b>Total Rebate Amount:</b>	<b>\$56,563.00</b>

The information contained herein is correct as at 08 Jan 2020

OK

# CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440  
Email: [clappraiser@yahoo.com](mailto:clappraiser@yahoo.com) Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## INVOICE

Alvin Lim Hong Ghuan  
C/o: The Mechanic (Private Limited)  
25 Kaki Bukit Road 4  
#05-85 Synergy@KB, Singapore 417800

Invoice No: CL/191191  
Ref No: TMPL/09/1902/TP  
Date: 27 September 2019

### DESCRIPTION

### AMOUNT

#### OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. SKM 6795 B
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES  
(INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL SS 631.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

# C L APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440  
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Alvin Lim Hong Ghuan  
C/o: The Mechanic (Private Limited)  
25 Kaki Bukit Road 4  
#05-85 Synergy@KB, Singapore 417800

Date : 27 September 2019  
Our ref : TMPL/09/1902/TP

Accident Date : 19 September 2019  
Inspection Date : 23 September 2019  
Repairer Name : The Mechanic (Private Limited)  
25 Kaki Bukit Road 4  
#05-85 Synergy@KB, Singapore 417800

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No : SKM 6795 B  
Make / Model : BMW 320i  
Chassis No : WBA3B16000NS51606  
Engine No : A2780662N20B20B

Year / Capacity : 2014 / 1997 cc  
Colour : Black  
Mileage : 65551

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	Michelin	245/35 R19	5 mm	Sport
Front Offside	Michelin	245/35 R19	5 mm	Sport
Rear Nearside	Michelin	245/35 R19	5 mm	Sport
Rear Offside	Michelin	245/35 R19	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 61 copies

### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis  
and we have not given authorization and instruction to the repairer to proceed with the repair

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle  
and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 7,100.00** on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.

# S&L APPRAISER PTE LTD

Vehicle Registration No: SKM 6795 B

Our Ref No: TMPL/09/1902/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

## SPARE PARTS - LIST ITEMS

1	Rear boot lid	Damage	\$ 1,658.00	\$ 1,658.00 X repair
1	Rear boot lamp	Intact	\$ 390.00	
1	Rear boot logo	Necessary	\$ 79.00	\$ 79.00 /
1	Rear boot rubber	Necessary	\$ 225.00	\$ 225.00 X SVC
1	Rear n/s taillamp	Damage	\$ 655.00	\$ 655.00 / 357
1	Rear end panel	Repair	\$ 1,018.50	
1	Rear keyless sensor	Damage	\$ 195.00	\$ 195.00 X SVC
1	Rear bumper	Damage	\$ 1,495.00	\$ 1,495.00 / 1172.3
2	Rear bumper brackets	Damage	\$ 98.00	\$ 98.00 / 42
1	Rear bumper inner frame garnish	Damage	\$ 335.00	\$ 335.00 / 78
1	Rear bumper reinforcement	Damage	\$ 685.00	\$ 685.00 X SVC
2	Rear bumper side retainers	Necessary	\$ 279.90	\$ 279.90 X SVC
1/2	Rear bumper PDC sensors	Damage	\$ 627.00	\$ 627.00 309
1	Control unit for rear function module	Damage	\$ 365.00	\$ 365.00 X SVC
1	Control module for park assistant kit	Damage	\$ 345.00	\$ 345.00 X SVC
1	Sensor wire for smart opener kit	Damage	\$ 385.00	\$ 385.00 X SVC
			\$ 8,835.40	\$ 7,426.90 2037.3
Less 5%			\$ 441.77	\$ 371.35
Total Cost - List Items			\$ 8,393.63	\$ 7,055.56

## SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	Necessary	\$ 60.00	\$ 60.00 /
Total Cost - Special Nett items			\$ 60.00	\$ 60.00

Total cost of parts

\$ 8,453.63 \$ 7,115.56

# SCL APPRAISER PTE LTD

Vehicle Registration No: SKM 6795 B

Our Ref No: TMPL/09/1902/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 8,453.63	\$ 7,115.56

## LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 30
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 60
3	To remove and refit rear reverse sensor.	\$ 150.00	\$ 120.00 40
4	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 60.00 X
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,080.00	\$ 750.00 300
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,000.00	\$ 660.00 400

## GRAND TOTAL

\$ 11,013.63 \$ 8,875.56

2825.44

20% 2250



Vehicle Registration No: SKM 6795 B

Our Ref No: TMPL/09/1902/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : S 7,100.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

C L APPRAISER PTE LTD

Cheong K. H.  
Automotive Appraiser






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD			Ref : CS3/FWD19016722/Gsf3s2-1	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4 SINGAPORE 038986			Date : 09-01-2020	
			Code : FWD	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLW 8648R	Veh. Inspected	SKM 6795B	
Policy No.	PNCV2019-00000194	Coverage (\$)	0.00	
Claim No.	1201900028351	Excess (\$)	0.00	
Assign From	LIONEL	Assign Date	08/11/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	BMW 320i	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WBA3B16000NS51606	Colour	BLACK	
Odometer	65551	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	275/30 ZR19	MICHELIN	6 mm	
L/H Front Tyre	275/30 ZR19	MICHELIN	6 mm	
R/H Rear Tyre	275/30 ZR19	MICHELIN	6 mm	
L/H Rear Tyre	275/30 ZR19	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/09/2019	Inspection Date	23/09/2019	
Survey held at	THE MECHANIC PTE LTD 25 KAKI BUKIT ROAD 4 #05-85 SYNERGY @ KB SINGAPORE 417800			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 6795B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	1,658.00	-
1	REAR BOOT LAMP	INTACT	390.00	-
1	REAR BOOT LOGO	NECESSARY	79.00	79.00
1	REAR BOOT RUBBER	SERVICEABLE	225.00	-
1	REAR N/S TAILLAMP	DAMAGED	655.00	357.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,018.50	-
1	REAR KEYLESS SENSOR	SERVICEABLE	195.00	-
1	REAR BUMPER	DAMAGED	1,495.00	1,172.30
2	REAR BUMPER BRACKETS	DAMAGED	98.00	42.00
1	REAR BUMPER INNER FRAME GARNISH	DAMAGED	335.00	78.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	685.00	-
2	REAR BUMPER SIDE RETAINERS	SERVICEABLE	279.90	-
2	REAR BUMPER PDC SENSORS	DAMAGED 1PC ONLY	627.00	309.00
1	CONTROL UNIT FOR REAR FUNCTION MODULE	SERVICEABLE	365.00	-
1	CONTROL MODULE FOR PARK ASSISTANT KIT	SERVICEABLE	345.00	-
1	SENSOR WIRE FOR SMART OPENER KIT	SERVICEABLE	385.00	-
	LESS 5% DISCOUNT		-441.77	-101.86
			8,393.63	1,935.44
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	60.00
			60.00	60.00
<b>LABOUR</b>				
	TO REMOVE, REFIT, REPLACE DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.		150.00	60.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	40.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	100.00	-

Report Ref No. CS3/FWD19016722/Gsf3s2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOT LID AND REAR END PANEL.		1,080.00	300.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	400.00
			2,560.00	830.00
GRAND TOTAL			11,013.63	2,825.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CS3/FWD19016722/Gsf3s2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.