

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022744/KEA3Q2

Date: 27/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994406

Claimant
Vehicle No : SLG6649K **Insured Vehicle No :** SKV1320Z

Date of Loss: 21/05/2019 Nature of Claim: TP Claim No: 4686369512SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG6649K	Engine No:	2ZRR955064
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU803535994
Reg. Date:	10/10/2016 (Man. Year: 2016)	Odometer:	222388 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,786.14	2,786.14	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	294.10	294.10	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,080.24	3,080.24	0.00	0.00
+ GST 7.00/7.00% (\$\$)	215.62	215.62	0.00	0.00
Nett Amount (\$\$)	3,295.86	3,295.86	0.00	0.00
+ Car Rental (2.0 x S\$74.95/day) (\$\$)		149.90		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,453.21		

INSPECTION

Date of Assignment: 26/12/2019

Date Inspected: 26/12/2019 Inspected At: Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	450.80 FL	*450.80 FL
2	1		*FRONT MANUFACT BADGE	Necessary	87.10 FL	*87.10 FL
3	1		*R/HEADLAMP GLASS	Mtg Cracked	2,531.60 FL	*2,531.60 FL
4	1		*FOG LAMP RH	Cracked	910.70 FL	*910.70 FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (S\$)	3,980.20
					- List Item Discount on L Items 30.00/30.00% (S\$)	1,194.06
					Total Parts (S\$)	2,786.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	19.0 WU X 50.00 SGD/H	New	95.00	95.00
2	LABOUR COST 23.0 WU X 50.00 SGD/H	New	115.00	115.00
3	MATERIAL COST	New	84.10	84.10
Gross Labour Cost (\$\$)			294.10	294.10

Report was unsubmitted during this print-out.

< END OF ESTIMATES >