

AIG

**Esteem Performance Pte Ltd**  
**385 Sin Ming Drive, Vicom Vehicle**  
**Inspection Centre (575718)**

**Insurer Reference: SKV1320Z**  
**Repairer Reference: 025048**  
**Date calculated: 24/12/2019 1:43 PM**

**Full Report**  
**Registration: SLG6649K**  
**Printed: 24/12/2019 1:44 PM**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AIG Asia Pacific Insurance Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:	SKV1320Z	Date of Incident:	21/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer: TOYOTA  
 Model: PRIUS IV  
 Sub Model: BASE MODEL  
 Model Sheet Number: 70 P5 01  
 Registration: SLG6649K  
 VIN number:  
 Odometer:

**Model Specs**

TWO COAT METALLIC

*Not Authorized  
 Repairing B4 pain  
 2 days*

**Vehicle Condition**

**Vehicle Status**

Pre-Accident Damage:  
 Date of Inspection:


**Damage Areas**

**All** ☐  
**Underbody** ☐

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



## Labour

		Time Base 10 WU/h	Price = 50.00 SGD/h	
Code	Description		WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		15.0	75.00
B040)	R + R RIGHT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	5.00
NO NUMBER	R/HEADLAMP OUTER LENS R + R		1.0	5.00
NO NUMBER	ADJUST HEADLAMPS		2.0	10.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		<b>1.90</b>	<b>19.0</b>	<b>95.00</b>
<b>Total of Labour</b>				<b>95.00</b>

## Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1R		14.0	

### Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	67.90

### Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			14.0	
	Preparation Comp. Work Plastic		0.90	9.0	45.00
<b>Total</b>		<b>10 WU/h</b>	<b>2.30</b>	<b>23.0</b>	<b>115.00</b>

### Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	67.90
Material-constant Plastic	16.20
<b>Total</b>	<b>84.10</b>

## Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER	52119 47962		CRM 450.80 ✓
0431	FRONT MANUFACT BADGE	75310 47060		M 87.10 ✓
0564	R/HEADLAMP GLASS	81131 47690		M 2,531.60 ✓
1000	FOG LAMP RH	FOG LAMP RH		910.70 ?

f: OEM Parts

n: Non-OEM Parts

u: Used parts

<b>Savings</b>	<b>0.00</b>
<b>Subtotal</b>	<b>3,980.20</b>
<b>Subtotal Discount(+30.00%)</b>	<b>-1,194.06</b>
<b>Total</b>	<b>2,786.14</b>

### Final Calculation

	SGD	SGD
<b>Parts</b>	3,980.20	
Total Discount(+30.00%)	-1,194.06	
<b>Total Parts</b>		<b>2,786.14</b>
<b>Labour Time Base 10 WU/h</b>		
Total 19.0 WU X 50.00 SGD/h	95.00	
<b>Total of Labour</b>		<b>95.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 23.0 WU X 50.00 SGD/h	115.00	
Material Cost	84.10	
<b>Total Paint Including Material</b>		<b>199.10</b>
<b>Repair Cost Excludes GST</b>		<b>3,080.24</b>
GST (+7.0%)		<b>215.62</b>
<b>Repair Cost Included GST</b>		<b>3,295.86</b>

### Comments

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

No assessment notes entered.