

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022747/T1KA3Q2

Date: 14/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900092789

Claimant
Vehicle No : SH7805G **Insured Vehicle No :** SBW19C

Date of Loss: 25/12/2019 **Nature of Claim:** TP **Claim No:** 0751713154SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7805G	Engine No:	D4FDGU690472
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMHU096500
Reg. Date:	24/11/2016 (Man. Year: 2016)	Odometer:	48912 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,400.26	1,160.90	239.36	17.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	730.00	540.00	190.00	26.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,130.26	1,700.90	429.36	20.16
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	2,130.26	1,300.00	830.26	38.97
+ GST 7.00/7.00% (S\$)	149.12	91.00	58.12	38.98
Nett Amount (S\$)	2,279.38	1,391.00	888.38	38.97
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$112.67/day) (S\$)		225.34		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,723.83		
Global Sum Settlement (S\$)		1,720.00		

INSPECTION

Date of Assignment: 26/12/2019

Date Inspected: 27/12/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
2	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
3	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
4	1		*REAR BUMPER UNDER COVER	Repair	228.00 FL	*- FL
5	1		*REAR BUMPER REVERSE SENSOR	Not Working	135.70 FS	*135.70 FS
6	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
7	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
8	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
9	1		*REAR BUMPER SPONGE	Deformed	103.50 FL	*103.50 FL
10	1		*REAR BUMPER UNDER COVER	Deformed	228.00 FL	*228.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,641.40	1,342.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	241.14	181.30
Total Parts (\$\$)	1,400.26	1,160.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	280.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
3	WIRING CHARGE	New	50.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			730.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >