

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19022752/EDS3Q2

Date: 16/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800008325-01

Claimant
Vehicle No : SMN2767E **Insured Vehicle No :** SDY123A

Date of Loss: 24/12/2019 Nature of Claim: TP Claim No: 7023865949SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN2767E		
Make & Model:	AUDI A4, 2.0 MU TFSI (8E) (A)	Engine No:	CVK079367
Reg. Date:	01/07/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF48KN011309
Colour:	Blue	Odometer:	4940 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,981.00	6,691.20	7,289.80	52.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,072.00	1,972.00	2,100.00	51.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	18,053.00	8,663.20	9,389.80	52.01
+ GST 7.00/7.00% (\$\$)	1,263.71	606.42	657.29	52.01
Nett Amount (\$\$)	19,316.71	9,269.62	10,047.09	52.01
+ Loss of Use (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		9,571.62		

INSPECTION

Date of Assignment: 13/01/2020

Date Inspected: 13/01/2020 Inspected At: 281 ALEXANDRA ROAD
Repairer: Premium Automobiles Pte Ltd (UBI)

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,999.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	531.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	32.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -CENTRE	Not Necessary	178.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	191.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE-RH	Not Necessary	56.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,227.00 FS	*981.60 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	123.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
10	1		*FRONT BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
11	1		*FRONT BUMPER COVER	Not Necessary	116.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	34.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
14	1		*AIRCON STICKER	Not Necessary	7.00 FS	*- FS
15	1		*LOCK CARRIER BRACKET	Not Necessary	125.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT -LH/RH	Not Necessary	52.00 FS	*- FS
17	1		*HORN -RH LOW TONE	Not Necessary	262.00 FS	*- FS
18	1		*SPRING SHACKLE -RH	Not Necessary	26.00 FS	*- FS
19	2		*FRONT PARKING AID SENSOR -INNER /OUTER	Not Necessary	462.00 FS	*- FS
20	4		*FRONT PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
21	1		*LED HEADLIGHT -RH	Cut	7,087.00 FS	*5,669.60 FS
22	1		*LIFT CYLINDER -RH	Not Necessary	192.00 FS	*- FS
23	1		*RADIATOR OUTER DUCT -RH	Not Necessary	25.00 FS	*- FS
24	1		*RADIATOR INNER DUCT -RH	Not Necessary	11.00 FS	*- FS
25	1		*RADIATOR AIR GUIDE -UPPER	Not Necessary	15.00 FS	*- FS
26	1		*RADIATOR AIR GUIDE-LOWER	Not Necessary	19.00 FS	*- FS
27	1		*FRONT NO PLATE	Cut	40.00 FS	*40.00 FS
28	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 13,981.00 6,691.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKIN AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHTS ,RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,400.00	750.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			4,072.00	1,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >