

INS CASE OWNER:

CC 6/AIG190 22/55, T. 2/19

LKK:
IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGN 66264

Claim No.:

Name of Insured:

SEE KOK LIN

Policy No.:

70082644-03

Insured Tel No.:

HP:

Make / Model:

KIA

Excess Sec II :\$

D.O.A.:

10/11/19

Place of Accident:

7008 LEE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

LIN 6542B

INSRS:
WSP:
Tel:
Liability:
RMKS:CAS
GARANJAINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

LIN 6542B - 1

SGN 66264 - 5

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdowns Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MTR

Repair Cost:

42 \$51250.00

(5 days) Reduction:

34 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

0

(Agreed / Assessed) BOLA S/N No.:

38(0)

If NO or B 28, Ass. Lia: 0%

Repair Cost:

\$5

3 YRM CC TP 487

Loss of Rental (LOR):

\$5

(1 days)

Loss of Use (LOU):

\$5

(\$ 1 days)

Loss of Income (LOI):

\$5

(\$ 1 days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4320

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

\$5

Name 1:

Payee 2: (Strike if N.A.)


\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

COPY SENT
9/3/2022

**CAS GARAGE PTE LTD**

(Reg No: 201128067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: NO 78, SHENTON WAY, #07-16
S(079120)

Telephone: 64193000

Fax: 68357416

Email: assignment@lkauto.com

Make/ Model : HYUNDAI I30

Date: 23.12.2019

Chassis No : KMHC851CVHU035133

Vehicle No: SLN5543B

Date/Time of Accide 20.12.2019/ 2200

Date of Reg: 09.05.2017

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE		FINAL PRICE \$
1	FRONT BUMPER	1	\$ 846.50	de✓	\$ 846.50
2	FRONT BUMPER TOWING COVER	1	\$ 45.20	X m	\$ 45.20
3	FRONT BUMPER LOWER LIP	1	\$ 298.50	Rm	\$ de✓ 298.50
4	FRONT BUMPER UPPER STRIP RUBBER	1	\$ 145.30	1?	\$ 145.30
5	FRONT RADIATOR GRILLE WITH SENSOR	1	\$ 1,456.30	orig✓	1,456.30
6	FRONT RADIATOR AIR GUIDE	2	\$ 185.70	LH-RH X m	371.40
7	FRONT GRILLE UPPER GARNISH	1	\$ 265.80	de✓	\$ 265.80
8	FRONT GRILLE CHROME MOLDING	1	\$ 289.60	ora✓	\$ 289.60
9	FRONT LOGO	1	\$ 75.80	na✓	\$ 75.80
10	FRONT BUMPER SIDE RETAINERS	2	\$ 85.70	LH-de✓	\$ RH-X ¹ 171.40
11	FRONT BUMPER BRACKETS	2	\$ 85.90	LH-de✓	\$ RH-X ¹ 171.80
12	FRONT BUMPER SPONGE	1	\$ 245.80	ora✓	\$ 245.80
13	FRONT NUMBER PLATE GARNISH	1	\$ 65.80	de✓	\$ 65.80
14	FRONT BUMPER REINFORCEMENT	1	\$ 1,076.20	BT✓	\$ 1,076.20
15	FRONT BUMPER STIFFENER	1	\$ 185.70	X m	\$ 185.70
16	FRONT BUMPER SENSORS	4/2	\$ 225.80	na✓	\$ 903.20
17	FRONT SENSOR HARNESS	1	\$ 398.70	fm✓	\$ 398.70
18	FRONT RESONATOR BOX	1	\$ 345.20	X ¹	\$ 345.20
19	FRONT INTAKE AIR VENT	1	\$ 198.50	X ¹ m	\$ 198.50
20	FRONT WASHER TANK	1	\$ 158.90	X	\$ 158.90
21	FRONT BUMPER DAYLIGHT COVERS	2	\$ 198.50	LH-orig✓	\$ RH-X ¹ 397.00
22	FRONT BUMPER DAYLIGHT	2	\$ 643.00	LH-ora✓	\$ RH-X ¹ 286.00
23	FRONT BUMPER DAYLIGHT SIDE AIR VENTS	2	\$ 98.70	LH-ora✓	\$ RH-X ¹ 197.40
24	FRONT BUMPER ACTIVE FLAPS	2	\$ 382.50	X m	\$ 765.00
25	FRONT SUPPORT PANEL	1	\$ 1,335.80	?	\$ 1,335.80
26	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 245.30	de✓	\$ 245.30
27	FRONT ENGINE UNDERCOVER	1	\$ 398.20	de✓	\$ 398.20
28	HEADLAMPS	2	\$ 1,405.80	LH-orig✓	\$ RH-X ¹ 2,811.60
29	HEADLAMPS BRACKETS	2	\$ 95.60	LH-?	\$ RH-X ¹ 191.20
30	FRONT RADIATOR	1	\$ 658.20	de?	\$ 658.20
31	FRONT RADIATOR FAN COWLING	1	\$ 345.80	X m	\$ 345.80

32	FRONT RADIATOR FAN MOTOR	2	\$ 285.60	Xm	\$ 571.20
33	FRONT CONDENSER	1	\$ 698.50	HD	\$ 698.50
34	FRONT BONNET	1	\$ 2,254.20	bf	\$ 2,254.20
35	FRONT BONNET INNER LOCK	1	\$ 185.60	Kx	\$ 185.60
36	FRONT FENDERS	2	\$ 987.10	X	\$ 1,974.20
37	FRONT FENDERS INSULATOR	2	\$ 158.20	X	\$ 316.40
38	FRONT FENDERS INNER SHIELD	2	\$ 245.60	RH X	\$ 491.20
Total List Price Cost					\$ 22,838.40
PARTS DISCOUNT 20%					\$ 18,270.72

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	FRONT NUMBER PLATE WITH CASING	1SET	\$ 50.00	bt	\$ 45 50.00
2	FRONT BUMPER CLIPS	1SET	\$ 30.00	ner	\$ 30.00
3	FRONT ENGINE UNDERCOVER CLIPS	1 SET	\$ 30.00	ND	\$ 20- 30.00
4	FRONT FENDER INNER COWLING SET	2 SET	\$ 30.00	ND	\$ 20- 60.00
5	SUPPORT PANEL TOP GARNISH CLIPS	1 SET	\$ 30.00	DR	\$ 10 30.00
Total Special Nett Items					\$ 200.00

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 2,000.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,000.00

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00
TO REMOVE AND REFIT CONDENSER /RADIATOR AND TOP UP AIR CON GAS	\$ 120.00
TO REMOVE AND REPLACE FRONT SENSORS AND DISTANCE SETTLING	\$ 150.00
Total Others Cost	\$ 470.00

GRAND TOTAL

\$ 22,940.72

CAS GARAGE PTE LTD

UEN 201828067M

1 KAKI BUKIT AVENUE 6, #02-22 AITTOBAY,
SINGAPORE 417022

CAS GARAGE PTE LTD

Person Incharge: Allan

Direct Contact: +65 8782 7171

Email: allan@casgarage.sg

Fax : 6509 9501

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Tanflin 97445749/67418434
wp
27/12/19 @ 1015
sur @ lkkauto.com
tanflin @ lkkauto.com
5 days
Lumpsum
Resurvey after repair

REQUEST FOR SUPPLEMENTS PARTS

Vehicle No	SLN5543B	Date of Request	30.12.2019
Vehicle Model	HYUNDAI IONIC	Number of Days to Extend (If any)	

/N	Part Number	Part Description	Quantity	LIST Price
1		FRONT RADAR DETECTOR <i>cpa ✓</i>	1	\$2,910.50
2		FRONT RADIATOR INVERTER <i>?</i>	1	\$798.70
3		FRONT RADAR SENSOR HARDNESS <i>cut ✓</i>	1	\$298.50
4		FRONT BUMPER LOWER GRILLE <i>del ✓</i>	1	\$293.60

4,301.30

-20%

3,441.04

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 723K

Vehicle Details

Vehicle No.: SLN5543B

Vehicle to be Exported: No

Intended Deregistration
Date: 31 Dec 2019

Vehicle Make: HYUNDAI

Vehicle Model: AE IONIQ HEV 1.6 DCT
SR

Primary Colour: Silver

Manufacturing Year: 2017

Engine No.: G4LEHU395160

Chassis No.: KMHC851CVHU035133

Maximum Power
Output: 103.6 kW (138 bhp)

Open Market Value: \$27,850.00

Original Registration
Date: 09 May 2017

First Registration Date: 09 May 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 08 May 2027

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 08 May 2027

COE Category: B - Car above 1600cc or
97kW (130bhp)

COE Period(Years): 10

QP Paid: \$54,405.00

COE Rebate Amount: \$40,013.00

Total Rebate Amount: \$43,763.00

The information contained herein is correct as at 31 Dec 2019

OK

Nivitha (LKK Auto)

From: Allan Goh <allan@casgarage.sg>
Sent: Monday, 23 December 2019 5:02 PM
To: assignments@lkkauto.com
Cc: Nicole Chong
Subject: ACCIDENT INVOLVING SLN55438 & SGN6636U and SMH 7057U ALONG
BRADDELL ROAD TOWARDS CTE
Attachments: 23122019164922-0001.pdf

To the officer in charge,

Accident happened due to the negligence of SMH7057U(insured by AIG), kindly help to arrange for PRI at the soonest available time at the following address:

CAS Garage Pte. Ltd.
No.1 Kaki Bukit Ave 6
#02-22
Singapore 417883

Regards,
Allan Goh
CAS Garage Pte. Ltd.
No.1 Kaki Bukit Ave 6
#02-22
Singapore 417883
UEN: 201828067M
Mobile: 8782 7171



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : See Kok Sin
 Period of Insurance : 26 Sep 2019 To 25 Sep 2020
 Engine No. : G4FGGH539418
 Chassis No. : KNAFX411MH5651060

Vehicle No. : SGN6636U
 Policy No. : 2100483544-03
 Endorsement No. :
 Issued Date : 09 Aug 2019

ABOUT THE COVER

Make/Model : KIA FORTE K3 1.6 A EX
 Engine Capacity/Tonnage : 1,591.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2016
 Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

*You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 3 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, game-making, reliability trial or speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 188), Section 96 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$000 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

See Kok Sin - \$000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- 1 Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 600 Sri Ming Ave Singapore 575731 65328000
- 2 Cycle & Carriage Body & Paint Centre Add: 208 Pandan Gardens Singapore 609329 69644501
- 3 Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 109901 64279800
- 4 Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 130 Ulu Rd 2 Singapore 408650 67481000

For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG-SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 188), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third-Party Risks) Rules, 1980 (Malaysia).

0900710089

C&C FULCO-CORP SALES
 22 UBI ROAD 4 FULCO BUILDING
 SINGAPORE 408617 ANSP - MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mawle

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE

88P000

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 6 March 2020 9:57 AM
To: 'Md Noor, Norsiah'
Subject: RE: [MANDATE REQUEST] Your ref: 7805911424SG, ACCIDENT INVOLVING SGN 6636U (OI) & SLN 5543B (TP) ON 20/12/2019

Hi Norsiah,

We refer to our tele-conversation.

Base on your email below, BOLA S28d applied and third party was the last vehicle.

We will process to reject the claim and submit our report.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Md Noor, Norsiah <Norsiah.MdNoor@aig.com>
Sent: Tuesday, 3 March 2020 5:08 PM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: RE: [MANDATE REQUEST] Your ref: 7805911424SG, ACCIDENT INVOLVING SGN 6636U (OI) & SLN 5543B (TP) ON 20/12/2019

Dear Assher,

BOLA S28(d) apply for this accident.

Thank you

Kind regards
Norsiah

Norsiah Md Noor
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #08-16 Singapore 079120
Tel + (65) 6419-1805



Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Asher Sng (LKKAuto) [mailto:AsherSng@lkkauto.com]

Sent: Wednesday, January 8, 2020 9:55 AM

To: Md Noor, Norsiah <Norsiah.MdNoor@aig.com>

Subject: [EXTERNAL] [MANDATE REQUEST] Your ref: 7805911424SG, ACCIDENT INVOLVING SGN 6636U (OI) & SLN 5543B (TP) ON 20/12/2019

This message is from an external sender; be cautious with links and attachments.

Your ref: **7805911424SG**

Dear Sir/Madam,

ACCIDENT INVOLVING SGN 6636U (OI) & SLN 5543B (TP) ON 20/12/2019

We refer to the above matter.

Both party reported that involved in the chain collision that insured cut into third party lane.

Third party video uploaded in merimen clearly show that third party rear ended insured after insured complete changed into third party lane as result of a chain collision.

We are of the opinion that the liability in not third party favour.

In view of the above, we are intending to reject TP claim.

For your approval/ comments/ instruction.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 6 March 2020 10:03 AM
To: Nicole Chong
Cc: Allan Goh; CAS Garage Garage
Subject: ACCIDENT INVOLVING SLN 5543B AND SGN 6636U ON 20/12/2019
Attachments: OI SKETCH PLAN.pdf

Your Ref: SLN 5543B

'WITHOUT PREJUDICE'
SAVE AS TO COSTS


Hi Sir/Mdm,

We refer to the above matter.

ACCIDENT INVOLVING SLN 5543B AND SGN 6636U ON 20/12/2019

We attached here with a copy of our insured's accident statement for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client rear ended our insured vehicle in a chain collusion.



We are of the opinion that liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2019 Edit Reg		27 Dec 2019 00:00 Edit Adj Rpt	S\$12,250.00 Edit Estimates	S\$12,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SEE KOK SIN , ID: -								
Main Claimant:	CYCLEHERE								
Vehicle Reg. No.:	SLN5543B	Date of Loss:	20/12/2019 22:00 - :59 31 Months and 11 Days From LTA Reg Date (Man Yr)						
Claim Type:	TP / 7805911424SG	Policy/Cover Note No.:	2100483544 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGN6636U	Policy No. (Claimant):	VCX/P1941966						
	Excess:								
Repairer:	Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 6, #02-22 Autobay, 417883 Kaki Bukit - Tel: 9090 1222								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (30/12/2019): Re: Request for OI GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN5543B (7805911424SG)
[SGN6636U]
TP
CYCLEHERE
Dec 20 2019 10:00PM
[SEE KOK SIN]
Cas Garage Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	27/12/19 12:54	SLN5543B Video - Accident															Load AVI			
Photos/Images															1 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	08/01/20 09:46	Odometer Reading															Load JPG ☒			
2	08/01/20 09:46	Chassis Number															Load JPG ☒			
3	08/01/20 09:46	General View															Load JPG ☒			
4	08/01/20 09:46	General View															Load JPG ☒			
5	08/01/20 09:46	General View															Load JPG ☒			
6	08/01/20 09:46	General View															Load JPG ☒			
7	08/01/20 09:46	General View															Load JPG ☒			
8	08/01/20 09:46	General View															Load JPG ☒			
9	08/01/20 09:46	General View															Load JPG ☒			
10	08/01/20 09:46	General View															Load JPG ☒			
11	08/01/20 09:46	General View															Load JPG ☒			
12	08/01/20 09:46	General View															Load JPG ☒			
13	08/01/20 09:46	General View															Load JPG ☒			
14	08/01/20 09:46	General View															Load JPG ☒			
15	08/01/20 09:46	General View															Load JPG ☒			
16	08/01/20 09:46	General View															Load JPG ☒			
17	08/01/20 09:46	General View															Load JPG ☒			
18	08/01/20 09:46	General View															Load JPG ☒			
19	08/01/20 09:46	General View															Load JPG ☒			
20	08/01/20 09:46	General View															Load JPG ☒			
21	08/01/20 09:46	General View															Load JPG ☒			
22	08/01/20 09:46	General View															Load JPG ☒			
23	08/01/20 09:46	General View															Load JPG ☒			
24	08/01/20 09:46	General View															Load JPG ☒			
25	08/01/20 09:46	General View															Load JPG ☒			
26	08/01/20 09:46	General View															Load JPG ☒			
27	08/01/20 09:46	General View															Load JPG ☒			
28	08/01/20 09:46	General View															Load JPG ☒			
29	08/01/20 09:46	General View															Load JPG ☒			
30	08/01/20 09:46	General View															Load JPG ☒			
31	08/01/20 09:46	General View															Load JPG ☒			
32	08/01/20 09:46	General View															Load JPG ☒			
33	08/01/20 09:46	General View															Load JPG ☒			
34	08/01/20 09:46	General View															Load JPG ☒			
35	08/01/20 09:46	General View															Load JPG ☒			
36	08/01/20 09:46	General View															Load JPG ☒			
37	08/01/20 09:46	General View															Load JPG ☒			
38	08/01/20 09:46	General View															Load JPG ☒			
39	08/01/20 09:46	General View															Load JPG ☒			
40	08/01/20 09:46	General View															Load JPG ☒			

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	08/01/20 09:46	General View	 Load JPG	☒
42	08/01/20 09:46	General View	 Load JPG	☒
43	08/01/20 09:46	General View	 Load JPG	☒
44	08/01/20 09:46	General View	 Load JPG	☒
45	08/01/20 09:46	General View	 Load JPG	☒
46	08/01/20 09:46	General View	 Load JPG	☒
47	08/01/20 09:46	General View	 Load JPG	☒
48	08/01/20 09:46	General View	 Load JPG	☒
49	08/01/20 09:46	General View	 Load JPG	☒
50	08/01/20 09:46	General View	 Load JPG	☒
51	08/01/20 09:46	General View	 Load JPG	☒
52	08/01/20 09:46	General View	 Load JPG	☒
53	08/01/20 09:46	General View	 Load JPG	☒
54	08/01/20 09:46	General View	 Load JPG	☒
55	08/01/20 09:46	General View	 Load JPG	☒
56	08/01/20 09:46	General View	 Load JPG	☒
57	08/01/20 09:46	General View	 Load JPG	☒
58	08/01/20 09:46	General View	 Load JPG	☒
59	08/01/20 09:46	General View	 Load JPG	☒
60	08/01/20 09:46	General View	 Load JPG	☒
61	08/01/20 09:46	General View	 Load JPG	☒
62	08/01/20 09:46	General View	 Load JPG	☒
63	08/01/20 09:46	General View	 Load JPG	☒
64	08/01/20 09:46	General View	 Load JPG	☒
65	08/01/20 09:46	General View	 Load JPG	☒
66	08/01/20 09:46	General View	 Load JPG	☒
67	08/01/20 09:46	General View	 Load JPG	☒
68	08/01/20 09:46	General View	 Load JPG	☒
69	08/01/20 09:46	General View	 Load JPG	☒
70	08/01/20 09:46	General View	 Load JPG	☒
71	08/01/20 09:46	General View	 Load JPG	☒
72	08/01/20 09:46	General View	 Load JPG	☒
73	08/01/20 09:46	General View	 Load JPG	☒
74	08/01/20 09:46	General View	 Load JPG	☒
75	08/01/20 09:46	General View	 Load JPG	☒
76	08/01/20 09:46	General View	 Load JPG	☒
77	08/01/20 09:46	General View	 Load JPG	☒
78	08/01/20 09:46	General View	 Load JPG	☒
79	08/01/20 09:46	General View	 Load JPG	☒
80	08/01/20 09:46	General View	 Load JPG	☒
81	08/01/20 09:46	General View	 Load JPG	☒
82	08/01/20 09:46	General View	 Load JPG	☒
83	08/01/20 09:46	General View	 Load JPG	☒
84	08/01/20 09:46	General View	 Load JPG	☒
85	08/01/20 09:46	General View	 Load JPG	☒
86	08/01/20 09:46	General View	 Load JPG	☒
87	08/01/20 09:46	General View	 Load JPG	☒
88	08/01/20 09:46	General View	 Load JPG	☒
89	08/01/20 09:46	General View	 Load JPG	☒
90	08/01/20 09:46	General View	 Load JPG	☒
91	08/01/20 09:46	General View	 Load JPG	☒
92	08/01/20 09:46	General View	 Load JPG	☒
93	08/01/20 09:46	General View	 Load JPG	☒
94	08/01/20 09:46	General View	 Load JPG	☒
95	08/01/20 09:46	General View	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	08/01/20 09:46	General View	 Load JPG	☒
97	08/01/20 09:46	General View	 Load JPG	☒
98	08/01/20 09:46	General View	 Load JPG	☒
99	08/01/20 09:46	General View	 Load JPG	☒
100	08/01/20 09:46	General View	 Load JPG	☒
101	08/01/20 09:46	General View	 Load JPG	☒
102	08/01/20 09:46	General View	 Load JPG	☒
103	08/01/20 09:46	General View	 Load JPG	☒
104	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
105	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
106	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
107	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
108	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
109	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
110	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
111	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
112	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
113	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
114	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
115	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
116	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
117	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
118	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
119	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
120	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
121	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
122	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
123	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
124	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
125	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
126	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
127	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
128	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
129	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
130	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
131	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
132	08/01/20 09:47	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/12/19 12:53	TP GIA REPORT	 Load PDF	
2	02/01/20 14:22	TP ESTIMATE-MARKED	 Load PDF	
3	06/03/20 10:04	APPROVAL TO REJECT TP CLAIM	 Load PDF	
4	06/03/20 10:04	EMAIL WSP TO REJECT TP CLAIM	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/12/19 10:06	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19022755/T1ES3Q2

Date: 11/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100483544
Claimant
Vehicle No : SLN5543B **Insured Vehicle No :** SGN6636U
Date of Loss: 20/12/2019 **Nature of Claim:** TP **Claim No:** 7805911424SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN5543B**
 Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEHU395160
 Reg. Date: 09/05/2017 (Man. Year: 2017) Chassis No: KMHCB51CVHU035133
 Colour: White Odometer: 218805 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,911.76	13,664.28	8,247.48	37.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,470.00	1,660.00	2,810.00	62.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,381.76	15,324.28	11,057.48	41.91
Approved Total (Overridden) (S\$)		12,250.00		
Nett Amount (S\$)	26,381.76	12,250.00	14,131.76	53.57
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 27/12/2019
 Date Inspected: 27/12/2019 Inspected At: Cas Garage Pte Ltd (HQ)
 No.1, Kaki Bukit Ave 6, #02-22
 Autobay
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	846.50 FL	*846.50 FL
2	1		*FRONT BUMPER TOWING COVER	Not Necessary	45.20 FL	*- FL
3	1		*FRONT BUMPER LOWER LIP	Deformed	298.50 FL	*298.50 FL
4	1		*FRONT BUMPER UPPER STRIP RUBBER	*Check	145.30 FL	*- FL
5	1		*FRONT RADIATOR GRILLE WITH SENSOR	Cracked	1,456.30 FL	*1,456.30 FL
6	1		*FRONT RADIATOR AIR GUIDE	N/S Deformed/O/S Not Necessary	371.40 FL	*185.70 FL
7	1		*FRONT GRILLE UPPER GARNISH	Deformed	265.80 FL	*265.80 FL
8	1		*FRONT GRILLE CHROME MOULDING	Cracked	289.60 FL	*289.60 FL
9	1		*FRONT LOGO	Necessary	75.80 FL	*75.80 FL
10	1		*FRONT BUMPER SIDE RETAINERS	N/S Deformed /O/SNot Necessary	171.40 FL	*85.70 FL
11	1		*FRONT BUMPER BRACKETS	N/S Deformed /O/SNot Necessary	171.80 FL	*85.90 FL
12	1		*FRONT BUMPER SPONGE	Cracked	245.80 FL	*245.80 FL
13	1		*FRONT NUMBER PLATE GARNISH	Deformed	65.80 FL	*65.80 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	1,076.20 FL	*1,076.20 FL
15	1		*FRONT BUMPER STIFFENER	Not Necessary	185.70 FL	*- FL
16	4		*FRONT BUMPER SENSORS	Not Working (2 PCS ONLY)	903.20 FL	*451.60 FL
17	1		*FRONT SENSOR HARNESS	Torn	398.70 FL	*398.70 FL
18	1		*FRONT RESONATOR BOX	Not Necessary	345.20 FL	*- FL
19	1		*FRONT INTAKE AIR VENT	Not Necessary	198.50 FL	*- FL
20	1		*FRONT WASHER TANK	Not Necessary	158.90 FL	*- FL
21	1		*FRONT BUMPER DAYLIGHT COVERS	N/S Cut / O/S Not Necessary	397.00 FL	*198.50 FL
22	1		*FRONT BUMPER DAYLIGHT	N/S Cracked / O/SNot Necessary	1,286.00 FL	*643.00 FL
23	1		*FRONT BUMPER DAYLIGHT SIDE AIR VENTS	N/S Deformed /O/SNot Necessary	197.40 FL	*98.70 FL
24	2		*FRONT BUMPER ACTIVE FLAPS	Not Necessary	765.00 FL	*- FL
25	1		*FRONT SUPPORT PANEL	*Check	1,335.80 FL	*- FL
26	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed	245.30 FL	*245.30 FL
27	1		*FRONT ENGINE UNDERCOVER	Deformed	398.20 FL	*398.20 FL
28	2		*HEADLAMPS	N/S Cut / O/S Cracked	2,811.60 FL	*2,811.60 FL
29	1		*HEADLAMPS BRACKETS	N/S *Check / O/S Not Necessary	191.20 FL	*- FL
30	1		*FRONT RADIATOR	*Check	658.20 FL	*- FL
31	1		*FRONT RADIATOR FAN COWLING	Not Necessary	345.80 FL	*- FL
32	2		*FRONT RADIATOR FAN MOTOR	Not Necessary	571.20 FL	*- FL
33	1		*FRONT CONDENSER	Dented	698.50 FL	*698.50 FL
34	1		*FRONT BONNET	Bent	2,254.20 FL	*2,254.20 FL
35	1		*FRONT BONNET INNER LOCK	Repair	185.60 FL	*- FL
36	2		*FRONT FENDERS	Not Necessary	1,974.20 FL	*- FL
37	2		*FRONT FENDERS INSULATOR	Not Necessary	316.40 FL	*- FL
38	1		*FRONT FENDERS INNER SHIELD	N/S Deformed /O/SNot Necessary	491.20 FL	*245.60 FL
39	1		*SET FRONT NUMBER PLATE WITH CASING	Bent	50.00 FS	*45.00 FS
40	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
41	1		*SET FRONT ENGINE UNDERCOVER CLIPS	Necessary	30.00 FS	*20.00 FS
42	2		*SET FRONT FENDER INNER COWLING	Necessary	60.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SET SUPPORT PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
44	1		*FRONT RADAR DETECTOR	Cracked	2,910.50 FL	*2,910.50 FL
45	1		*FRONT RADIATOR INVERTER	*Check	798.70 FL	*. FL
46	1		*FRONT RADAR SENSOR HARDNESS	Cut	298.50 FL	*298.50 FL
47	1		*FRONT BUMPER LOWER GRILLE	Deformed	293.60 FL	*293.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,339.70	17,049.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,427.94	3,384.82
Total Parts (\$\$)	21,911.76	13,664.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS	New	2,000.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	2,000.00	700.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	30.00
4	TO REMOVE AND REFIT CONDENSER /RADIATOR AND TOP UP AIR CON GAS	New	120.00	100.00
5	TO REMOVE AND REPLACE FRONT SENSORS AND DISTANCE SETTING	New	150.00	30.00
Gross Labour Cost (\$\$)			4,470.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >