

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022758/KEA3Q2

Date: 17/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800103974

Claimant
Vehicle No : SLM3083E **Insured Vehicle No :** SMD7568H

Date of Loss: 24/12/2019 Nature of Claim: TP Claim No: 3442374439SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM3083E	Engine No:	2ZRS030875
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU103554516
Reg. Date:	27/03/2017 (Man. Year: 2017)	Odometer:	225533 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,532.53	2,418.91	113.62	4.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	260.96	210.96	50.00	19.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,793.49	2,629.87	163.62	5.86
+ GST 7.00/7.00% (\$\$)	195.54	184.09	11.45	5.86
Nett Amount (\$\$)	2,989.03	2,813.96	175.07	5.86
+ Car Rental (5.0 x S\$71.94/day) (\$\$)		359.70		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		3,181.15		

INSPECTION

Date of Assignment: 27/12/2019

Date Inspected: 27/12/2019 Inspected At: Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/F DOOR WINDOW	Cracked	486.50 F	*486.50 F
2	1		*L/F DOOR MIRROR ASSY	Cracked	1,374.20 F	*1,374.20 F
3	1		*L/DOOR MIRROR COVER	Serviceable	87.40 F	*- F
					Sub Total (S\$)	1,948.10
					+ Margin on L,N Items 30.00/30.00% (S\$)	584.43
					Total Parts (S\$)	2,532.53

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TUFF COAT TO TUFF COAT	New	50.00	0.00
2	5.0 WU X 50.00 SGD/H	New	25.00	25.00
3	LABOUR COST 19.0 WU X 50.00 SGD/H	New	135.00	135.00
4	MATERIAL COST	New	50.96	50.96
Gross Labour Cost (\$\$)			260.96	210.96

Report was unsubmitted during this print-out.

< END OF ESTIMATES >