

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19022764/KQD3E2

Date: 28/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKS1046G

Insured Vehicle No : SKV7930Z

Date of Loss: 22/12/2019

Nature of Claim: TP

Claim No: 0644355517SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS1046G**

Make & Model: NISSAN ALMERA, 1.5 (A)

Engine No: HR15972877C

Reg. Date: 26/03/2015 (Man. Year: 2014)

Chassis No: MNTBBAN17Z0500076

Colour: Metallic Grey

Odometer: 87561 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Winrun 9 mm

Rear Left Side: APOLLO 9 mm

Front Right Side: Winrun 9 mm

Rear Right Side: APOLLO 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,501.00	1,881.90	3,619.10	65.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,470.00	1,160.00	44.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,131.00	3,351.90	4,779.10	58.78
Approved Total (Overridden) (S\$)		2,650.00		
Nett Amount (S\$)	8,131.00	2,650.00	5,481.00	67.41

INSPECTION

Date of Assignment: 27/12/2019

Date Inspected: 27/12/2019 Inspected At:

Heng Yap Seng Auto Services

160 Sin Ming Auto City, #08-13

Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	645.10 F	*563.00 FL
2	2		*REAR BUMPER BRACKETS	Repair	72.00 F	*- FL
3	1		*REAR BUMPER RETAINERS	N/S Cracked	100.80 F	*50.40 FL
4	1		*REAR BUMPER LOWER GARNISH	No such part	588.00 F	*- FL
5	1		*REAR BUMPER REVERSE SENSOR LH	Shorted	224.00 F	*224.00 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
7	1		*TAILLAMP LH	Cracked	535.90 F	*292.40 FL
8	1		*TAILLAMP PANEL LH	Bent	102.40 F	*102.40 FL
9	1		*REAR FENDER LH	Bent	1,104.00 F	*818.80 FL
10	1		*REAR FENDER INNER SHIELD LH	Serviceable	72.40 F	*- FL
11	1		*REAR FENDER INNER TRIM LH	Serviceable	254.40 F	*- FL
12	1		*REAR END PANEL	Repair	454.30 F	*- FL
13	1		*REAR END PANEL TOP GARNISH	Serviceable	189.00 F	*- FL
14	1		*REAR SPARE TYRE COMPARTMENT	Repair	788.70 F	*- FL
15	1		*REAR SPARE TYRE TOP BOARD	Serviceable	270.00 F	*- FL
16	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,501.00	2,091.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	209.10
Total Parts (\$\$)	5,501.00	1,881.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS	New	1,200.00	700.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	900.00	600.00
3	TO REMOVE, REPLACE REAR FENDER FITTINGS TO FACILITATE REPAIR	New	300.00	100.00
4	TO REMOVE, REPLACE REAR REVERSE SENSOR	New	150.00	50.00
5	TO CHECK WIRING AND LIGHTINGS	New	80.00	20.00
Gross Labour Cost (S\$)			2,630.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >