

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119022769/KTD3E2

Date: 30/11/2020

REFERENCE

Insured/Claimant:	HONG SOON FISHERY PTE LTD	Policy No:	DMCVSN3057061901		
Date of Loss:	21/12/2019	Nature of Claim:	OD	Claim No:	SNM19D206154/GBG6034C/CBS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG6034C		
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No:	1KD2745494
Reg. Date:	15/09/2017 (Man. Year: 2017)	Chassis No:	JTFAT35Y60K208987
Colour:	Metallic Silver	Odometer:	132405 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$50,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Lassa 9/9 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Lassa 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,486.00	7,249.00	1,237.00	14.58
Miscellaneous Items	130.00	75.00	55.00	42.31
Labour	1,373.40	1,285.20	88.20	6.42
Paintwork Labour	348.60	348.60	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,338.00	8,957.80	1,380.20	13.35
- Excess (S\$)	350.00	350.00	0.00	0.00
(S\$)	9,988.00	8,607.80	1,380.20	13.82
+ GST 7.00/7.00% (S\$)	699.16	602.55	96.61	13.82
Nett Amount (S\$)	10,687.16	9,210.35	1,476.81	13.82

INSPECTION

Date of Assignment:	27/12/2019 Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	27/12/2019 Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Nov 2020)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG6034C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*Spare Parts		6,795.00 F	*6,425.00 F	
Supplementary #1							
2	1		*WASHER RESERVOIR	Dented	55.00 F	*55.00 F	
3	1		*LWR INSTR PANEL TRIM	Dented	120.00 F	*120.00 F	
4	1		*R/LWR INSTR PNL CVR	Dented	140.00 F	*140.00 F	
5	1		*FRONT CHASSIS CROSS MEMBER	Bent	95.00 F	*95.00 F	
6	1		*R/F BUMPER BRACKET	Bent	85.00 F	*85.00 F	
7	1		*FAN	Distorted	65.00 F	*65.00 F	
8	1		*BOOSTER PUMP BRACKET	Not Necessary	280.00 F	*- F	
9	7		*RADIATOR GRILLE CLIPS	Necessary	17.50 F	*17.50 F	
10	1		*WIPER PANEL CLIPS	Necessary	3.50 F	*3.50 F	
11	2		*FRONT CORNER PANEL CLIPS	Necessary	6.00 F	*6.00 F	
Supplementary #2							
12	1		*WASHER RESERVOIR	Repeated	55.00 F	*- F	
13	1		*LWR INSTR PANEL TRIM	Repeated	120.00 F	*- F	
14	1		*R/LWR INSTR PNL CVR	Repeated	140.00 F	*- F	
15	1		*FRONT CHASSIS CROSS MEMBER	Repeated	95.00 F	*- F	
16	1		*R/F BUMPER BRACKET	Repeated	85.00 F	*- F	
17	1		*FAN	Repeated	65.00 F	*- F	
18	7		*RADIATOR GRILLE CLIPS	Repeated	17.50 F	*- F	
19	1		*WIPER PANEL CLIPS	Repeated	3.50 F	*- F	
20	2		*FRONT CORNER PANEL CLIPS	Repeated	6.00 F	*- F	
21	1		*BRAKE PEDAL	Distorted	150.00 F	*150.00 F	
22	1		*BRAKE FLUID	Necessary	12.00 F	*12.00 F	
23	1		*RADIATOR SHROUD	Necessary	75.00 F	*75.00 F	
					Total Parts (S\$)	8,486.00	7,249.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AIR CON GAS (NECESSARY)	50.00	50.00
2	1	FRONT NUMBER PLATE (BENT)	25.00	25.00
3	1	IU BRACKET (NOT NECESSARY)	15.00	0.00
4	1	W/S SEALANT (NOT NECESSARY)	40.00	0.00
Sub Total (S\$)			130.00	75.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Including Materials	New	348.60	348.60
Labour Items				
2	Total of Labour	New	1,373.40	1,285.20
Gross Labour Cost (S\$)			1,722.00	1,633.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >