



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2003784
INV Date 11/05/2020
Reference CS/AGI19022796/Atd3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SJP 860G
Insured Veh. SGX 5693H
Claim No. C10004999
Policy No.
Accident Date 23/12/2019
Inspection Date 31/12/2019

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI19022796/Atd3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 11-05-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGX 5693H	Veh. Inspected	SJP 860G
Policy No.		Coverage (\$)	0.00
Claim No.	C10004999	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	27/12/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ SLK 200	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WDB1714452F209659	Colour	SILVER
Odometer	123802	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/35 R19	DUNLOP	6 mm
L/H Front Tyre	225/35 R19	DUNLOP	6 mm
R/H Rear Tyre	225/35 R19	DUNLOP	6 mm
L/H Rear Tyre	225/35 R19	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/12/2019	Inspection Date	31/12/2019
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 860G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	2,094.30	1,539.20
1	FRONT BUMPER FOGLAMP COVER LH	NOT NECESSARY	95.00	-
2	FRONT BUMPER SIDE RETAINER LH & RH @\$151.00	NECESSARY	302.00	160.00
1	FRONT BUMPER LOGO	NECESSARY	120.00	120.00
1	FRONT BUMPER UPPER GARNISH	CRACKED	321.00	321.00
1	FRONT GRILLE	CRACKED	785.00	412.00
	LESS 10% DISCOUNT		-371.73	-255.22
			3,345.57	2,296.98
<u>SPECIAL NETT ITEMS</u>				
4	PARKING SENSOR @\$210.00 (SN)	NOT NECESSARY	840.00	-
1	SET PARKING SENSOR WIRE HARNESS (SN)	NOT NECESSARY	175.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	SET FRONT CAR PLATE WITH HOLDER (SN)	CRACKED	100.00	60.00
			1,215.00	90.00
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS.		1,000.00	250.00
	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED.		800.00	250.00
	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS.		180.00	30.00
	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
	TO REMOVE & REPLACE PARKING SENSOR.		120.00	60.00
	TO CLEAR FAULT CODE WITH DIAGNOTIC COMPUTER AND RESET TO MERCEDES SPECIFICATION.	NOT NECESSARY	250.00	-
	-		-	-
	-		-	-
	-		-	-
			2,500.00	590.00
GRAND TOTAL			7,060.57	2,976.98



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,300.00
---	--	--	-----------------

Report Ref No. CS/AGI19022796/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJP 860G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

