

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM19022801/Apa3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN			Date: 02-11-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMH 7683L	Veh. Inspected	SMN 1844Y	
	Policy No.	P2241918	Coverage (\$)	0.00	
	Claim No.	S9M02BAB	Excess (\$)	0.00	
	Assign From		Assign Date	26/12/2019	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FIT 1.3	c.c	1317	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	GK33414671	Colour	BLUE	
	Odometer	7379	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	175/70 R14	YOKOHAMA	8 mm	
	L/H Front Tyre	175/70 R14	YOKOHAMA	8 mm	
	R/H Rear Tyre	175/70 R14	YOKOHAMA	8 mm	
	L/H Rear Tyre	175/70 R14	YOKOHAMA	8 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	25/12/2019	Inspection Date	27/12/2019	
	Survey held at	ACE AUTOLUTION PTE LTD			
		13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days			