

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWER SINGAPORE 048583

INV No. AC2007060

INV Date 19/10/2020

Reference CC6/QBE19022844/Uka3q2

Code OBE

PROFESSIONAL SERVICE FEE

Vehicle No. GBG 1166M

Insured Veh. SLP 2696C

Claim No. VC013284

Policy No. 8-V0022461-MVA

Accident Date 20/12/2019

Inspection Date 30/12/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile				
QBE IN	E INSURANCE (SINGAPORE) PTE LTD Ref : CC6/QBE19022844/Uka3q2				
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date: 19-10-2020 Code: QBE			
1.		Policy Particulars :	- THIRD PARTY CLAIM		
Ir	nsured Veh.	SLP 2696C	Veh. Inspected	GBG 1166M	
Р	Policy No.	8-V0022461-MVA	Coverage (\$)	0.00	
С	laim No.	VC013284	Excess (\$)	0.00	
Α	ssign From		Assign Date	30/12/2019	
2.		Vehicle Partic	culars & Condition		
M	lake & Model	NISSAN ABSTAR (M)	c.c	2953	
E	ingine No.	HIDDEN	Year of Reg.	2017	
С	hassis No.	JN1SC2F24Z0859615	Colour	SILVER	
0	Odometer	41216	Steering	IN ORDER	
В	Brakes	IN ORDER	Modification	NIL	
G	Seneral	GOOD			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
R	R/H Front Tyre	195 R15	DUNLOP	6 mm	
L	/H Front Tyre	195 R15	DUNLOP	6 mm	
R	R/H Rear Tyre	155 R13 (D)	DUNLOP	6/6 mm	
L	/H Rear Tyre	155 R13 (D)	DUNLOP	6/6 mm	
4.		Description	on of Damages		
T	HE VEHICLE SUS	STAINED DAMAGES AT THE REA	AR PORTION.		
D.	AMAGES SEE DE	ETAILS.			
5.		General	Information		
Α	ccident Date	20/12/2019	Inspection Date	30/12/2019	
s	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.		Re	emarks		
		N WAS CONDUCTED ON A"WITH E TO YOUR INSTRUCTIONS, WI		REPAIRS.	
5b.					
E	STIMATED NORM	MAL PERIOD FOR REPAIR:	4 Working Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 1166M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	DENTED / BENT	2,668.00	1,399.70
1	TAILGATE ,NISSAN ,EMBLEM	NECESSARY	175.00	141.80
1	TAILGATE LOWER MEMBER	TO REPAIR SEE LABOUR	688.00	-
2	TAILGATE LOCK LATCHS @\$215.00	NOT NECESSARY	430.00	-
2	TAILGATE HINGES @\$50.00	NOT NECESSARY	100.00	-
2	TAILGATE 'L' LOWER PANELS @\$145.00	NOT NECESSARY	290.00	-
2	TAILGATE 'L' LOWER PANEL STOPPERS @\$121.00	NOT NECESSARY	242.00	-
2	TAILLAMPS @\$208.00	CRACKED	416.00	416.00
2	TAILLAMP BRACKETS @\$165.00	NO SUCH PARTS	330.00	-
2	DROP SIDEGATES @\$2998.00	TO REPAIR SEE LABOUR	5,996.00	-
2	DROP SIDEGATE LOWER PANELS @\$981.00	TO REPAIR SEE LABOUR	1,962.00	-
1	REAR CARGO PANEL FRONT PANEL	NOT NECESSARY	1,455.00	-
1	REAR SPARE TYRE & CHAIN	DENTED/ JAMMED	799.00	399.10
1	CHASSIS FRAME N/S	TO REPAIR SEE LABOUR	3,800.00	-
	LESS 10% DISCOUNT		-	-235.66
			19,351.00	2,120.94
	SPECIAL NETT ITEMS			
1	SET 70KM/H STICKER & 13 PAX (SN)	NECESSARY	25.00	20.00
1	SET REAR REVERSE SENSOR (SN)	CRACKED	280.00	200.00
			305.00	220.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACING REVERSE SENSOR .		80.00	50.00
	TO LIFT UP REAR CARGO DECK FOR REPAIR CHASSIS.	NOT NECESSARY	880.00	_
	TO SPRAY RUST PROOFING.		180.00	50.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE LOWER MEMBER ,DROP SIDEGATES,DROP SIDEGATE		1,800.00	680.00

Report Ref No. CC6/QBE19022844/Uka3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,800.00	680.00
			4,790.00	1,480.00
	GRAND TOTAL		24,446.00	3,820.94

RECOMMENDED COST OF LUMP SUM REPAIRS		3,050.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/QBE19022844/Uka3q2

CHUA KANG SENG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 1166M

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 1166M













