

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19022848/R1PA3Q2

Date: 07/10/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0001228
Claimant Vehicle No :	YQ758L	Insured Vehicle No :	GBC3994Y
Date of Loss:	22/12/2019	Nature of Claim:	TP
		Claim No:	MCV2020D0000042

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ758L	Engine No:	4P10D18750
Make & Model:	MITSUBISHI FEB21ER3SDEN, 3.0 D (A)	Chassis No:	FEB71EA25158
Reg. Date:	18/04/2019 (Man. Year: 2018)	Odometer:	50886 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 R17.5	Rear Tyre Size:	215/75 R17.5 (D)
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7/7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	360.00	360.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	450.00	400.00	47.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,210.00	810.00	400.00	33.06
+ GST 7.00/7.00% (S\$)	84.70	56.70	28.00	33.06
Nett Amount (S\$)	1,294.70	866.70	428.00	33.06
+ Loss of Use (2.0 x S\$120.00/day) (S\$)		240.00		
		(S\$)	1,106.70	
Liabe Amount (50.00%) (S\$)		553.35		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		555.35		

INSPECTION

Date of Assignment:	30/12/2019	
Date Inspected:	30/12/2019 Inspected At:	8 TUAS AVE 18 Repairer:Goldbell Engineering Pte Ltd (Tuas)
Estimated Period of Repair:	1.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Sep 2020)	
Parts:	N/A	MITSUBISHI FEB21ER3SDEN 3.0 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ758L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*J-STRIP	Bent	250.00 FS	*250.00 FS
2	1		*SET BOLT NUT	Necessary	45.00 FS	*45.00 FS
3	1		*SAFETY LOCK WITH CHAINS	Missing	65.00 FS	*65.00 FS
					Total Parts (S\$)	360.00
						360.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIX DAMAGED PARTS ,CUT, WELD ,PANELBEAT ,STRAIGHTEN & REALIGN ETC	New	550.00	300.00
2	TO PUTTY ,CLEAN ,SPRAY PAINT AND POLISH ETC	New	300.00	150.00
Gross Labour Cost (\$\$)			850.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >