

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022862/KBA3Q2

Date: 16/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800064100

Claimant
Vehicle No : SGD3622G **Insured Vehicle No :** SMQ23R

Date of Loss: 19/12/2019 Nature of Claim: TP Claim No: 5901860028SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SGD3622G | | |
| Make & Model: | KIA RIO, 1.4 (A) | Engine No: | G4EE6H032801 |
| Reg. Date: | 14/02/2006 (Man. Year: 2005) | Chassis No: | KNADE221266103083 |
| Colour: | Metallic Light Blue | Odometer: | 390306 km |
| Engine Capacity: | 1399 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 185/65 R14 | Rear Tyre Size: | 185/65 R14 |
| Front Left Side: | Yokohama 8 mm | Rear Left Side: | Yokohama 8 mm |
| Front Right Side: | Yokohama 8 mm | Rear Right Side: | Yokohama 8 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 4,169.70 | 2,970.00 | 1,199.70 | 28.77 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,650.00 | 1,330.00 | 320.00 | 19.39 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,819.70 | 4,300.00 | 1,519.70 | 26.11 |
| Approved Total (Overridden) (S\$) | | 3,400.00 | | |
| Nett Amount (S\$) | 5,819.70 | 3,400.00 | 2,419.70 | 41.58 |
| + Loss of Use (5.0 x S\$60.00/day) (S\$) | | 300.00 | | |
| (S\$) | | 3,700.00 | | |
| Liabile Amount (50.00%) (S\$) | | 1,850.00 | | |
| Global Sum Settlement (S\$) | | 1,800.00 | | |

INSPECTION

Date of Assignment: 26/12/2019

Date Inspected: 27/12/2019 Inspected At:

Loh Heng (HQ)
176 Sin Ming Drive, #03-08 Sin Ming
Auto Care
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------|-------------|------------|------------|
| 1 | 1 | | *FRONT BUMPER | Bent | 489.00 FL | *489.00 FL |
| 2 | 1 | | *BUMPER LOWER GRILLE | Cracked | 129.00 FL | *129.00 FL |
| 3 | 1 | | *BUMPER RIGHT PROTECTOR | Missing | 82.00 FL | *82.00 FL |
| 4 | 1 | | *BUMPER SPONE | Cracked | 121.00 FL | *121.00 FL |
| 5 | 1 | | *BUMPER RIGHT RETAINER | Cracked | 67.00 FL | *67.00 FL |
| 6 | 1 | | *FRONT RIGHT HEADLAMP | Mtg Cracked | 549.00 FL | *549.00 FL |
| 7 | 1 | | *FRONT RIGHT FENDER | Bent | 450.00 FL | *450.00 FL |
| 8 | 1 | | *RIGHT FENDER COWLING | Cracked | 178.00 FL | *178.00 FL |
| 9 | 1 | | *RIGHT FENDER PROTECTOR | Missing | 54.00 FL | *54.00 FL |
| 10 | 1 | | *FRONT RIGHT KNUCKLE | Bent | 372.00 FL | *280.00 FL |
| 11 | 1 | | *FRONT RIGHT WHEEL BEARING | Necessary | 287.00 FL | *105.00 FL |
| 12 | 1 | | *FRONT RIGHT BEARING HUP | Bent | 281.00 FL | *186.00 FL |
| 13 | 1 | | *FRONT RIGHT SHOCK ABSORBER | Bent | 328.00 FL | *240.00 FL |
| 14 | 1 | | *ROAD RIM | Dented | 260.00 FL | *260.00 FL |
| 15 | 1 | | *WASHER TANK | Cracked | 110.00 FL | *110.00 FL |
| 16 | 1 | | *DRIVE SHAFT | Repair | 876.00 FL | *- FL |

F=Franchise part. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 4,633.00 | 3,300.00 |
| - List Item Discount on L Items 10.00/10.00% (\$) | 463.30 | 330.00 |
| Total Parts (\$) | 4,169.70 | 2,970.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE AND REFIX NEW PARTS PANEL BEATING INNER PANEL | New | 700.00 | 500.00 |
| 2 | TO PUTTY AND SPRAY PAINT ON PANEL AND NEW PARTS | New | 700.00 | 600.00 |
| 3 | TO REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS | New | 200.00 | 180.00 |
| 4 | TO DO WHEEL ALIGNMENT | New | 50.00 | 50.00 |
| Gross Labour Cost (S\$) | | | 1,650.00 | 1,330.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >