

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INV No.

### **TAX INVOICE**

SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER

SINGAPORE 048623

INV Date Reference

ce CS/SMO19022894/Gsd3n2

Code SMC

AC2003371

22/04/2020

#### PROFESSIONAL SERVICE FEE

Vehicle No. SLZ 1725G

Insured Veh. SMM 6414C

Claim No. CMTD1905987/GPL

Policy No.

Accident Date 24/12/2019

Inspection Date 31/12/2019

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile					
SOM	PO INSURANCE	SINGAPORE PL	Ref : CS/SMO19022894/Gsd3n2		
#05-0		OWERSINGAPORE 048623	Date: 22-04-2020  Code: SMO		
1.	,	Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	SMM 6414C	Veh. Inspected	SLZ 1725G	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD1905987/GPL	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	30/12/2019	
2.		Vehicle Partic	culars & Condition		
	Make & Model	HONDA FIT 1.3G	c.c	1317	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	GK31309310	Colour	WHITE	
	Odometer	56492	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Conditi	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	195/55 R15	MICHELIN	6 mm	
	L/H Front Tyre	195/55 R15	MICHELIN	6 mm	
	R/H Rear Tyre	195/55 R15	MICHELIN	6 mm	
	L/H Rear Tyre	195/55 R15	MICHELIN	6 mm	
4.	I	<u> </u>	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.		
	DAMAGES SEE D				
5.	1		I Information		
	Accident Date	24/12/2019	Inspection Date	31/12/2019	
	Survey held at	BODYFIX			
		NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06 AMK AUTOPOINT SINGAPORE 568047			
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	5 Working Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 1725G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE	BUCKLED	1,150.00	803.20
1	REAR WINDSCREEN SEALANT	NECESSARY	120.00	35.00
1	REAR WINDSCREEN MOULDING	NECESSARY	125.00	68.50
1	REAR TAILGATE EMBLEM	NECESSARY	80.00	42.50
6	REAR BUMPER CLIPS @\$5.00	NECESSARY	30.00	30.00
1	REAR TAIL LAMP LH	CRACKED	480.00	305.00
1	REAR END PANEL	BUCKLED	550.00	320.40
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	180.00	-
1	SIDE RETAINER LH	DEFORMED	40.00	18.00
1	SIDE RETAINER RH	NOT NECESSARY	40.00	-
1	TAILGATE LOCK	NOT NECESSARY	280.00	-
1	REAR BUMPER	DEFORMED	750.00	545.30
1	REAR FENDER (LH)(NPA)	NOT NECESSARY	-	-
1	REAR TAILGATE RUBBER	NOT NECESSARY	160.00	-
	LESS 20% DISCOUNT		-	-433.58
			3,985.00	1,734.32
	SPECIAL NETT ITEMS			
1	SET REVERSE SENOR (SN)	NOT WORKING	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	RUST-PROOFING ON THE REAR ACCIDENT AFFECTED PORTIONS.	NOT NECESSARY	100.00	-
	TO CHECK & TEST LIGHTING FUNCTIONS & REVERSE SENSOR WIRING.		40.00	40.00
	LABOUR TO REPLACE ABOVE PARTS,PANEL BEAT,REPAIR & RE-ALIGN DAMAGE PARTS.		800.00	600.00
	PUTTY & SPRAY PAINT REAR BOOTLID,REAR BUMPER & OTHER AFFECTED AREAS.		1,000.00	600.00
	TO REMOVE & REFIT REAR WINDSCREEN TO ASSIST REPAIRS.		100.00	100.00
			2,040.00	1,340.00

Report Ref No. CS/SMO19022894/Gsd3n2



Page No.:2 of 2

GRAND TOTAL	6,225.00	3,274.32
RECOMMENDED COST OF REPAIRS		3 274 32

Report Ref No. CS/SMO19022894/Gsd3n2



**XING GUO QIANG** 

M.MATAI, AMSAE-A

X.2.

**ADRIAN LING WAI PING** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser** 

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLZ 1725G

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLZ 1725G

### RE-INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLZ 1725G

### RE-INSPECTION











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLZ 1725G

RE-INSPECTION





