

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022923/UYP3E2

Date: 09/04/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30570619011

Claimant Vehicle No : XD687M

Insured Vehicle No : GBG6034C

Date of Loss: 21/12/2019

Nature of Claim: TP

Claim No: SNM19D206154C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XD687M**

Make & Model: ISUZU CXZ50K, 12.1 D (M)

Engine No: 6WA1400399

Reg. Date: 01/09/2006 (Man. Year: 2006)

Chassis No: JALCXZ50K67000102

Colour: White/Blue

Odometer: 672283 km

Engine Capacity: 12068 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D/D)

Front Left Side: Double Star 6 mm

Rear Left Side: Double Star 6/6/6/6 mm

Front Right Side: Double Star 6 mm

Rear Right Side: Double Star 6/6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	65,780.00	45,229.50	20,550.50	31.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,480.00	3,158.00	2,322.00	42.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	71,260.00	48,387.50	22,872.50	32.10
+ GST 7.00/7.00% (S\$)	4,988.20	3,387.13	1,601.07	32.10
Nett Amount (S\$)	76,248.20	51,774.63	24,473.57	32.10

INSPECTION

Date of Assignment: 31/12/2019

Date Inspected: 08/01/2020 Inspected At:

Kan Fook Sing Motor Workshop (Kaki Bukit)
61 DEFU LANE 12
Singapore

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 09 Apr 2020)

Parts: N/A ISUZU CXZ50K 12.1 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XD687M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CARTRIDGE SECTION A (WCP)	Distorted	28,000.00 F	*19,250.00 F
2	1		*CARTRIDGE SECTION B (WCP)	Distorted	28,000.00 F	*19,250.00 F
3	1		*IMPACT FRAME PLATE - REFLECTIVE (WCP)	Distorted	1,200.00 F	*830.00 F
					Sub Total (S\$)	57,200.00
					+ Margin on L,N Items 15.00/15.00% (S\$)	8,580.00
					Total Parts (S\$)	65,780.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	BREAKEAWAY CABLES BOLT	New	180.00	60.00
2	TO ADJUST AND ALIGN THE WHOLE TMA	New	1,000.00	650.00
3	LABOUR, INSTALLATION & FIXING CHARGES FOR ABOVE DISMANTLING CHARGES FROM OLD UNIT	New	4,000.00	2,350.00
4	TO RESPRAY PAINT SIDE GUIDE BAY	New	300.00	98.00
Gross Labour Cost (S\$)			5,480.00	3,158.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >