

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19022930/R1VF3E2

Date: 11/09/2020

REFERENCE

Insured/Claimant:	CHAN KHENG HUI	Policy No:	1900169775	
Date of Loss:	27/12/2019	Nature of Claim:	OD	Claim No: 9083144926SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ328L	Engine No:	DAX059818
Make & Model:	AUDI Q3, 2.0 TFSI QU (A)	Chassis No:	WAUZZZF7K2139013
Reg. Date:	30/09/2019 (Man. Year: 2019)	Odometer:	2272 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$195,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,047.20	8,568.24	6,478.96	43.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,972.00	7,092.00	3,880.00	35.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	26,019.20	15,660.24	10,358.96	39.81
- Excess (\$\$)	1,000.00	1,000.00	0.00	0.00
(\$\$)	25,019.20	14,660.24	10,358.96	41.40
+ GST 7.00/7.00% (\$\$)	1,751.34	1,026.22	725.12	41.40
Nett Amount (\$\$)	26,770.54	15,686.46	11,084.08	41.40

INSPECTION

Date of Assignment:	31/12/2019	
Date Inspected:	31/12/2019	Inspected At: 281 ALEXANDRA ROAD
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,364.00 FS	*- FS
2	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	34.00 FS	*- FS
3	1		*FRONT FENDER-LH	Bent	1,301.00 FS	*1,040.80 FS
4	1		*FRONT FENDER BRACKET-LH	Serviceable	16.00 FS	*- FS
5	1		*FRONT FENDER BRACE-LH	Serviceable	206.00 FS	*- FS
6	1		*FRONT WHEEL HOUSING LINER-LH	Serviceable	246.00 FS	*- FS
7	1		*WHEEL HOUSING LINER ATTACHMENTS PARTS	Not Necessary	35.00 FS	*- FS
8	1		*WHEEL SPOILER-LH	Serviceable	-	*- FS
9	2		*FRONT WHEEL COVER-LH/RH	N/S Scratched / O/S Necessary	1,154.00 FS	*922.40 FS
10	1		*S-LINE INSCRIPTION	Not Necessary	113.00 FS	*- FS
11	1		*DOOR-LH	Bent	2,377.60 FS	*2,377.60 FS
12	1		*OUTER DOOR SEAL-LH/RH	Necessary	370.00 FS	*147.60 FS
13	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
14	1		*DOOR ATTACHMENT PARTS	Not Necessary	239.00 FS	*- FS
15	1		*DOOR CATCH	Bent	132.00 FS	*109.60 FS
16	1		*WINDOW REGULATOR-LH	Serviceable	270.00 FS	*- FS
17	1		*FRONT DOOR COVER-LH	Necessary	661.00 FS	*528.80 FS
18	1		*DOOR-RH	Bent	2,377.60 FS	*2,377.60 FS
19	1		*OUTER DOOR SEAL-RH	Necessary	190.00 FS	*154.40 FS
20	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
21	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
22	1		*SEALING STRIP	Not Necessary	15.00 FS	*- FS
23	1		*DOOR CATCH	Serviceable	132.00 FS	*- FS
24	1		*DOOR HINGE HALF UPPER PART-LH UPPER	Serviceable	42.00 FS	*- FS
25	1		*DOOR HINGE HALF LOWER PART-LH UPPER	Serviceable	42.00 FS	*- FS
26	1		*DOOR HINGE HALF UPPER PART-LH LOWER	Serviceable	42.00 FS	*- FS
27	1		*DOOR HINGE HALF LOWER PART-LH LOWER	Serviceable	42.00 FS	*- FS
28	1		*REAR DOOR SEAL BRACKET-LH	Serviceable	39.00 FS	*- FS
29	1		*REAR DOOR COVER-LH	Necessary	577.00 FS	*461.20 FS
30	1		*REAR WHEEL COVER-LH	Scratched	487.00 FS	*389.60 FS
31	1		*REAR ALUMINIUM RIM-LH	Serviceable	923.00 FS	*- FS
32	1		*SUNDRIES	Necessary	400.00 F	*22.72 F
33	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 15,047.20 8,568.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HANRESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH LHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.	New	720.00	720.00
3	TO DISMANTLE FRONT BUMPER,LHS FRONT FENDER,LHS FRONT AND REAR DOORS, INSPECT LHS LHS B-PILLAR AND LHS REAR FENDER FOR DAMAGES.RENEW FRONT BUMPER,LHS FRONT FENDER,LHS FRONT AND REAR DOORS AND LHS REAR WHEEL ARCH TRIM. REINSTALL ALL PARTS REMOVED.	New	4,000.00	2,500.00
4	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER,LHS FRONT AND REAR DOORS,DOOR COVERS AND WHEEL ARCH TRIMS.	New	5,300.00	3,200.00
5	TO RENEW LHS REAR RIM.CARRY OUT WHEEL ALIGNMENT.	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			10,972.00	7,092.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >