



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 7303C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	REVERSE SENSOR	SERVICEABLE	379.60	-
1	REAR BUMPER	BUCKLED	398.30	398.30
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	97.80	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	97.80	-
1	REAR BUMPER BRACKET LH	TO REPAIR SEE LABOUR	122.67	-
1	REAR BUMPER BRACKET RH	TO REPAIR SEE LABOUR	122.67	-
1	REAR BUMPER REINFORCEMENT	BENT	398.90	398.90
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	62.30	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	62.30	-
1	REAR BUMPER REFLECTOR GARNISH LH	SERVICEABLE	108.70	-
1	REAR BUMPER REFLECTOR GARNISH RH	SERVICEABLE	108.70	-
1	REAR BUMPER LOWER GARNISH CENTRE	DENTED	397.60	397.60
1	REAR BUMPER TOW COVER	SERVICEABLE	21.69	-
1	TAIL DOOR	BENT	1,022.50	1,022.50
1	TAIL DOOR LOCK	TO REPAIR SEE LABOUR	478.40	-
1	TAIL DOOR EMBLEM	NOT NECESSARY	61.70	-
1	WORDING "CH-R"	NOT NECESSARY	51.36	-
1	WORDING "HYBRID SYNERGY DRIVE"	NOT NECESSARY	55.75	-
1	TAIL DOOR GARNISH	SERVICEABLE	882.70	-
1	TAILDOOR REFLECTOR LH	SERVICEABLE	486.70	-
1	TAILDOOR REFLECTOR RH	SERVICEABLE	489.70	-
1	TAIL END PANEL	TO REPAIR SEE LABOUR	701.25	-
1	TAIL END PANEL GARNISH	SERVICEABLE	295.50	-
8	TAIL END PANEL GARNISH CLIP	NOT NECESSARY	28.00	-
1	BOOT WEATHERSTRIP	SERVICEABLE	361.70	-
1	WORDING "HYBRID"	NOT NECESSARY	49.87	-

Report Ref No. CS/INC19022938/Ksf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-1,846.04	-564.33
			5,538.12	1,692.97
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL). INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET LH, REAR BUMPER BRACKET RH, TAIL DOOR LOCK AND TAIL END PANEL		1,600.00	500.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL).		1,400.00	600.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT REAR BUMPER SENSOR.		120.00	50.00
	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO TUFF COAT.	NOT NECESSARY	150.00	-
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.		120.00	60.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	20.00
			3,830.00	1,370.00
GRAND TOTAL			9,368.12	3,062.97
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,062.97

Report Ref No. CS/INC19022938/Ksf3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.