



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 5747D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	420.00	-
1	L/R BUMPER SUPPORT (WCP) (CONSISTENT)	NOT NECESSARY	30.00	-
1	R/R BUMPER SUPPORT (WCP) (CONSISTENT)	NOT NECESSARY	30.00	-
1	RR BUMPER CLAMP KIT (WCP) (CONSISTENT)	NOT NECESSARY	20.00	-
1	L/R SIDE PANEL CPL (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	900.00	-
1	L/R WHEELARCH MLDG (WCP) (CONSISTENT)	CUT	160.00	160.00
1	L/R SIDE WINDOW (WCP) (CONSISTENT)	NOT NECESSARY	380.00	-
1	L/R WDW BONDING KIT (WCP) (CONSISTENT) (NPA)	NOT NECESSARY	-	-
1	L/R WHEELHOUSE COVER (WCP) (CONSISTENT)	NOT NECESSARY	95.00	-
1	REAR AXLE SUBFRAME (WCP) (CONSISTENT)	NOT NECESSARY	950.00	-
1	L/R LOWER JOINT ROD (WCP) (CONSISTENT)	NOT NECESSARY	220.00	-
1	L/R UPPER JOINT ROD (WCP) (CONSISTENT)	NOT NECESSARY	220.00	-
1	L/R WHEEL HUB (WCP) (CONSISTENT)	NOT NECESSARY	290.00	-
1	L/R SHOCK ABSORBER (WCP) (CONSISTENT)	NOT NECESSARY	135.00	-
1	L/R AXLE STEERING (WCP) (CONSISTENT)	NOT NECESSARY	870.00	-
1	L/R WHEEL (WCP) (CONSISTENT)	CUT	1,200.00	1,200.00
1	L/R COWLING CLIP (WCP) (CONSISTENT)	NOT NECESSARY	20.00	-
1	ARCH GARNISH CLIP (WCP) (CONSISTENT)	NOT NECESSARY	40.00	-
1	L/R HUB CAP (WCP) (CONSISTENT)	MISSING	40.00	40.00
	COST PLUS 15%		903.00	210.00
			6,923.00	1,610.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	AUDATEX FEE (SN)(CONSISTENT)	NOT NECESSARY	42.00	-
1	QTR GLASS SEALANT (SN)(CONSISTENT)	NOT NECESSARY	40.00	-
1	TYRE TUBELESS VALVE (SN)(CONSISTENT)	NECESSARY	15.00	15.00
			97.00	15.00
	<b><u>LABOUR</u></b>			
	ALIGNMENT.		60.00	60.00
	169.0 WU X 45.00 SGD/H.		760.50	409.50

Report Ref No. CC4/ASM19022970/Gpa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR COST 82.0 WU X 45.00 SGD/H.INCLUSIVE OF THE REPAIR OF L/R SIDE PANEL CPL AND REAR BUMPER.		369.00	261.00
	MATERIAL COST .		133.61	85.24
			1,323.11	815.74
GRAND TOTAL			8,343.11	2,440.74
RECOMMENDED COST OF REPAIRS				2,440.74

Report Ref No. CC4/ASM19022970/Gpa3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.