

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19022971/GEA3Q2

Date: 28/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100409897
Claimant
Vehicle No : SLP6864H **Insured Vehicle No :** SKS1584U
Date of Loss: 27/12/2019 Nature of Claim: TP Claim No: 9362042948SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP6864H**
Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) Engine No: CHZ345025
Reg. Date: 14/06/2017 (Man. Year: 2017) Chassis No: WAUZZZGA3HA040768
Colour: Red Odometer: 42897 km
Engine Capacity: 999 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,781.00	2,224.40	5,556.60	71.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,732.00	3,482.00	4,250.00	54.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,513.00	5,706.40	9,806.60	63.22
+ GST 7.00/7.00% (S\$)	1,085.91	399.45	686.46	63.22
Nett Amount (S\$)	16,598.91	6,105.85	10,493.06	63.22
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,607.85		

INSPECTION

Date of Assignment: 02/01/2020
Date Inspected: 02/01/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,706.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	314.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -CENTRE	Not Necessary	179.00 FS	*- FS
4	1		*FRONT BUMPER SPOILER	Cut	273.00 FS	*218.00 FS
5	1		*FRONT BUMPER CARRIER	Not Necessary	625.00 FS	*- FS
6	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	71.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,301.00 FS	*1,040.80 FS
8	1		*RADIATOR GRILLE STRIKER	Not Necessary	114.00 FS	*- FS
9	2		*FRONT WHEEL COVER -LH/RH	Necessary	588.00 FS	*469.60 FS
10	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
11	1		*REAR BUMPER	Repair	1,074.00 FS	*- FS
12	1		*REAR BUMPER SPOILER -LH	Scratched	259.00 FS	*207.20 FS
13	1		*REAR BUMPER CARRIER	Not Necessary	501.00 FS	*- FS
14	2		*REAR BUMPER HOLDING STRAP -LH/RH	Not Necessary	24.00 FS	*- FS
15	2		*REAR WHEEL COVER -LH/RH	Necessary	312.00 FS	*248.80 FS
16	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **7,781.00** **2,224.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUM-PER ASSY REORGANISE FRONT CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY FRONT BUMPER	New	1,000.00	550.00
4	TO REMOVE AND TRANSFER REAR PARKING AID ,CHECK FUNCTION	New	280.00	280.00
5	TO DISMANTLE AND RENEW REAR BUMPER ASSY .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
6	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO REPAIR REAR BUMPER	New	700.00	0.00
9	TO REPAIR AND RESPRAY END PANELLING	New	1,800.00	550.00
Gross Labour Cost (S\$)			7,732.00	3,482.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >