

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19022973/R1EA3Q2

Date: 12/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SJV7730X

Insured Vehicle No : PC4859H

Date of Loss: 24/12/2019

Nature of Claim: TP

Claim No: 0110168021SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJV7730X

Make & Model: AUDI A3, 999cc TFSI S-TRONIC (A)

Engine No: CHZC27190

Reg. Date: 14/03/2019 (Man. Year: 2019)

Chassis No: WAUZZZ8V8K1021092

Colour: Black

Odometer: 12977 km

Engine Capacity: 999 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,776.00	6,193.44	4,582.56	42.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,002.00	2,902.00	2,100.00	41.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,778.00	9,095.44	6,682.56	42.35
+ GST 7.00/7.00% (\$\$)	1,104.46	636.68	467.78	42.35
Nett Amount (\$\$)	16,882.46	9,732.12	7,150.34	42.35
+ Loss of Use (5.0 x S\$60.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		10,039.57		

INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 03/01/2020 **Inspected At:**

Premium Automobiles Pte Ltd (HQ)

55 UBI ROAD 1

Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	35.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	488.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -RH	Not Necessary	270.00 FS	*- FS
6	1		*FRONT BUMPER COVER TRIM -RH	Not Necessary	148.00 FS	*- FS
7	1		*FRONT WHEEL HOUSING LINER ADAPTER -RH	Not Necessary	34.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	171.00 FS	*- FS
9	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	660.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
11	1		*FOAM FILLER PIECE COVER	Not Necessary	111.00 FS	*- FS
12	1		*FRONT FENDER -RH	Bent	778.00 FS	*622.00 FS
13	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
14	1		*FRONT FENDER BRACKET -RH	Not Necessary	25.00 FS	*- FS
15	1		*FRONT FENDER BRACKET -RH	Not Necessary	35.00 FS	*- FS
16	1		*FRONT FENDER BRACE	Bent	88.00 FS	*69.84 FS
17	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	158.00 FS	*- FS
18	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	81.00 FS	*- FS
19	1		*LED HEADLIGHT -RH	Obstructed	5,029.00 FS	*4,023.20 FS
20	1		*LIFT CYLINDER -RH	Not Necessary	128.00 FS	*- FS
21	1		*SUNDRIES	Necessary	300.00 FS	*14.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 10,776.00 6,193.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,450.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,002.00	2,902.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >